

ALERT SERVICE BULLETIN
Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

NO. 206-06-110

DATE SEP 7, 2006

PAGE 1 of 5

DATE
REV

MODEL AFFECTED: 206A/B and TH-67 Series

SUBJECT: UPPER LEFT-HAND TAILBOOM ATTACHMENT
HARDWARE, INSPECTION OF

HELICOPTERS AFFECTED: All Model 206A/B helicopters serial number 4 through 4449 and model TH-67 helicopters 5101 through 5237 that had a 407-030-750-103 upper left-hand CRES steel fitting field retrofitted.

All Model 206A/B helicopters serial number 4450 through 4617 and model TH-67 helicopters 5238 through 5312 that had a 407-030-750-103 upper left-hand CRES steel fitting installed at manufacturing.

[Model 206A/B helicopters serial numbers 4618 and subsequent will have the intent of this bulletin accomplished prior to delivery. Model TH-67 helicopters serial numbers 5313 and subsequent will have the intent of this bulletin accomplished prior to delivery]

COMPLIANCE: PART I Within the next 50 hours after receipt of this bulletin.

PART II At the next scheduled 100 Hrs/annual inspection, after Part I have been accomplished.

DESCRIPTION:

Bell Helicopter found that on some helicopters having the 407-030-750-103 CRES steel fitting installed at the upper left-hand location, the attachment bolt might not meet the installation requirement.

PART I of this bulletin provides instructions to verify if a CRES steel fitting is installed at the upper left-hand location and check for the amount of bolt threads exposed. PART II of this bulletin provides instructions to replace the upper left-hand bolt if required, as indicated in PART I.

APPROVAL:

The engineering design aspects of this bulletin are Transport Canada approved.

MANPOWER:

Approximately 0.5 man-hour is required to perform PART I and 1 man-hour to perform PART II of this bulletin. Man-hours are based on hands-on time, and may vary with personnel and facilities available.

WARRANTY:

Warranty does not apply for parts or labor associated with this bulletin.

MATERIAL:

Required Material:

The following material is required for the accomplishment of this bulletin and may be obtained through your Bell Helicopter Textron Supply Center.

<u>Part Number</u>	<u>Nomenclature</u>	<u>Quantity</u>
NAS6606-25	Bolt	1

Note: The bolt may not require replacement. Refer to PART I.

SPECIAL TOOLS:

None required

WEIGHT AND BALANCE:

Not Affected

ELECTRICAL LOAD DATA:

Not affected

REFERENCES:

BHT-206A/B-MM-5, Maintenance Manual

PUBLICATIONS AFFECTED:

BHT-206A/B-SERIES-IPB, Illustrated Parts Breakdown
BHT-206A/B-MM-5, Maintenance Manual

ACCOMPLISHMENT INSTRUCTIONS:

PART I. Left-hand upper fitting and bolt inspection.

1. Remove the tailboom attachment access door from right side of fuselage forward of tailboom bulkhead as per BHT-206A/B-SERIES-MM, chapter 53.
2. Gain access to upper left-hand tailboom fitting (7, Figure 1).

-NOTE-


Helicopters 206B S/N 4450 through subsequent and TH-67 S/N 5238 through subsequent were delivered with CRES steel fitting 407-030-750-103 installed.

3. For helicopters 206A/B S/N 4 through 4449 and TH-67 S/N 5101 through 5237, verify if CRES steel fitting is installed. Those aircraft were originally delivered with aluminum fitting that may have been replaced by the CRES fitting and longeron assembly 206-031-314-201A. CRES steel fitting (7) may be identified as follows:
 - a. The part number 407-030-750-103 maybe stamped on the fitting.
 - b. Longeron and aluminum fitting were replaced by longeron assembly 206-031-314-201A.
 - c. The CRES fitting 407-030-750-103 is composite bonded to the longeron and the bonding layer might be visible.

- d. The CRES fitting 407-030-750-103 is ferrous and can be identified using a magnet.
4. If the helicopter does not have a CRES fitting installed, no further action is required. Make an entry in the helicopter records to indicate that this bulletin has been accomplished.
5. For helicopters affected by this bulletin that have a CRES fitting installed, perform thread count on the upper left hand attachment bolt (1) as per Figure 1.
6. If the correct amount of thread is exposed (between 1 and 3), do a torque check. Refer to the Maintenance Manual. If the torque is correct, make an entry in the helicopter records to indicate that this bulletin has been accomplished. If the torque is found below minimum and a replacement bolt (1) is not available at this time, adjust the washer (3) quantity as required per Figure 1. Refer to the Maintenance Manual and torque as required. Make an entry in the helicopter records to indicate that the PART I of this bulletin have been accomplished and that the PART II of this bulletin will require accomplishment.
7. If less than 1 thread is exposed, adjust the washer (3) quantity as required per Figure 1. Refer to the Maintenance Manual and torque as required. Make an entry in the helicopter records to indicate that this bulletin has been accomplished.
8. If more than 3 threads are exposed and a replacement bolt (1) is not available at this time, adjust the washer (3) quantity as required per Figure 1. Refer to the Maintenance Manual and torque as required. Make an entry in the helicopter records to indicate that the PART I of this bulletin have been accomplished and that the PART II of this bulletin will require accomplishment.
9. If more than 3 threads are exposed and a replacement bolt (1) is available, accomplish PART II of this bulletin.

PART II. Upper left hand tailboom attachment bolt replacement.

1. Remove and discard the upper left hand tailboom attachment bolt (1, Figure 1). Install new bolt (1) and adjust the quantity of washer (3) as required to ensure correct installation as shown on Figure 1. If serviceable, the nut (4) does not require replacement. Refer to Maintenance Manual.
2. 100 hours after installation, do a torque check of the upper left hand tailboom attaching hardware (BHT-206A/B-SERIES-MM).
3. Make an entry in the helicopter records to indicate that this bulletin has been accomplished.



1. Bolt
2. Washer, chamfered under bolt head
3. Washer, as required
4. Nut
5. Tailboom
6. AFT fuselage
7. Fitting

NOTES

- 1 Bolt (1) and chamfered washer (2) are to be installed through tailboom (5) and Aft fuselage (6). Bolt head and chamfered washer are to be installed on the tailboom side. Steel washers (3) are to be installed next to fitting (7) to provide not less than one thread and not more than three threads exposed on threaded end of bolt (1).
- 2 If thread count is less than one, remove washers as required.
- 3 If thread count is more than three, remove and replace bolt, then readjust number of washers to meet requirement of note 1.

RAM_06519_001_c1

Figure 1: Tailboom Attachment