

ALERT SERVICE BULLETIN

REVISION NOTICE



A Textron Company

DATE JUN 10, 2009

TO: All Owners/Operators of Bell 206A/B and TH-67 Series Helicopters

**SUBJECT: Revision "A" to Alert Service Bulletin 206-09-123: DISC ASSEMBLY
101584-2, RECALL OF**

Revision "A" to this bulletin adds the date when Bell Helicopter has started to sell disc assembly 101584-2 through Spares to the DESCRIPTION section.

AN APPROPRIATE ENTRY SHOULD BE MADE IN THE AIRCRAFT LOGBOOK UPON ACCOMPLISHMENT
IF OWNERSHIP OF AIRCRAFT HAS CHANGED PLEASE FORWARD TO NEW OWNER

ALERT SERVICE BULLETIN



A Textron Company

NO. 206-09-123

DATE APR 20, 2009

PAGE 1 of 4

DATE JUN 10, 09

REV A

MODEL AFFECTED: 206A/B and TH-67 Series

SUBJECT: DISC ASSEMBLY 101584-2, RECALL OF

HELICOPTERS AFFECTED: 206A Helicopters serial number 004 through 660 and 672 through 715.

206A Helicopters converted to 206B as per Service Instruction 206-80.

206B Helicopters serial number 661 through 671 and 716 and subsequent.

206B (TH-67) Helicopters serial number 5101 and subsequent.

[All 206 helicopters delivered new form factory had disc assembly P/N 32721-1 installed at delivery]

-NOTE-

Each laminate of disc assembly 101584-2 is ink stamped with P/N 101584-1.

COMPLIANCE: PART I: For disk assembly P/N 101584-2 in spares stock, immediately after receipt of this bulletin.

PART II: For disk assembly P/N 101584-2 installed on helicopter, within the next 100 hours after receipt of this bulletin but not to exceed 30 days.

DESCRIPTION:

Bell Helicopter found that new disc assembly P/N 101584-2 sold through Spares beginning March 2009 as an alternate to P/N 32721-1 does not conform to the **A**

approved Engineering. This Alert Service Bulletin mandates the removal from service of all disc assemblies P/N 101584-2.

APPROVAL:

The engineering design aspects of this bulletin are Transport Canada Civil Aviation (TCCA) approved.

MANPOWER:

No additional man-hours are required to accomplish PART I of this bulletin.

Approximately 1.0 man-hour is required to replace each disc assembly that is affected by the **ACCOMPLISHMENT INSTRUCTIONS PART II** section of this bulletin. Man-hours are based on hands-on time, and may vary with personnel and facilities available.

WARRANTY:

Owners / Operators of Bell Helicopters who comply with the instructions in this Bulletin will be eligible to receive a 100% credit towards replacement Disc Assemblies part number 32721-1.

To receive this credit:

- Comply with the instructions contained in this Bulletin no later than the applicable hours in the “compliance section” of this ASB, or no later than the March 31, 2010.
- Purchase replacement parts from a Bell approved source.
- Submit an MMIR to the Bell Warranty Department referencing this ASB.

Customers who fail to comply with the instructions in this Bulletin before the March 31, 2010 are not eligible for the special warranty credit listed above. There is no labor associated with this bulletin.

MATERIAL:

Required Material:

The following material is required for the accomplishment of this bulletin and may be obtained through your Bell Helicopter Textron Supply Center.

<u>Part Number</u>	<u>Nomenclature</u>	<u>Quantity</u>
32721-1	DISC ASSEMBLY	A/R

SPECIAL TOOLS:

None required

ELECTRICAL LOAD DATA:

Not affected

REFERENCES:

BHT-206A/B-SERIES-MM, Maintenance Manual

PUBLICATIONS AFFECTED:

None affected

ACCOMPLISHMENT INSTRUCTIONS:

PART I: For disc assembly in spares stock

-NOTE-

Each laminate of disc assembly 101584-2 is ink stamped with P/N 101584-1.

1. Verify if disk assemblies in spare stock are identified with P/N 101584-2. If a disc assembly is identified with P/N 101584-2, refer to the WARRANTY section of this bulletin.

PART II: Disc assembly installed on Helicopter

-NOTE-

Each laminate of disc assembly 101584-2 is ink stamped with P/N 101584-1.

1. Review helicopter records to determine if Disc Assembly P/N 101584-2 has been installed on the helicopter.

- a. If helicopter records indicate that a Disc Assembly P/N 101584-2 has been installed, proceed with step 2.
 - b. If helicopter records review indicates that no Disc Assembly P/N 101584-2 has been installed, proceed with step 3.
2. Gain access to the tail rotor driveshaft system and replace Disc Assembly P/N 101584-2 with serviceable Disc Assembly P/N 32721-1 (BHT-206A/B-SERIES-MM, Chapter 65).
 3. Make a log book entry to indicate that this bulletin has been accomplished.