



A Textron Company

ALERT SERVICE BULLETIN

212-20-164

20 November 2020
Revision A, 17 December 2020

MODEL AFFECTED: 212

SUBJECT: FUEL CHECK VALVE P/N 209-062-607-001,
INSPECTION AND REPLACEMENT OF.

HELICOPTERS AFFECTED: Serial numbers 30501 through 30999, 31101
through 31311, 32101 through 32142 and 35001
through 35103 having a Circor Aerospace (Circle
Seal) fuel check valve not marked "TQL".

[Serial numbers listed above having a Circor
Aerospace (Circle Seal) fuel check valve marked
"TQL" are not affected by this bulletin.]

COMPLIANCE:

Part I: Within the next 25 flight hours or 30 days,
whichever comes first after the release date of the
revision A of this bulletin.

Part II: Within the next 25 flight hours or 30 days,
whichever comes first after accomplishment of Part I
and every 25 flight hours or 30 days thereafter until
Part III is accomplished.

Part III: No later than 600 flight hours or 12 months,
whichever comes first after accomplishment of Part I.

DESCRIPTION:

Bell recently received a report of a cracked check valve manufactured by Circor Aerospace (Circle Seal). This check valve was manufactured in 2009 which is outside of the manufacturing date range (October 2011 – March 2015) addressed by the ASB 212-15-155 Rev A. Corrective actions implemented in 2015 by Circor Aerospace to prevent cracking of the check valve housings are indicated by the "TQL" marking.

This recent check valve cracking report indicates that additional fuel check valves P/N 209-062-607-001 manufactured by Circor Aerospace (Circle Seal) not having the “TQL” marking may be susceptible to cracking with time in service.

This Alert Service Bulletin mandates a one-time inspection of the suspected fuel check valves for housing dimension measurement. Fuel check valves that do not meet the inspection requirements outlined in the Part I of the Accomplishment Instructions of this bulletin will require replacement. Valves that are found serviceable after accomplishment of Part I of this bulletin will not require further inspection or replacement.

The original release of this bulletin mandated a one-time inspection of fuel check valves manufactured between 1995 and March 2015 without the “TQL” marking. Following the original release of this bulletin, Bell received reports from operators indicating that some fuel check valves did not have a manufacturing date stamped on the housing. Based on additional information provided by Circor Aerospace, revision A of this bulletin mandates the inspection of all fuel check valves manufactured by Circor Aerospace at the Corona facility in California, not having the “TQL” marking. Fuel check valves manufactured at the Corona facility have the “CORONA CA” marking. Regardless of the manufacturing date, fuel check valves with the “TQL” marking are not affected by this bulletin. This revision corrects the metric dimension provided in Part I for the fuel check valve outside diameter measurement in addition to minor editorial changes.

Applicability of this bulletin to any spare part shall be determined prior to its installation on an affected helicopter.

APPROVAL:

The engineering design aspects of this bulletin are FAA approved for FAA certified helicopters as listed in the applicable Type Certificate Data Sheet. For non FAA certified helicopters, the engineering design aspects of this bulletin are Bell Engineering approved.

CONTACT INFO:

For any questions regarding this bulletin, please contact:

Bell Product Support Engineering
Tel: 1-450-437-2862 / 1-800-363-8023 / productsupport@bellflight.com

MANPOWER:

Approximately 1 man-hour is required to accomplish Part I of this bulletin and 0.5 man-hour to accomplish Part II. Approximately 1 man-hour per check valve is required to accomplish Part III of this bulletin. This estimate is based on hands-on time and may vary with personnel and facilities available.

WARRANTY:

There is no warranty credit applicable for parts or labor associated with this bulletin.

MATERIAL:

Required Material:

The following material is required for the accomplishment of this bulletin and may be obtained through your Bell Supply Center.

<u>Part Number</u>	<u>Nomenclature</u>	<u>Qty (Note)</u>
209-062-607-001	Fuel check valve	A/R (1)

NOTE 1: Two fuel check valves are installed per helicopter. Replacement will be required only if the valve does not meet the inspection requirements.

Consumable Material:

None required.

SPECIAL TOOLS:

None required.

WEIGHT AND BALANCE:

Not affected.

ELECTRICAL LOAD DATA:

Not affected.

REFERENCES:

BHT-212-MM Maintenance Manual, Chapter 28
Alert Service Bulletin 212-15-155 RA

PUBLICATIONS AFFECTED:

None affected.

ACCOMPLISHMENT INSTRUCTIONS:

Part I. Fuel check valve inspection.

1. Prepare the helicopter for maintenance and gain access to the fuel check valves. The check valves are located in the aft pylon area (Figure 1).

-NOTE-

It is not necessary to remove the fuel check valve for inspection. Regardless of manufacturing date, any fuel check valves with the "TQL" marking are not affected by this bulletin. Fuel check valves manufactured by other suppliers are also not affected by this bulletin. Fuel check valves with the "CORONA CA" marking and without the "TQL" marking are affected by this bulletin. (Figure 2, Details A and B).

2. Verify if the check valves installed are affected by this bulletin.
3. If the check valves are not affected, make an entry in the helicopter logbook and historical service records indicating the findings and compliance with this Alert Service Bulletin.
4. If one or both check valves are affected, proceed as follows:
 - a. Using a caliper or equivalent, measure the check valve housing at the center and record dimension (Figure 3).
 - b. Measure the housing at the inlet end where the threaded fitting is installed and record dimension.
 - c. If the dimension measured at the inlet end is no more than 0.003 inch (0.0762 mm) greater than the measurement at the center, the valve is serviceable and does not require further inspection or replacement. Make an entry in the helicopter logbook and historical service records indicating the findings and compliance with this Alert Service Bulletin.

-NOTE-

Due to possible delay in getting replacement check valves, Bell recommends that operators place their order as soon as Part I is accomplished if one or two check valves are found defective.

- d. If the dimension measured at the inlet end is greater than 0.003 inch (0.0762 mm) when compared to the measurement at the center, the valve will require

replacement. Part III can be accomplished immediately, or Part II can be accomplished until the defective valve can be replaced in accordance with Part III.

- e. If the defective check valve is not replaced immediately, make an entry in the helicopter logbook and historical service records indicating the findings and that Part II must be accomplished every 25 flight hours or 30 days whichever comes first until Part III is accomplished.

Part II. Recurring 25 flight hour or 30-day inspection.

1. Prepare the helicopter for maintenance and gain access to the fuel check valves (Figure 1).
2. Using a strong light source, visually inspect the fuel check valves for general condition and fuel leaks. Inspect for cracks at the inlet end where the threaded fitting is installed (Figure 3).
3. If a crack is found, replace the check valve prior to next flight. Figure 4 shows an example of a cracked check valve.
4. If no cracks or any other defects that would cause the valve to be unserviceable are found, make an entry in the helicopter logbook and historical service records indicating the findings and that Part II will require accomplishment until Part III is accomplished.

Part III. Fuel check valve replacement.

-NOTE-

The accomplishment of Part III constitutes the terminating action of this ASB.

1. Prepare the helicopter for maintenance and gain access to the fuel check valves (Figure 1, Details A and B).
2. Refer to the applicable Maintenance Manual and replace defective fuel check valve(s) (BHT-212-MM, Chapter 28).
3. Make an entry in the helicopter logbook and historical service records indicating compliance with this Alert Service Bulletin.



Figure 1. Fuel Check Valves Location



Detail A. Circor Aerospace Fuel Check Valve Marked "TQL"



Detail B. Fuel Check Valve not Manufactured by Circor Aerospace

Figure 2. Fuel Check Valves not Affected




Figure 3. Fuel Check Valve Outside Diameter Measurement




Figure 4. Cracked Fuel Check Valve