



ALERT SERVICE BULLETIN INDEX

NOTE

THIS INDEX IS A LIST OF ALERT SERVICE BULLETINS ISSUED. THIS INDEX DOES NOT IDENTIFY WHICH ALERT BULLETINS ARE ACTIVE OR INACTIVE.

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Alert Service Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-206A/B/B3-ASB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL® HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

206A/B/B3 ALERT SERVICE BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206A-1	Basic	10-10-67		VII	Engine Droop Compensator Safety Wire Provisions
206A-2	Basic	10-16-67		IV	Cyclic Control System Inspection and Addition of Shield
206A-3	Basic	10-25-67		VII	Exhaust Stack Clamp, Inspection and Safety Wiring
206A-4	Basic Rev. A	11-8-67 1-20-68		VII	Engine Mount, Inspection and Addition of Support Bracket
206A-5	Basic	11-9-67		IV	Tail Rotor Control, Addition of Friction Clamp, Spring and Support
206A-6	Basic	11-10-67		IV	Cyclic and Collective Control Tubes, Inspection of
206A-7	Basic	8-22-68		VIII	Magnesium Tail Boom, Inspection of
206A-8	Basic	10-21-68		VI	Transmission Spider, Inspection and Retirement of
206A-9	Basic	12-30-68		VI	Fan Shaft Assembly, Inspection
206A-10	Basic	4-11-69		VI	Transmission Spindle, Inspection of

BHT-206A/B/B3-ASB INDEX**206A/B/B3 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
206A-11	Basic Rev. B	5-9-69 9-29-69		IV	Cyclic Control Bellcrank Support, Replacement of
206A-12	Basic Rev. A	7-25-69 4-8-70		V	Hydraulic Cylinder, P/N 41103750, 41103750-2, and 41103650-005, Retirement Life
206A-13	Basic	8-4-69		IV	Dual Control, Lever Assy., Inspection of
206A-14	Basic Rev. C	12-12-69 4-8-70		VI	Transmission Spider, Retirement of
206A-15	Basic	12-19-69		VIII	Tail Rotor Gear Box and Tail Boom, Inspection of
206A-16	Basic	3-3-70		S.I.	Snow Winterization Kit, Modification
206A-17	Basic	9-10-70		VI	Installation and Inspection of Improved Magnetic Plug, Updating Transmission
206A-18	Basic	11-19-70		VII	Aluminum Fuel Lines, Replacement of
206A-19	Basic Rev. C	12-18-70 12-11-73		II	Main Rotor Blade Inspection
206-20	Basic Rev. A	12-10-71 2-21-72		II	Strap, P/N 206-031-200-23 and -24, Inspection of
206-21	Basic Rev. A	7-24-72 8-14-73		S.I.	Pop-Out Float System Valve Assy., Functional Check Procedure of
206-22	Basic	10-25-72		IV	Idler Assy., P/N 206-001-746-5, Inspection and Rework
206-23	Basic	11-13-72		VI	Main Rotor Mast Inspection
206-24	Basic	11-21-72		II	Nuts, P/N NAS1022A14, Inspection of
206-25	NEVER ISSUED				
206-26	Basic	12-18-72		VIII	Vertical Fin, Inspection of
206-01-73-1	Basic	1-9-73		VIII	Vertical Fin, Inspection of
206-01-73-2	Basic Rev. A	3-9-73 3-27-73		VIII	Pylon Support Link, Inspection of

206A/B/B3 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
206-01-73-3	Basic Rev. B	4-12-73 10-23-73		VIII	Removal of Metal Plug Buttons
206-01-73-4	Basic Rev. B	4-16-73 10-16-73		VIII	Tailboom Skin Splice Rivets, Inspection of
206-01-73-5	Basic Rev. A	6-27-73 9-21-73		VIII	Vertical Fin Support, Inspection and Replacement of
206-01-73-6	Basic	9-19-73		VIII	Pylon Support Links, P/N 206-031- 508-5 and -7, Retirement of
206-01-73-7	Basic Rev. E	11-16-73 9-18-74		VIII	Horizontal Stabilizers, Inspection and Rework of
206-03-73-1	Basic Rev. C	10-19-73 2-25-75		XI	Starter Generator Retaining Clamp "T" Bolt, Inspection and Replacement of
206-04-73-1	Basic	8-8-73		VI	Tail Rotor Gear Inspection
206-04-73-2	Basic Rev. A	11-13-73 10-21-75		VI	Restricted Use of Grease, P/N 204-040-755-3
206-(04-1)-73-1	Basic	6-25-73		II	Main Rotor Hub Strap Fittings and Pins, Retirement of
206-(04-2)-73-1	Basic	5-7-73		IV	Main Rotor Pitch Link Tubes, Inspection of
206-(04-2)-73-2	Basic	5-15-73		IV	Swashplate Bearing, Inspection of
206-06-73-1	Basic Rev. A	4-27-73 6-26-73		V	Hydraulic Servo Actuator Piston Assy., P/N 41000005, Inspection and Rework of
206-06-73-2	Basic	5-11-73		V	Hydraulic Servo Actuator Servo Valve Drive Locknut, Inspection of
206-12-73-1	Basic Rev. A	6-26-73 7-19-73		S.I.	Heater Fuel Line Inspection
206-50-73-1	Basic	1-16-73		S.I.	Heater Fuel Line Inspection
206-50-73-2	Basic Rev. A	4-4-73 8-6-73		S.I.	Rotor Brake Disc Assy, Inspection of
206-01-74-1	Basic Rev. B	4-17-74 6-4-74		VIII	Horizontal Stabilizer Stop, Kit Installation of

BHT-206A/B/B3-ASB INDEX**206A/B/B3 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206-01-74-2	Basic	11-12-74		VIII	Cabin Roof Straps, Mandatory Replacement of by 30 September 1975
206-01-74-3	Basic	10-16-74		VIII	Transmission Mount Spindle, Inspection of
206-04-74-1	Basic Rev. B	6-25-74 10-8-74		VI	Tail Rotor Driveshaft Bearing Hanger Screws, P/N 206-040-323-1, Mandatory Replacement of
206-(04-1)-74-1	Basic Rev. A	8-20-74 8-22-74		II	Main Rotor Hub Yoke, Inspection and Rework Mandatory by 31 December 1974
206-(04-1)-74-2	Basic	11-21-74		II	Main Rotor Grip Inspection
206-(04-2)-74-1	Basic	6-20-74		IV	Cyclic and Collective Control System Attaching Bolts Mandatory Replacement by 30 July 1974
206-06-74-1	Basic Rev. A	9-6-74 10-8-74		V	Hydraulic Servo Actuators, Inspection of
206-06-74-2	NEVER ISSUED				
206-06-74-3	Basic	12-10-74		V	Hydraulic Pump and Reservoir Repair to Stop Fretting, Mandatory by 15 January 1975
206-08-74-1	Basic	3-25-74		VII	Oil Pressure Tube Assy., Mandatory Replacement by 1 July 1974
206-10-74-1	Basic	1-29-74		VII	Fuel Cell Cavity and Vent Line Modification
206-10-74-2	Basic Rev. A	3-21-74 5-8-74		VII	Fuel Cavity Vent Line, Modification
206-50-74-1	Basic Rev. A	9-17-74 10-29-74		S.I.	Rotor Brake Shock Mounted Disc Assy., Mandatory Removal by 30 September 1974
206-75-1	Basic	3-4-75		VI	Tail Rotor Drive Installation, Inspection of
206-75-2	Basic Rev. A	2-18-75 4-16-75		IV	Tail Rotor Control Tube, Inspection Mandatory by 20 March 1975

206A/B/B3 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
206-75-3	Basic	5-1-75		II	Main Rotor Hub Pillow Blocks Epoxy Resin Coated Flanged Bushings, Installation of
206-75-4	Basic	5-15-75		III	Tail Rotor Yoke Retirement
206-75-5	Basic	5-22-75		S.I.	Rework of External Hoist, Mandatory by 1 September 1975
206-75-6	Basic Rev. B	6-6-75 1-12-76		XI	Fuel Pump Circuit Capacitor, Removal of
206-75-7	Basic	9-5-75		VIII	Passenger Door Hinge Rivets, Inspection of
206-75-8	Basic	10-16-75		VII	Fuel Purge Line 10 Micron Filters, Installation of
206-75-9	Basic	10-25-75		V	Hydraulic Pressure Regulator Valve, Modification of
206-75-10	Basic	11-13-75		II	Main Rotor Blades, P/N 206-010-200-29, Mandatory Retirement of
206-76-1	Basic	1-26-76		IV	Inspection of Hydraulic Servo Actuator Support Assembly, P/N 206-001-520-5, for Cracks in Forward Web
206-76-2	Basic	2-6-76		II	Installation of Model 206L Main Rotor Split Cone Set, P/N 206-010-003-7, on Model 206B Helicopters
206-76-3	Basic	4-20-76		VII	Inspection of Fuel System
206-76-4	Basic Rev. B	5-7-76 7-8-76		II	Inspection of Main Rotor Hub Tension/Torsion Strap Assembly, P/N 206-010-105-3
206-76-5	Basic	5-12-76		V	Inspection of Hydraulic Servo Actuators, P/N 206-076-031-7 or -13 (H. R. No. 41000670-1, -003, or -005)
206-76-6	Basic	6-16-76		VII	Linear Actuator, P/N 206-062-721-1 or -11 (Vendor P/N 7185-1)

BHT-206A/B/B3-ASB INDEX**206A/B/B3 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
206-76-7	Basic Rev. A	8-13-76 1-6-77		II	Reduction of Service Life, Tension/ Torsion Straps, P/N 206-010-105- 3. Replacement of Strap Fittings, P/N 206-010-155-11 and -15
206-76-8	Basic Rev. A	7-13-76 8-20-76		IV	Installation of Taper Washers Under Hydraulic Servo Actuator Support Assembly
206-76-9	Basic Rev A	7-23-76 7-23-76		IV	Installation of Bearings, P/N 206- 040-339-9
206-76-10	Basic Rev. B	8-26-76 10-7-76		VIII	Replacement of Litter Door Post Striker Housing Assembly
206-76-11	Basic	9-7-76		VI	Replacement of Collars, P/N 206- 040-319-3 and -5
206-76-12	Basic Rev. A	9-7-76 12-2-76		VI	Installation of Bearings, P/N 206- 040-339-9
206-77-1	Basic	3-15-77		II	Main Rotor Hubs P/N 206-010-100 and 206-011-100 (All Dash Numbers)
206-77-2	Basic	3-22-77		S.I.	Rotor Brake Kits - Replacement of Lining Retention Screws
206-77-3	Basic	4-1-77		VII	Inspection of Tube Assembly, P/N 206-061-541-1 or 206-061- 522-1, for Evidence of Chafing
206-77-4	Basic	4-6-77		II	Reduction in Calendar Life, Tension/Torsion Straps, P/N 206-010-105-3 and -5
206-77-5	Basic Rev. A	5-12-77 5-16-77		VI	Inspection of Oil Cooler Blower Impeller, P/N 206-061-432-5
206B-77-6	Basic	6-20-77		VII	N ₂ Operating Speed Restriction
206-77-7	Basic	10-10-77		II	Retirement Time and Calendar Life, Tension/Torsion Straps, P/N 206-010-105-3 and -5, and 206-011-147-1
206-77-8	Basic	10-20-77		B3: 66	Inspection of Oil Cooler Blower Impeller, P/N 206-061-432-11

206A/B/B3 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
206-77-9	Basic	10-21-77		A/B: VI	Replacement of Tail Rotor Drive Shaft Clamp Type Bearing Hangars With Shims
206-77-10	Basic Rev. A	12-8-77 2-21-78		B3: 66	Replacement of Oil Cooler Blower Impeller, P/N 206-061-432-11, With Impeller, P/N 206-061-432-31
206-78-1	Basic	4-14-78		A/B:II B3:65	M/R Hub Tension Torsion Straps, P/N 206-010-105-3, -5, Retirement of
206-78-2	Basic	12-18-78		B3: 66	Freewheeling Outer Race Shaft, P/N 206-040-221-3, Inspection
206-79-3	Basic	5-23-79		A/B: XII B3:97	VOR Antenna P/N CI-159 and CI-159A
206-79-4	Basic	7-17-79		A/B: II B3: 65	Main Rotor Yoke, P/N 206-010-101 (All Dash Numbers), Inspection and Retirement Life of
206-79-5	Basic	10-24-79		A/B: VI B3: 66	206 Main Input Driveshaft Assy, P/N 206-040-100-13, Inspection Interval of
206-80-6	Basic	2-22-80		A/B: III B3: 65	Tail Rotor Blade, P/N 206-010-750-005 and -007, Inspection of
206-80-7	Basic Rev. B	2-26-80 10-15-80		A/B: 11 B3:65	Main Rotor Trunnion, P/N 206-010-136-001, 206-010-136-003, and 206-011-113-001, Inspection Requirements
206-80-8	Basic	4-11-80		A/B: IV B3:27	Anti-Torque Control System Procedures
206-80-9	Basic	6-3-80		A/B: II B3:65	Addition of Calendar Life Retirement on TT Straps, P/N 206-011-147-001 and 206-011-147-005
206-80-10	Basic	6-4-80		A/B: VII B3:71	Engine Lower Center Support Legs Acoustic Mounts, Modification of

BHT-206A/B/B3-ASB INDEX**206A/B/B3 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206-80-11	Basic	6-27-80		S.I.	External Hoist Kit, P/N 206-706-126-001, Mod and Inspection of (Inspect and Modify as Described in the Attached Breeze Corp. Bulletin No. BEB-162-8)
206-80-12	Basic	9-9-80		A/B: III B3: 65	Aluminum Tail Rotor Blade, P/N 206-010-750-005 and -007, Retirement and Replacement of
206-81-13	Basic	4-24-81		S.I.	Stability and Control Augmentation System (SCAS) Anti-Torque Cylinder Assembly, Inspection and Rigging of
206-81-14	Basic	6-22-81		A/B: VII B3:71	Engine, Allison 250-C20/C20B, N1 and N2 Operating Speed Restrictions
206-81-15	Basic Rev. A	8-21-81 9-28-81		S.I.	External Hoist and Hoist Provision Kits, P/N 206-706-124-001/003, 206-706-126-001/003, Addition of Ground to Hoist Assy. and Route Shield Through Electrical Connector on
206-82-16	Basic	5-19-82		A/B: III B3:65	Tail Rotor Blade, P/N 206-016-201-001 and 206-016-201-103, Check and Repair of
206-82-17	Basic	5-28-82		S.I.	Skid Mounted, Light-Weight Emergency Flotation System Kit, P/N 206-706-211-101 and -103, Float Restraint Tubes, P/N 206-050-269-101, Addition of
206-82-18	Basic	7-19-82		B3: 28	Fuel Shutoff Valve, Provision for Thermal Relief
206-82-19	Basic	11-15-82		A/B: VI B3: 66	Tail Rotor Gearbox P/N 206-040-400 (All Dash Numbers), Inspection of
206-83-20	Basic	8-29-83		S.I.	External Hoist Kits, P/N 206-706-126-1/-5/-101/-103, Hoist P/N BL-16600 (All Dash Numbers), Conversion and Inspection of

206A/B/B3 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206-83-21	Basic Rev. A	12-22-83 2-29-84		A/B: VI B3: 66	Mast Assembly, Main Rotor, P/N 206-010-332, Inspection and Processing of
206-84-22	Basic	1-4-84		B3: 28	Fuel Supply Tube Assembly, P/N 206-061-452-101, Replacement of
206-84-23	Basic	1-24-84		S.I.	Emergency Flotation Kit Reservoir and Piping Installation, P/N 206-073-801-001, Clamps, P/N MS 21920-53, Replacement
206-84-24	Basic	8-30-84		S.I.	Reservoir, Emergency Flotation, P/N 274645, 206-073-919-001, 206-073-919-003, 206-073-919- 005, 206-073-919-007, Installation of Decal (WARNING), P/N 31-023- 8B, Decal (CAUTION), P/N 31-023-9B, On
206-84-25	Basic	8-30-84		S.I.	Reservoir, Emergency Flotation, P/N 1269556-4, Installation of Decal (WARNING), P/N 31-023- 8B, and Decal (CAUTION), P/N 31-023-9B, On
206-84-26	Basic	8-30-84		S.I.	Reservoir, Emergency Flotation, P/N 206-073-922-1, -101, 206- 073-919-1, -3, -5, -7, Installation of Decal (WARNING), P/N 31-023- 8B, and Decal (CAUTION), P/N 31-023-9B, On
206-85-27	Basic Rev. A	2-13-85 3-15-85		S.I.	Quick Disconnect Dual Controls P/N 206-706-127-1, -101, -109, Installation of Spring Pin Assembly
206-85-28	Basic Rev. B	3-7-85 6-21-85		A/B: III B3: 65	Tail Rotor Blade, P/N 206-016-201- 001/-103/-107, Check and Rivet Replacement
206-85-29	Basic	6-21-85		A/B: IV B3:27	Cyclic Control Stick Assembly, P/N 206-001-334-1/-101, and 206- 001-381-7, Inspection of

BHT-206A/B/B3-ASB INDEX**206A/B/B3 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206-85-30	Basic Rev. B	9-30-85 10-13-86		S.I.	External Hoist Kits, P/N 206-706-126-1/-5/-101/-103, Conversion of Hoist P/N BL-16600-80 to P/N BL-16600-110
206-86-31	Basic	3-24-86		A/B: IV	Tail Rotor Crosshead, P/N 206-011-857-001, Installation of
206-86-32	Basic	3-27-86		A/B: X B3: 95	206-070-263-005 Altimeter, Malfunction of Setting Knob Mechanism
206-86-33	Basic	8-13-86		A/B: VI B3: 66	Oil Cooler Blower Impeller P/N 206-061-432-031, Inspection of
206-86-34	Basic Rev. A	9-30-86 10-23-86		A/B: VII B3: 28	Airframe Fuel Filter Assembly P/N 222366-621-003 and P/N 52-2889-016 or -016A, Modification of
206-87-35	Basic	1-19-87		S.I.	Reservoir Assembly, P/N 206-073-848-103/-105/-109, Valve Assembly, P/N 206-073-915-005/-101, Cap, Replacement of
206-87-36	Basic Rev. A	1-28-87 6-17-87		S.I.	Rescue Hoist Cable Cutter Circuit, Rewiring of, In Accordance with Breeze Manufacturing Preferred Method
206-87-37	Basic	4-23-87		A/B: VI B3: 66	Main Rotor Mast, P/N 206-010-332-121, Return for Metallurgical Evaluation
206-87-38	Basic	5-26-87		-	Wire Strike Protection System, Inspection and Rework of
206-87-39	Basic	9-17-87		A/B: IV B3: 65	Tail Rotor Pitch Link(s), P/N 206-010-793-101, Inspection of
206-87-40	Basic Rev. A	10-8-87 11-3-87		A/B: VII B3: 28	Engine Fuel Valve Electrical Connector, P/N 3456W14S-5S, One Time Inspection of
206-88-41	Basic	1-28-88		A/B: III B3: 65	Tail Rotor Yoke, P/N 206-011-819-101, Return for Inspection and Rework

206A/B/B3 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206-88-42	Basic Rev. A	7-26-88 8-26-88		S.I.	External Hoist, P/N BL-16600-(All Dash Numbers), Inspection of Load Cable and Hook/Bumper Stowage
206-89-43	Basic Rev. A	1-10-89 8-1-89		A/B: VII B3: 79	Aeroquip 601 Hose Assemblies, One-Time Inspection and Replacement
206-89-44	Basic	3-21-89		A/B: VII B3: 71	Pc Air Filter Housing Assembly, Replacement of
206-89-45	Basic Rev. B	4-11-89 7-28-92		A/B: VII	Bendix Power Turbine Governor Py Port, Inspection of
206-89-46	Basic Rev. A	8-2-89 8-29-89		A/B: II B3: 65	Strap Assembly, Main Rotor, Tension-Torsion P/N 206-011-147-7 and P/N 206-011-154-101/-105, Removal from Service
206-89-47	Basic Rev. A	8-20-89 8-29-89		A/B: III B3: 65	Tail Rotor Hub Assembly P/N 206-011-810-015 and Tail Rotor Yoke P/N 206-011-811-009, Removal from Service
206-89-48	Basic	9-21-89		A/B: II B3: 65	Main Rotor Flight Control System Bolts, Inspection of
206-89-49	Basic	10-10-89		S.I.	Emergency Float Bag Inflation Valve Restrictors-Installation of, (Service Instruction 206-115)
206-89-50	Basic Rev. A	10-25-89 11-29-89		A/B: II	Main Rotor Blade P/N 206-010-200-033, Removal from Service
206-89-51	Basic Rev. B	10-29-89 2-5-90		S.I.	Breeze-Eastern Cargo Hooks P/N SP4232-5, -31 and 14027-2, Warning Plate, Addition of
206-90-52	Basic Rev. B	2-23-90 3-5-92		A/B: IV	Tail Rotor Control Tube-Inspection For Possible Interference of
206-90-53	Basic	5-15-90		A/B:XII B3: 97	VOR Antenna P/N CI-259D Date Coded D/M 8930 to D/M 9015 Inclusive
206-90-54	Basic	5-31-90		A/B: XI B3:96	Fuel Valve Switch Guard, Installation of

BHT-206A/B/B3-ASB INDEX**206A/B/B3 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206-90-55	Basic Rev. A	6-12-90 7-16-90		A/B:VII B3:71	Turbine Spline Adapter, Replacement of
206-90-56	Basic Rev. A	6-21-90 1-15-91		A/B: VI B3: 66	Sungear P/N 206-040-662-101, Recall of by Serial Number
206-90-57	Basic	6-27-90		A/B: III B3: 65	Tail Rotor Blade P/N 206-016-201- 113 and 206-016-201-127, Inspection of
206-90-58	Basic Rev. A	9-18-90 10-31-90		A/B: III B3: 65	Tail Rotor Blade 206-016-201-125/ -127, Removal From Service
206-91-59	Basic	1-30-91		A/B: VI	Bearing Hanger, 206-040-346 One Time Insp.
206-91-60	Basic	6-28-91		A/B: VII B3: 53	PART I: Vertical Fin Supports P/N 206-031-417 and 206-031- 418, Inspection and Modification of PART II: Vertical Fin Assembly P/N 206-020-113-5, -7, -9, -107 Inspection for Gaps and Addition of Mounting Spacers, if Required
206-91-61	Basic	9-13-91		A/B: VI B3:66	Driveshaft Seal Assembly 206-040-272-101, Replacement of
206-91-62	Basic	9-19-91		A/B: VIII B3: 25	Restraint Assembly 222-320-823- 109, -111, Improvement of
206-91-63	Basic Rev. A	10-10-91 10-31-91		A/B: VII B3:76	Possible Incorrect Max Fuel Flow Setting on Certain Bendix Fuel Controls
206-91-64	Basic	11-21-91		A/B: VIII B3: 53	Horizontal Stabilizer Spare Assembly P/N 206-020-120-011, Removal From Service
206-91-65	Basic	11-26-91		A/B: VII 83:71	Engine Bleed Valve, Removal From Service
206-92-66	Basic	5-5-92			Main Rotor Pillow Block Retention Hardware, Replacement of Bolt MS21250-04018
206-92-67	Basic	5-7-92			Tail Rotor Gearbox Oil Level Indicators 204-040-508-001 and 204-040-508-011

206A/B/B3 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206-92-68	Basic	8-5-92			Flap Restraint 206-011-117-003
206-92-69	Basic Rev. A	9-29-92 2-27-95			Bracket, Bearing Support 206-030-407-007/-009 and 206- 030-433-005/-007/-011/-013/-015 and -017, One Time Inspection
206-92-70	Basic	12-3-92			Main Rotor Latch Bolt 206-011- 260-101 and -103, Removal of Unapproved Bolts From Service
206-92-71	Basic	12-8-92			Fuel Quantity Probes 7740-00381 and 7740-00302, One Time Inspection
206-92-72	Basic	12-14-92			Torque Transducer 206-061-535- 005-011, -013, Replacement of
206-93-73	Basic Rev. A	6-21-93 6-20-94			Cargo Hook, Breeze Eastern Customer Advisory Bulletin No. CAB-100-41 and Customer Service Bulletin No. CSB-143 and CSB-144
206-93-74	Basic Rev. B	9-7-93 4-4-94			Swashplate Support Assembly 206-010-452-001/-005/-109, Inspection of
206-93-75	Basic	10-19-93			Trunnion 206-011-113-103 Master Spline Mislocation of
206-93-76	Basic Rev. B	12-7-93 9-6-94			Main Driveshaft Grease Lubricated Couplings 206-040-108 and 206- 040-118, Over-Temperature Indicators, Installation of
206-93-77	Basic	11-17-93			Main Rotor Blade 206-010-200- 133 Inspection and Rework
206-94-78	Basic	4-11-94			Landing Gear Assembly Improve- ment: Crosstube Assemblies, Replacement of and Skid Tube Assemblies, Modification of
206-94-79	Basic	5-5-94			Tail Rotor Pitch Horn 206-011-809- 005/-107/-109, Looseness Check of

BHT-206A/B/B3-ASB INDEX**206A/B/B3 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206-94-80	Basic	8-2-94			Main Rotor Trunnion 206-011-113-103, Removal From Service
206-94-81	Basic Rev. A	8-17-94 11-1-95			Landing Gear Assembly Improvement; Fixed Floats Kit P/N 206-706-008-013, Crosstube Assemblies P/N 206-050-169-001/-003, Replacement of
206-94-82	Basic Rev. A	9-6-94 4-17-95			Landing Gear Assembly Improvement; Emergency Flotation System Kit P/N 206-706-010, Crosstube Assemblies P/N 206-050-134-001, -007, -103, -003, -005, -011 and -105, Replacement of
206-94-83	Basic	9-6-94			Landing Gear Assembly Improvement Emergency Lightweight Float Kit P/N 206-706-211, Crosstube Assemblies P/N 206-050-107-25, -27, -119 and -121, Replacement of Skid Tube Assemblies P/N 206-050-246-ALL Dash Numbers, Modification of and Step Assemblies, P/N 206-050-259, Modification of
206-95-84	Basic	7-24-95			Hydraulic Servo Actuators (HR Textron) Shoulder Bolts, One Time Inspection of
206-95-85	Basic	9-5-95			Main Drive Shaft 206-040-015-103 Inner Coupling to Shaft Attachment Hardware, One Time Inspection of
206-95-86	Basic Rev. B	9-11-95 12-18-95			Tail Rotor Driveshaft Hanger Assembly and Spring, Inspection of
206-96-87	Basic Rev. A	2-26-96 3-22-96			Cyclic and Collective Servo Support Assembly P/N 206-001-566-105, Identification of

206A/B/B3 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206-96-88	Basic	6-3-96			Landing Gear Assembly Improvement; Fixed Float Kit P/N 206-706-008-011; Crosstube Assemblies P/N 206-050-157-001 & -003, Replacement of
206-97-89	Basic	5-20-97			R-134a Air Conditioning System Installation Hardware, Replacement of
206-97-90	Basic	6-20-97			Main Rotor Hub Pillow Block, Change in Retention Hardware
206-97-91	Basic	10-10-97			Engine Driven Fuel Pump (CECO), Internal Drive Spline, Inspection of
206-98-92	Basic Rev. A	10-14-98 10-10-02			Engine Fuel Control Unit, Internal Spring Replacement
206-00-93	Basic Rev. A	3-10-00 5-10-00			Collective Lever Assembly 206-010-467-001, Modification and New Collective Lever Assembly/-105, Introduction of
206B1-01-94	Basic	1-19-01			Magnetic Brake P/N 204-001-376-003, One Time Inspection of
206-01-95	Basic	3-6-01			Rescue Hoist, BL-16600 Series, Breeze Eastern Customer Alert Bulletin CAB-100-58
206-01-96	Basic Rev. A	3-30-01 5-7-01			Chip Detector Assembly, Tedeco B3188B
206-01-97	Basic	7-26-01			Strap Fittings P/N 206-011-140-001, Tail Rotor Gearbox Input Pinions, P/N 206-040-405-101, Inspection and Recall of Specific Serial Number Part
206-01-98	Basic	10-11-01			Rolls Royce Engine, Gearbox Assembly – Inspection of Helical Torquemeter Gearshaft Assembly
206-02-99	Basic Rev. A	11-26-02 1-31-03			Main Rotor Blades 206-010-200-ALL Inspection and Rework of

BHT-206A/B/B3-ASB INDEX**206A/B/B3 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206-04-100	Basic Rev. C	3-12-04 3-22-05			Tail Rotor Blades 206-016-201-133/-131 Check/Inspection of
206-04-101	Basic	9-13-04			Tail Rotor Blade 206-016-201-131, Check and Removal from Service of
206-04-102	Basic	9-24-04			Inside Door Handle Assembly P/N 206-031-620-101, Inspection and Rework of
206-05-103	Basic Rev. A	2-15-05 7-12-06			Fuel Distribution System, Inspection and Rework of
206-05-104	Basic	5-17-05			Torque Indicator 206-075-739-125, Recall of
206-05-105	Basic	11-8-05			Tail Rotor Trunnion Housing Seal 535642 Installation, One Time Inspection of
206-06-106	Basic	2-17-06			Float Inflation Valve Squib P/N 29022968, Misidentification of
206-06-107	Basic Rev. A	4-26-06 6-15-06			Vertical Fin Supports 206-031-417-003/-007 and 206-031-418-001/-005, Inspection of
206-06-108	Basic	7-8-06			Aeronautical Accessories Inc. Flat Crew Door Window P/N 206-202-001 and 206-202-002, STC SH5773SW
206-06-109	Basic	7-25-06			Main Rotor Latch Bolts 206-010-169-001/-003 and 206-011-122-003, Removal from Service of
206-06-110	Basic	9-7-06			Upper Left-hand Tailboom Attachment Hardware, Inspection of
206-06-111	Basic	10-12-06			Engine, Turbine Assembly — Power Turbine Outer Shaft

206A/B/B3 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206-07-112	Basic	3-9-07			Aeronautical Accessories, Inc. PC Safety Valve™ Stem Over Torque STC SE5511NM
206-07-113	Basic	3-23-07			Cargo Hook Stress Corrosion Cracks
206-07-114	Basic	3-28-07			Disc Assembly P/N 32721-1, Inspection of
206-07-115	Basic	5-21-07			Power Turbine RPM (N2) Steady State Operation Avoidance, Introduction of
206-07-116	Basic Rev A	9-11-07 9-19-07			Tail Rotor Blade Assembly, Inspection of

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
---------------	--------------	-------------	---------------	--------------------------	----------------

BHT-206A/B/B3-ASB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------