



A Textron Company

## **INFORMATION LETTER**

**206-24-106**

3 December 2024

**TO: All owners and operators of Model 206A/B helicopters**

**SUBJECT: DRIVESHAFT ASSEMBLY 206-040-330-001 DISCONTINUED**

This information letter is to inform owners / operators of 206A/B models serial numbers 4 through 1251 equipped with tail rotor driveshaft (one-piece long shaft) 206-040-330-001 that spares production of this part has ceased.

As a solution to this driveshaft part obsolescence, Technical Bulletin 206-23-212 segmented tail rotor driveshafts retrofit can be accomplished.

For any questions regarding this letter, please contact:

Bell Product Support Engineering

Tel: 1-450-437-2862 / 1-800-363-8023 / [productsupport@bellflight.com](mailto:productsupport@bellflight.com)