



A Textron Company

## **INFORMATION LETTER**

**412-25-99**  
14 January 2025

**TO: All owners and operators of 412EPX helicopters**

**SUBJECT: 412EPX TRANSMISSION OVERHAUL INTERVAL REDUCTION**

Bell is continually assessing the in-service reliability of our components. Recently it has been determined that the 412EPX (S/N 39101 and subsequent) configuration transmission assembly 412-040-008-103/-105/-107 overhaul interval needs to be reduced from 6000 hours to 3000 hours.

Following the overhaul interval reduction to 3000 hours there will be no scheduled interim inspection required.

The 412EPX Maintenance Manual Supplement (MMS) Component Overhaul Schedule (DMC-412-A-05-10-00-01A-281A-A) will be amended to reflect the overhaul interval change.

Bell will be initiating a Lead the Fleet effort in the next few months where in-service transmissions will be evaluated with the goal of increasing the overhaul interval in the future. Bell will be providing additional details in the near term on how the voluntary program will work.

For any questions regarding this letter, please contact:

Bell Product Support Engineering  
Tel: 1-450-437-2862 / 1-800-363-8023 / [productsupport@bellflight.com](mailto:productsupport@bellflight.com)