



A Textron Company

INFORMATION LETTER

407-20-120
29 October 2020

TO: All owners and operators of Model 407 helicopters

SUBJECT: MAIN ROTOR BLADE TRAILING EDGE VOIDS/GAPS

The purpose of this Information Letter (IL) is to inform owners/operators of possible voids or gaps that may be found on the trailing edge area of some main rotor blades 407-015-001-137 that have been delivered. A complete stock purge of the Bell inventory has been accomplished, therefore no new main rotor blade deliveries following the release date of this letter should have these defects.

If voids or gaps are found on the trailing edge area during scheduled/periodic inspections, they can be repaired in accordance with the 407-MM Maintenance Manual [DMC-407-A-62-10-00-10A-685A-A](#).



For any questions regarding this letter, please contact:

Bell Product Support Engineering
Tel: 1-450-437-2862 / 1-800-363-8023 / productsupport@bellflight.com