



TECHNICAL BULLETIN INDEX

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

15 SEPTEMBER 2011

205A1 TECHNICAL BULLETIN INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205-01-73-1	Basic	25-Oct-73	Modification of Tailboom, P/N 205-032-802 (All Dash Numbers)
TB 205-03-73-1	Basic	30-Jan-73	Engine Mount - Allowable Rod End Bearing Wear Limits
TB 205-04-73-1	Basic	26-Jun-73	Modification Instructions for Incorporating 212 Type Support Case
TB 205-04-73-2	Basic	4-Jun-73	Modification of Main Driveshaft Boot Assembly, P/N 205-040-176-3
TB 205-04-73-3	Rev A	13-Sep-73	Increase Torque of the Mast Lower Bearing Retainer Nut, P/N 204-040-309-1
TB 205-04-73-4	Basic	10-Sep-73	Special Tool, P/N T101586, Pusher Set
TB 205-(04-2)-73-1	Basic	3-Apr-73	Scissors Assembly, P/N 204-011-406-15, and Tube Assembly (Mixing Lever to Scissors Assembly), P/N 212-010-404-5
TB 205-(04-2)-73-2	Basic	11-May-73	Stabilizer Bar Damper Overhaul and/or Exchange, P/N 204-010-937-7
TB 205-05-73-1	Basic	1-Aug-73	Improved 205A-1 Tail Rotor
TB 205-06-73-1	Basic	12-Jun-73	Inspection of Hydraulic Cylinder Assemblies, P/N 205-076-036-3, -5, -7, -9, -11, and -13
TB 205-10-73-1	Basic	29-Jan-73	Installation of Fuel Filter Screen in Fitting, P/N S2490
TB 205-11-73-1	Basic	13-Sep-73	Availability of Bearing Staking Tool Kit, P/N T101886-1, for Improved Universal Assembly, P/N 205-076-381-1
TB 205-13-73-1	Basic	2-Jan-73	Issuance of Technical Bulletins will Replace Service Letter Publications Effective Jan. 1973
TB 205-13-73-2	Basic	13-Mar-73	Component Exchange
TB 205-13-73-3			NEVER ISSUED
TB 205-13-73-4	Basic	27-Mar-73	Inspection of Airframe Dynamic Components
TB 205-13-73-5	Basic	5-Oct-73	Announcement of Increase on Time-Between-Overhaul of Dynamic Helicopter Components
TB 205-13-73-6	Basic	18-Sep-73	Fluorescent Penetrant Inspection
TB 205-50-73-1	Basic	8-Jan-73	Rotor Brake Assemblies (Goodyear)
TB 205-50-73-2	Basic	30-Apr-73	Installation of Improved Tail Rotor Kit, P/N 205-704-040-1 On Model 205A-1 Helicopters Prior to S/N 30020
TB 205-01-74-1	Basic	5-Jun-74	Installation Instruction for Support Assemblies, P/N 205-030-341-1 and -2 and 205-030-342-1 and -2
TB 205-04-74-1	Basic	10-May-74	Instructions for Installing 212 Type Support Cases on 205 Type Transmission
TB 205-04-74-2	Basic	16-Oct-74	Modification of Transmission Oil System
TB 205-(04-1)-74-1	Basic	27-Aug-74	M/R Yoke Assembly, P/N 204-011-102-17, Spindle Replacement Dimension Change
TB 205-05-74-1	Basic	10-Oct-74	Inspection of Inner Grip Plate Area, T/R Blade P/N 212-010-750 (All Dash Numbers)
TB 205-05-74-2	Basic	27-Nov-74	Dynamic Balance of T/R Hub and Blade Assembly, P/N 204-011-800 (All Dash Numbers)

205A1 TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205-11-74-1			NEVER ISSUED
TB 205-11-74-2	Basic	25-Jun-74	Lubrication of Anti-Torque Silent Chain Assembly, P/N 205-001-721-1
TB 205-12-74-1	Basic	11-Mar-74	Addition of Condensation Drain to Heater Sensor Line
TB 205-13-74-1	Rev A	19-Sep-74	Component Exchange
TB 205-75-1	Basic	24-Feb-75	Installation of Larger Diameter Grommet in the Anti-Torque Control System
TB 205-75-2	Basic	28-Feb-75	Heater Control Temperature Sensor
TB 205-75-3	Basic	13-Mar-75	Ground Handling Gear Hydraulic Pump Repair Kit, P/N KH9000
TB 205-75-4	Basic	7-Oct-75	Bearings, Oil Cooler Blower, P/N 204-062-540-1
TB 205-75-5	Basic	7-Oct-75	Lubrication of Starter Shaft Spline
TB 205-76-1	Basic	21-Jan-76	Transmission Case Exchange Program
TB 205-76-2	Basic	21-Jan-76	Modification of Transmission, P/N 205-040-001-23,-33,-45, and -49
TB 205-76-3	Basic	13-Feb-76	Repair of Electric Sump Drain Valve, P/N AF11C-9
TB 205-76-4	Basic	5-Mar-76	Component Exchange
TB 205-76-5	Rev A	29-Nov-76	Modification - Main Driveshaft Assembly, P/N 205-040-004-3
TB 205-76-6	Basic	7-Apr-76	Warranty Claim Procedure and Return of Parts
TB 205-76-7	Rev A	12-Nov-76	Transmission Oil Pump, P/N 212-040-184-1 (Vendor P/N GC 2778)
TB 205-76-8	Basic	15-Apr-76	Inspection and Rework of "J" Stringers Aft of Tailboom Baggage Compartment
TB 205-76-9	Rev A	9-Jun-76	Flight Control Hydraulic Actuators
TB 205-76-10	Rev A	13-Feb-78	Inspection and Repair of Main Beam Cap Extrusions, P/N 205-030-163-569 and 205-030-164-227
TB 205-76-11	Basic	6-Jul-76	Main input Driveshaft Assembly, P/N 205-040-004
TB 205-76-12	Basic	13-Aug-76	Flight Control Tubes and Bellcranks
TB 205-76-13	Basic	30-Sep-76	Skid Landing Gear Spares Replacement Part Number Change
TB 205-76-14	Basic	21-Oct-76	Modification of the Copilots Attitude Indicator Bracket
TB 205-77-1	Rev A	21-Jun-77	Main Rotor Splice Cover Assembly, P/N 204-015-011-1
TB 205-77-2	Basic	31-Oct-77	Installation of Reinforcement Kit, P/N 205-704-066-1
TB 205-77-3	Basic	13-Sep-77	One Time Inspection of Forward Cross Tube Assemblies, P/N 205-050-400-5, -13, -37, -39, -701, -703, Which Have Attained 1000 Hours Service Life
TB 205-77-4	Basic	6-Oct-77	Announcement of Increase in Time-Between-Overhauls of 205-040-001-33, -37, -45, and -49 Transmission Assemblies
TB 205-77-5	Basic	11-Oct-77	Transmission, 42 and 90 Gearbox Assembly Electrical Chip Detectors, P/N B752G, B3703, and B7669B
TB 205-77-6	Basic	11-Oct-77	Repositioning of Clamp Securing Cable Assembly, P/N 205-075-047-3 and -5, to Hydraulic Bypass Valve Sys 2

205A1 TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205-77-7	Basic	18-Oct-77	Rework Instructions for Cargo Hook Bumper Casting, P/N 204-072-901-1
TB 205-77-8	Basic	24-Oct-77	Insp. of Hyd Servo Actuator, P/N 204-076-029 (All Dash Numbers), Vendor P/N 41105930 (All Dash Numbers), and P/N 205-076-036 (All Dash Numbers), Vendor P/N 41105950 (All Dash Numbers), in Accordance with Hyd Research Textron Service Bulletin FMTC 238
TB 205-77-9	Basic	24-Oct-77	Installation of Bushing Containment Washers on the Hydraulic Actuator Spanner Link Input Lever in Accordance With Hyd Research Textron Service Bulletin FMTC 236
TB 205-77-10	Basic	24-Oct-77	Installation of Bushing Containment Washers on the Hyd Act Spanner Link Input Lever and Repl. of Shoulder Bolts in Accordance with HRT Service Bulletin FMTC 237
TB 205-78-1	Basic	24-Feb-78	Relocation of the Forward Friction Dampers, Fixed Floats Landing Gear
TB 205-78-2	Basic	28-Feb-78	Inspection and Maintenance of Emergency Exits
TB 205-78-3	Basic	3-Mar-78	Installation of Main Rotor Blade Inspection System Kit, P/N 212-704-116-1, on Main Rotor Blade, P/N 204-011-250-1 and -5
TB 205-78-4	Basic	8-Mar-78	Landing Gear, One Time Inspection of Aft Cross Tube Assemblies, P/N 205-050-400-7, -29, -35, and -705
TB 205-78-5	Basic	16-Mar-78	Hydraulic Line, P/N 70034M310W144, One Time Inspection
TB 205-78-6	Rev B	21-Aug-78	Flight Control Hydraulic Actuators, P/N 205-076-031-1, 212-076-005-7, -9, -11 and 205-076-029-5
TB 205-78-7	Basic	21-Mar-78	Main Rotor Blades, P/N 204-011-250-1 and -9, Removal and Repair of Blade Inspections System (BIS) Skin Ground
TB 205-78-8	Basic	19-Apr-78	Replacement of Cargo Door Sliders, P/N 204-030-220-1
TB 205-78-9	Basic	25-Apr-78	Main Rotor Blades, P/N 204-011-250 (All Dash Numbers) Announcement of Inspection Requirement Changes and Deletion of Blade Inspection System
TB 205-78-10	Basic	3-May-78	Announcement of Increase in Time-Between-Overhaul of Main Rotor Hub Assembly
TB 205-78-11	Basic	17-May-78	Main Rotor Hub Assembly P/N 204-012-101, Pillow Block Assembly Procedure
TB 205-78-12	Basic	22-Jun-78	Forty-Two Degree Gearbox Assembly, P/N 204-040-003-37, Increase in Time-Between-Overhaul (TBO)
TB 205-78-13	Basic	25-Jul-78	Tail Rotor Driveshaft Hanger Assembly, P/N 212-040-600-1, Modification of the Greaseable Hanger Assembly, P/N 212-040-600-5
TB 205-78-14	Basic	25-Jul-78	Transmission Bevel Gear Attachment Bolts, P/N AN107607, Replacement of

205A1 TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205-78-15	Basic	25-Sep-78	Tail Rotor Driveshaft, P/N 204-040-620-3 and -7, Replacement with New T/R Driveshaft, P/N 204-040-620-11
TB 205-78-16	Rev A	9-Mar-79	Skid Landing Gear Aft CrossTube Assembly, P/N 205-050-400-63, Procedure for Installation of Model 205A-1 Helicopters
TB 205-78-17	Basic	23-Oct-78	M/D Shaft Assembly, P/N 205-040-004 Series, Retrofit with newly Developed Boot Assembly, P/N 205-040-176-101
TB 205-78-18	Basic	21-Nov-78	Repair of Baggage Compartment Top Honeycomb Panel, P/N 205-032-812
TB 205-79-19	Rev B	22-Jun-79	Rework of the Baggage Compartment Forward Bulkhead, P/N 205-032-804
TB 205-79-20	Basic	24-Jan-79	Cylinder and Support Assembly, Anti-Torque Control, P/N 212-001-720-7, 205-001-729-1, or -5, Rework of Clevis, P/N 209-001-719-1
TB 205-79-21	Basic	16-Mar-79	Hydraulic Cylinder Assembly, P/N 212-076-004-003, -005, 212-076-005-007, -009 and -011
TB 205-79-22	Basic	26-Mar-79	High Skid Gear Forward and Aft Cross Tube Assemblies, P/N 205-050-403-31 and -33, Inspection and Rework
TB 205-79-23	Basic	26-Mar-79	Landing Gear Forward and Aft Cross Tube Assemblies, P/N 205-050-400-53, -55, and -63, Inspection and Rework
TB 205-79-24	Basic	26-Mar-79	Inspection and Repair of Fixed Floats Forward and Aft Cross Tube Assemblies, P/N 205-050-114-23 and -25
TB 205-79-25	Basic	26-Mar-79	Repair of Baggage Compartments Side Honeycomb Panels Right Side, P/N 205-032-811, and Left Side, P/N 205-032-813
TB 205-79-26	Basic	29-Mar-79	Replacement of Bearings Installed in Lift Link Assembly, P/N 209-030-357
TB 205-79-27	Basic	29-Mar-79	Structural Repair to Cabin Windshield Upper Longeron and Door Post, P/N 205-030-619
TB 205-79-28	Basic	29-Mar-79	Staking Tool for Bearing Installed in Lift Link, P/N 212-030-104
TB 205-79-29	Basic	23-Apr-79	Installation of Wear Sleeves on Flight Control Tube Assemblies in Anti-Torque Cable and Controls, P/N 205-001-045-001, 205-001-045-005, 205-001-005-001, 205-961-131-001 and Synchronized Elevator Controls Installations, P/N 205-001-023-003 and -005
TB 205-79-30	Basic	30-Apr-79	Repair of the Vertical Fin Forward Spar, P/N 205-032-851
TB 205-79-31	Basic	30-Jul-79	Tail Rotor Gearbox, P/N 212-040-004, Increase Torque of Attachment Nuts Removal of Aluminum Washers, P/N NAS1197 or AN960PD
TB 205-79-32	Basic	30-Jul-79	Main Rotor Mast Assemblies, 204-040-366-13, -15, -17, TBO Increase Mast Bearing, P/N 212-040-136-001, 1000 Hour Retirement Deletion

205A1 TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205-79-33	Basic	7-Aug-79	Ballast Plates on Front of Fixed Float Assemblies, Removal of
TB 205-79-34	Rev A	16-Feb-80	Main Beam, P/N 205-030-163 and P/N 205-030-164, Rivet Replacement
TB 205-80-35	Basic	18-Feb-80	Swashplate Support Assembly P/N 204-011-404-017, and Inner Ring Assembly, P/N 204-011-402-021, Installation of
TB 205-80-36	Basic	15-May-80	Gearbox Assembly, 42-degree Tail Rotor Drive, P/N 212-040-003, Gearbox Assembly, 90-degree Tail Rotor Drive, P/N 212-040-004, Time-Between Overhaul (TBO), Increase of
TB 205-80-37	Basic	2-Jun-80	Cyclic, Collective, and Tail Rotor Control Installations, Damage and Repair Limits of Bellcrank, Lever, and Support Assemblies Under the Cabin Floor Area
TB 205-80-38	Basic	3-Oct-80	Modification of Hydraulic Cylinder Assemblies, P/N 212-076-005-007, -009, and -011
TB 205-81-39	Basic	20-Jan-81	Hydraulic Pumps, P/N 212-076-010-001 (ABEX P/N AP2V-82) and P/N 204-076-065-003 (ABEX P/N AP2V-77), Modification of
TB 205-81-40	Basic	26-Jan-81	Bellcrank Assemblies, P/N 212-001-712-001, Rework to Allow Replacement of Bearing, P/N DSRP-4
TB 205-81-41	Rev A	14-Mar-84	Rework of Engine Driveshaft Adapter, P/N 204-040-812-003
TB 205-81-42	Basic	7-May-81	Cargo Release Relay, Electrical Grounding of
TB 205-81-43	Rev A	17-Sep-81	Main Rotor Hub Assembly, P/N 204-012-101 (All Dash Numbers), Modification to Grease Lubrication
TB 205-82-44	Basic	3-Feb-82	Hydraulic Cylinder Assemblies, P/N 212-076-005-001, -005, -007, -009, -011, Rework of Mounting Bracket, P/N 212-076-116-001, -003, and Bearing Nut, P/N 212-076-118-001
TB 205-82-45	Basic	5-May-82	Kaflex Driveshaft, P/N 204-040-433-101, Installation and Inspection of
TB 205-82-46	Basic	19-Jul-82	Suspension Assembly - Cargo, P/N 204-072-915-101 and Prior, Modification of
TB 205-82-47	Rev A	17-Mar-09	Replacement of Upper Honeycomb Panel, Tailboom Baggage Compartment, with Sheetmetal Skin
TB 205-82-48	Basic	29-Sep-82	Directional Hydraulic Servo Actuator, P/N 205-076-031-1, -3, and 212-076-004-003, -005, Change of Overhaul Interval
TB 205-83-49	Basic	15-Feb-83	Transmission, P/N 212-040-001-135, with Time-Between-Overhaul of 2500 Hours, Conversion to
TB 205-83-50	Basic	3-Jun-83	Inspection and Rework of the Vertical Fin Forward Spar and the Installation of a Doubler on the Upper Left Side Skin of Vertical Fin
TB 205-83-51	Basic	4-Aug-83	Hydraulic Pump, P/N 212-076-011-001 (ABEX P/N 66005, Model AP2V-81 and ABEX P/N 66003, Model AP2V-77), Seal Retainer Gasket, Installation of

205A1 TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205-83-52	Basic	30-Sep-83	Latch Installation, Crew Door, P/N 204-030-500-005/-006, Modification of
TB 205-83-53	Basic	12-Oct-83	Horizontal Stabilizer Ribs, P/N 205-030-856-095 and -097, Modification of
TB 205-83-54	Basic	21-Nov-83	Flight Control Cylinder P/N 212-076-005-7, -9, -011, -101, Input Lever Assembly, Replacement of
TB 205-83-55	Basic	1-Dec-83	3 Micron Transmission Oil Filter, P/N 204-040-760-105, Installation of
TB 205-84-56	Basic	8-Feb-84	Crew Door Hinge, P/N 204-031-837-011/-012 (Upper Fixed), 204-031-658-1/-2 (Upper Movable) 204-031-467-011/-012 (Lower Fixed), and 204-031-468-1/-2 (Lower Movable), Bushing of
TB 205-84-57	Rev A	13-Sep-85	Mast Assembly, P/N 204-040-366-021, Increase in Time-Between-Overhaul (TBO)
TB 205-84-58	Basic	16-Feb-84	Transmission Assembly, P/N 212-040-001-135, Increase in Time-Between-Overhaul (TBO)
TB 205-84-59	Basic	16-Feb-84	Gearbox Assembly, 42 Degree, P/N 212-040-003-023, Increase in Time-Between-Overhaul (TBO)
TB 205-84-60	Basic	16-Feb-84	Gearbox Assembly, 90 Degree, P/N 212-040-004-009, Increase in Time-Between-Overhaul (TBO)
TB 205-84-61	Basic	29-Feb-84	Flight Control Cylinder, P/N 212-076-005-7, -9, -11, -101, Piston Head Seals, Replacement of
TB 205-84-62	Basic	28-Nov-84	Cargo Release Relay, Rewiring of
TB 205-85-63	Basic	28-Jan-85	Flight Control Cylinder, P/N 212-076-005-7 and -9, Installation of Bushing Containment Washers in Accordance with HR Textron Service Bulletin FMTC 236
TB 205-85-64	Basic	1-Feb-85	Gearbox Assembly, Intermediate and Tail Rotor, Modification of
TB 205-85-65	Basic	1-Nov-85	Tail Rotor Blade, P/N 212-010-750 (All Dash Numbers), Improved Visibility Paint Scheme
TB 205-85-66	Basic	22-Nov-85	Universal Assembly, P/N 412-076-620-101, Replacement of Bearings
TB 205-86-67	Basic	12-Feb-86	Fin Spar Cap, P/N 212-030-447-101, Installation of
TB 205-86-68	Basic	26-Mar-86	Retainer Secured (Push Out) Passenger Compartment Windows
TB 205-86-69	Basic	28-Apr-86	Main Rotor Grip Seal, P/N S12561-341, Replacement of
TB 205-86-70	Basic	28-Jul-86	Hydraulic Pumps, P/N 212-076-011-001 (ABEX P/N 66005, Model AP2V-81 and ABEX P/N 66003, Model AP2V-77), Replacement of External Driveshaft
TB 205-87-71	Basic	19-Jun-87	Tail Rotor Driveshaft, P/N 204-040-620-011, Modification of
TB 205-87-72	Basic	17-Aug-87	Markings Installation, P/N 205-070-868 (All Dash Numbers), Tail Rotor Hazard Warning Decals, Addition to

205A1 TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205-87-73	Basic	28-Sep-87	Rotor Brake Assembly, Modification of
TB 205-88-74	Basic	8-Feb-88	Addition of Identification on Aircraft Exterior
TB 205-88-75	Basic	13-Apr-88	Tail Rotor Counterweight Bellcrank Assembly, Inspection of
TB 205-88-76	Basic	23-Nov-88	Plumb Bob Support Installation, P/N 205-030-147-009, Inspection of
TB 205-89-77	Basic	13-Mar-89	Tail Rotor Gearbox Assembly P/N 212-040-004-005, Conversion to the 212-040-004-009 Configuration
TB 205-89-78	Basic	13-Mar-89	Intermediate Gearbox Assembly P/N 212-040-003-007, Conversion to the 212-040-003-023 Configuration
TB 205-89-79	Rev A	19-Jun-90	Airborne Canister Type FuelBoost Pump Assembly P/N 206-062-687-101, Installation of
TB 205-89-80	Basic	18-Oct-89	Tail Rotor Yoke P/N 212-010-704-(All) and 212-010-744-(All), Announcement of an Increase in Retirement Life
TB 205-89-81	Basic	17-Oct-89	Introduction of New Step Actuator P/N 212-075-418-103
TB 205-89-82	Basic	27-Nov-89	Mast Assembly P/N 204-040-366-013, -015, -017, -021, Configuration Change and Upgrade
TB 205-90-83	Rev A	3-Aug-90	MRC Duplex Bearings P/N 204-040-424-001, Inspection and Recall
TB 205-90-84	Basic	31-Oct-90	Main Rotor Hub Assembly P/N 204-012-101, Configuration Change and Upgrade
TB 205-91-85	Basic	5-Feb-91	Stabilizer Bar Assembly P/N 204-011-326 and P/N 212-010-300, Configuration Change and Upgrade
TB 205-91-86	Basic	13-Feb-91	Swashplate and Support Assembly P/N 204-011-400, Configuration Change and Upgrade
TB 205-91-87	Rev A	10-Mar-92	Main Transmission Full Flow Debris Monitor
TB 205-91-88	Rev A	6-Oct-92	Introduction of Lift Link Fitting P/N 212-030-154-101 and Bolt P/N 412-030-224-101, Which Supersedes Lift Link Fitting P/N 212-030-154-001, And Bolt P/N 212-030-135-001
TB 205-91-89	Rev A	19-Mar-92	Tail Rotor Pitch Change Tube Assembly P/N 209-001-710-All, Electro Chemical Metallizing
TB 205-91-90	Basic	26-Jun-91	Transmission Oil Pump Key P/N 38-56007-1003-2 and MS35756-3 Which Were Supplied as Spares, Replacement of
TB 205-91-91	Basic	7-Oct-91	Main Transmission Assembly P/N 212-040-001-135/ -153 and -177 Configuration Change and Upgrade
TB 205-92-92	Basic	13-Feb-92	Installation of Improved Rotor Brake quill P/N 412-040-123-101 (Canceled by ASB 205-93-53)
TB 205-92-93	Basic	3-Feb-92	Transmission Assembly, P/N 212-040-001-135/ -137/-153/ -165/-177/ -179, Increase in Time-Between-Overhaul (TBO)
TB 205-92-94	Basic	3-Mar-92	Sump Case Assembly P/N 204-040-355-005 and -017, Rework Procedure to Reduce the Size of The Chip Detector Boss Entry-Countersink

205A1 TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205-93-95	Basic	24-Jun-93	Rotor Brake Quill P/N 412-040-123-101, One Time (External) Inspection
TB 205-94-96	Basic	7-May-94	Case Assembly, Bevel Gear P/N 212-040-053-009
TB 205-94-97	Basic	10-Sep-94	Electronic Power Turbine Overspeed Control System: Removal of
TB 205-94-98	Basic	28-Nov-94	Rotor Brake Assembly, Introduction of Stainless Steel Piston
TB 205-95-99	Basic	5-Apr-95	Lucas Western Service Bulletins: High Performance Rescue Hoist Assembly Washer Interference
TB 205-95-100	Basic	17-Jul-95	Tail Rotor Hub Assembly P/N 212-011-701-003, Conversion to -125 Configuration
TB 205-95-101	Basic	18-Sep-95	Pillow Block Bushing 204-011-135-105, Increase in Retirement Life
TB 205-96-102	Basic	16-Dec-96	Seal P/N 212-340-113-202 and Wear Sleeve P/N 212-040-867-101: Introduction of
TB 205-98-103	Basic	9-Sep-98	Breeze-Eastern A60LT Cargo Hooks
TB 205-99-104	Basic	10-Feb-99	Improved Pitch Horn Attachment Hardware
TB 205-99-105	Basic	22-Feb-99	New Door Rollers and Sliders
TB 205-99-106	Basic	19-Mar-99	Tail Rotor Gearbox Output Shaft Speedi-Sleeve, Addition of
TB 205-99-107	Basic	7-May-99	Bellcrank Assembly Rework
TB 205-99-108	Basic	7-May-99	New Sliding Door Latch Guard
TB 205-99-109	Basic	26-Nov-99	Hinged Panel Assembly, Improvement of
TB 205-00-110	Basic	30-Jun-00	Cyclic and Collective Jackshafts, Inspection and Modification of
TB 205-00-111	Basic	19-May-00	Fin Spar Cap 212-030-447-001/-101, Replacement of
TB 205-00-112	Basic	4-Aug-00	Forward Crosstube, Modification of
TB 205-01-113	Basic	31-Jan-01	Improved Tail Rotor Pitch Links
TB 205-03-114	Basic	20-Oct-03	Swashplate and Support Assembly, Bolt 204-011-463-107, Introduction of
TB 205-04-115	Basic	28-Jun-04	Transmission Oil Pump 212-040-184-001, Modification of
TB 205-04-116	Basic	7-Jun-04	Chip Detector Indicator, Replacement for Spares
TB 205-04-117	Basic	19-Oct-04	Main Rotor Flight Control System Bolts, Inspection of
TB 205-05-118	Basic	11-May-05	Bearing and Liner Assemblies P/N 204-010-433-001 and P/N 204-011-443-001: Installation Improvements
TB 205-05-119	Rev A	14-Dec-07	Tailboom Bulkhead Reinforcement
TB 205-06-120	Rev A	22-Jun-07	Improved Baggage Compartment Door Seal
TB 205-06-121	Basic	21-Jul-06	Vertical Fin Cover Hinge Pin Improved Installation
TB 205-08-122	Basic	16-Jan-08	Tailboom Assemblies P/N 205-032-802-003 Through -051 and 212-030-100-081 Through -107, Modification for Use on All Model 205A/A-1 Helicopters
TB 205-08-123	Basic	26-Feb-08	Upper Crew Door Hinge Structure, Reinforcement of
TB 205-08-124	Basic	13-May-08	Fuel Overflow Deflector Upgrade
TB 205-09-125	Basic	28-Apr-09	Tail Rotor Gearbox Excluder Housing Leak: Prevention of

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
--------------------	-----------------------	-------------	----------------