

ALERT SERVICE BULLETIN



A Textron Company

NO. 206-08-117

DATE Jun 17, 2008

PAGE 1 of 1

DATE
REV

MODEL AFFECTED: 206A/B

SUBJECT: ENGINE, FUEL AND CONTROL – POWER TURBINE GOVENOR INCREASED RELIABILITY

HELICOPTERS AFFECTED: 206A Helicopters serial number 004 through 660 and 672 through 715.

206A Helicopters converted to 206B as per Service Instruction 206-80.

206B Helicopters serial number 661 through 671 and 716 through 4655.

206B (TH-67) Helicopters serial number 5101 through 5313.

[206B helicopters serial number 4656 through subsequent and 206B (TH-67) helicopters serial number 5314 through subsequent will have the intent of this bulletin accomplished prior to delivery]

COMPLIANCE: See Rolls Royce bulletin CEB 318(250-C18 series) or CEB 1402(250-C20 series)

DESCRIPTION:

The purpose of this bulletin is to achieve complete distribution of Rolls Royce bulletin CEB 318 and/or CEB 1402 to the current affected model distribution list on record by Bell Helicopter. The vendor bulletins are available via Aviall (1-800-aviall1 or www.aviall.com or fax 1-972-406-2225).

APPROVAL:

See vendor bulletin approval