

**BHT-206A/B/B3-ASB-INDEX**

**Bell** *MODEL* **206A/B** *SERIES*

**ALERT  
SERVICE  
BULLETIN  
INDEX**

**COPYRIGHT NOTICE**

COPYRIGHT 2011  
BELL © HELICOPTER TEXTRON INC.  
AND BELL HELICOPTER TEXTRON  
CANADA LTD.  
ALL RIGHTS RESERVED

**Bell** *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

**15 SEPTEMBER 2011**



## 206A/B/B3 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 206A-1	Basic	10-Oct-67	Engine Droop Compensator Safety Wire Provisions
ASB 206A-2	Basic	16-Oct-67	Cyclic Control System Inspection and Addition of Shield
ASB 206A-3	Basic	25-Oct-67	Exhaust Stack Clamp, Inspection and Safety Wiring
ASB 206A-4	Rev A	20-Jan-68	Engine Mount, Inspection and Addition of Support Bracket
ASB 206A-5	Basic	9-Nov-67	Tail Rotor Control, Addition of Friction Clamp, Spring and Support
ASB 206A-6	Basic	10-Nov-67	Cyclic and Collective Control Tubes, Inspection of
ASB 206A-7	Basic	22-Aug-68	Magnesium Tail Boom, Inspection of
ASB 206A-8	Basic	21-Oct-68	Transmission Spider, Inspection and Retirement of
ASB 206A-9	Basic	30-Dec-68	Fan Shaft Assembly, Inspection
ASB 206A-10	Basic	11-Apr-69	Transmission Spindle, Inspection of
ASB 206A-11	Rev B	29-Sep-69	Cyclic Control Bellcrank Support, Replacement of
ASB 206A-12	Rev A	8-Apr-70	Hydraulic Cylinder, P/N 41103750, 41103750-2, and 41103650-005, Retirement Life
ASB 206A-13	Basic	4-Aug-69	Dual Control, Lever Assy., Inspection of
ASB 206A-14	Rev C	8-Apr-70	Transmission Spider, Retirement of
ASB 206A-15	Basic	19-Dec-69	Tail Rotor Gear Box and Tail Boom, Inspection of
ASB 206A-16	Basic	3-Mar-70	Snow Winterization Kit, Modification
ASB 206A-17	Basic	10-Sep-70	Installation and Inspection of Improved Magnetic Plug, Updating Transmission
ASB 206A-18	Basic	19-Nov-70	Aluminum Fuel Lines, Replacement of
ASB 206A-19	Rev C	11-Dec-73	Main Rotor Blade Inspection
ASB 206-20	Rev A	21-Feb-72	Strap, P/N 206-031-200-23 and -24, Inspection of
ASB 206-21	Rev A	14-Aug-73	Pop-Out Float System Valve Assy., Functional Check Procedure of
ASB 206-22	Basic	25-Oct-72	Idler Assy., P/N 206-001-746-5, Inspection and Rework
ASB 206-23	Basic	13-Nov-72	Main Rotor Mast Inspection
ASB 206-24	Basic	21-Nov-72	Nuts, P/N NAS1022A14, Inspection of
ASB 206-25			NEVER ISSUED
ASB 206-26	Basic	18-Dec-72	Vertical Fin, Inspection of
ASB 206-01-73-1	Basic	9-Jan-73	Vertical Fin, Inspection of
ASB 206-01-73-2	Rev A	27-Mar-73	Pylon Support Link, Inspection of
ASB 206-01-73-3	Rev B	23-Oct-73	Removal of Metal Plug Buttons
ASB 206-01-73-4	Rev B	16-Oct-73	Tailboom Skin Splice Rivets, Inspection of
ASB 206-01-73-5	Rev A	21-Sep-73	Vertical Fin Support, Inspection and Replacement of
ASB 206-01-73-6	Basic	19-Sep-73	Pylon Support Links, P/N 206-031-508-5 and -7, Retirement of
ASB 206-01-73-7	Rev E	18-Sep-74	Horizontal Stabilizers, Inspection and Rework of
ASB 206-03-73-1	Rev C	25-Feb-75	Starter Generator Retaining Clamp "T" Bolt, Inspection and Replacement of
ASB 206-04-73-1	Basic	8-Aug-73	Tail Rotor Gear Inspection
ASB 206-04-73-2	Rev A	21-Oct-75	Restricted Use of Grease, P/N 204-040-755-3

## 206A/B/B3 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 206-(04-1)-73-1	Basic	25-Jun-73	Main Rotor Hub Strap Fittings and Pins, Retirement of
ASB 206-04-2-73-1	Basic	7-May-73	Main Rotor Pitch Link Tubes, Inspection of
ASB 206-(04-2)-73-2	Basic	15-May-73	Swashplate Bearing, Inspection of
ASB 206-06-73-1	Rev A	26-Jun-73	Hydraulic Servo Actuator Piston Assy., P/N 41000005, Inspection and Rework of
ASB 206-06-73-2	Basic	11-May-73	Hydraulic Servo Actuator Servo Valve Drive Locknut, Inspection of
ASB 206-12-73-1	Rev A	19-Jul-73	Heater Fuel Line Inspection
ASB 206-50-73-1	Basic	16-Jan-73	Heater Fuel Line Inspection
ASB 206-50-73-2	Rev A	6-Aug-73	Rotor Brake Disc Assy, Inspection of
ASB 206-01-74-1	Rev B	4-Jun-74	Horizontal Stabilizer Stop, Kit Installation of
ASB 206-01-74-2	Basic	12-Nov-74	Cabin Roof Straps, Mandatory Replacement of by 30 September 1975
ASB 206-01-74-3	Basic	16-Oct-74	Transmission Mount Spindle, Inspection of
ASB 206-04-74-1	Rev B	8-Oct-74	Tail Rotor Driveshaft Bearing Hanger Screws, P/N 206-040-323-1, Mandatory Replacement of
ASB 206-04-1-74-1	Rev A	22-Aug-74	Main Rotor Hub Yoke, Inspection and Rework Mandatory by 31 December 1974
ASB 206-04-1-74-2	Basic	21-Nov-74	Main Rotor Grip Inspection
ASB 206-04-2-74-1	Basic	20-Jun-74	Cyclic and Collective Control System Attaching Bolts Mandatory Replacement by 30 July 1974
ASB 206-06-74-1	Rev A	8-Oct-74	Hydraulic Servo Actuators, Inspection of
ASB 206-06-74-2			NEVER ISSUED
ASB 206-06-74-3	Basic	10-Dec-74	Hydraulic Pump and Reservoir Repair to Stop Fretting, Mandatory by 15 January 1975
ASB 206-08-74-1	Basic	25-Mar-74	Oil Pressure Tube Assy., Mandatory Replacement by 1 July 1974
ASB 206-10-74-1	Basic	29-Jan-74	Fuel Cell Cavity and Vent Line Modification
ASB 206-10-74-2	Rev A	8-May-74	Fuel Cavity Vent Line, Modification
ASB 206-50-74-1	Rev A	29-Oct-74	Rotor Brake Shock Mounted Disc Assy., Mandatory Removal by 30 September 1974
ASB 206-75-1	Basic	4-Mar-75	Tail Rotor Drive Installation, Inspection of
ASB 206-75-2	Rev A	16-Apr-75	Tail Rotor Control Tube, Inspection Mandatory by 20 March 1975
ASB 206-75-3	Basic	1-May-75	Main Rotor Hub Pillow Blocks Epoxy Resin Coated Flanged Bushings, Installation of
ASB 206-75-4	Basic	15-May-75	Tail Rotor Yoke Retirement
ASB 206-75-5	Basic	22-May-75	Rework of External Hoist, Mandatory by 1 September 1975
ASB 206-75-6	Rev B	12-Jan-76	Fuel Pump Circuit Capacitor, Removal of
ASB 206-75-7	Basic	5-Sep-75	Passenger Door Hinge Rivets, Inspection of
ASB 206-75-8	Basic	16-Oct-75	Fuel Purge Line 10 Micron Filters, Installation of

## 206A/B/B3 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 206-75-9	Basic	25-Oct-75	Hydraulic Pressure Regulator Valve, Modification of
ASB 206-75-10	Basic	13-Nov-75	Main Rotor Blades, P/N 206-010-200-29, Mandatory Retirement of
ASB 206-76-1	Basic	26-Jan-76	Inspection of Hydraulic Servo Actuator Support Assembly, P/N 206-001-520-5, for Cracks in Forward Web
ASB 206-76-2	Basic	6-Feb-76	Installation of Model 206L Main Rotor Split Cone Set, P/N 206-010-003-7, on Model 206B Helicopters
ASB 206-76-3	Basic	20-Apr-76	Inspection of Fuel System
ASB 206-76-4	Rev B	8-Jul-76	Inspection of Main Rotor Hub Tension/Torsion Strap Assembly, P/N 206-010-105-3
ASB 206-76-5	Basic	12-May-76	Inspection of Hydraulic Servo Actuators, P/N 206-076-031-7 or -13 (H. R. No. 41000670-1, -003, or -005)
ASB 206-76-6	Basic	16-Jun-76	Linear Actuator, P/N 206-062-721-1 or -11 (Vendor P/N 7185-1)
ASB 206-76-7	Rev A	6-Jan-77	Reduction of Service Life, Tension/Torsion Straps, P/N 206-010-105-3. Replacement of Strap Fittings, P/N 206-010-155-11 and -15
ASB 206-76-8	Rev A	20-Aug-76	Installation of Taper Washers Under Hydraulic Servo Actuator Support Assembly
ASB 206-76-9	Rev A	23-Jul-76	Installation of Bearings, P/N 206-040-339-9
ASB 206-76-10	Rev B	7-Oct-76	Replacement of Litter Door Post Striker Housing Assembly
ASB 206-76-11	Basic	7-Sep-76	Replacement of Collars, P/N 206-040-319-3 and -5
ASB 206-76-12	Rev A	2-Dec-76	Installation of Bearings, P/N 206-040-339-9
ASB 206-77-1	Basic	15-Mar-77	Main Rotor Hubs P/N 206-010-100 and 206-011-100 (All Dash Numbers)
ASB 206-77-2	Basic	22-Mar-77	Rotor Brake Kits - Replacement of Lining Retention Screws
ASB 206-77-3	Basic	1-Apr-77	Inspection of Tube Assembly, P/N 206-061-541-1 or 206-061-522-1, for Evidence of Chafing
ASB 206-77-4	Basic	6-Apr-77	Reduction in Calendar Life, Tension/Torsion Straps, P/N 206-010-105-3 and -5
ASB 206-77-5	Rev A	16-May-77	Inspection of Oil Cooler Blower Impeller, P/N 206-061-432-5
ASB 206B-77-6	Basic	20-Jun-77	N2 Operating Speed Restriction
ASB 206-77-7	Basic	10-Oct-77	Retirement Time and Calendar Life, Tension/Torsion Straps, P/N 206-010-105-3 and -5, and 206-011-147-1
ASB 206-77-8	Basic	20-Oct-77	Inspection of Oil Cooler Blower Impeller, P/N 206-061-432-11
ASB 206-77-9	Basic	21-Oct-77	Replacement of Tail Rotor Drive Shaft Clamp Type Bearing Hangars With Shims
ASB 206-77-10	Rev A	21-Feb-78	Replacement of Oil Cooler Blower Impeller, P/N 206-061-432-11, With Impeller, P/N 206-061-432-31
ASB 206-78-1	Basic	14-Apr-78	M/R Hub Tension Torsion Straps, P/N 206-010-105-3, -5, Retirement of
ASB 206-78-2	Basic	18-Dec-78	Freewheeling Outer Race Shaft, P/N 206-040-221-3, Inspection

## 206A/B/B3 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 206-79-3	Basic	23-May-79	VOR Antenna P/N CI-159 and CI-159A
ASB 206-79-4	Basic	17-Jul-79	Main Rotor Yoke, P/N 206-010-101 (All Dash Numbers), Inspection and Retirement Life of
ASB 206-79-5	Basic	24-Oct-79	206 Main Input Driveshaft Assembly, P/N 206-040-100-13, Inspection Interval of
ASB 206-80-6	Basic	22-Feb-80	Tail Rotor Blade, P/N 206-010-750-005 and -007, Inspection of
ASB 206-80-7	Rev B	15-Oct-80	Main Rotor Trunnion, P/N 206-010-104-3 and 206-011-113-001, Magnetic Particle Inspection Requirements and Replacement of
ASB 206-80-8	Basic	11-Apr-80	Anti-Torque Control System Procedures
ASB 206-80-9	Basic	3-Jun-80	Addition of Calendar Life Retirement on TT Straps, P/N 206-011-147-001 and 206-011-147-005
ASB 206-80-10	Basic	4-Jun-80	Engine Lower Center Support Legs Acoustic Mounts, Modification of
ASB 206-80-11	Basic	27-Jun-80	External Hoist Kit, P/N 206-706-126-001, Mod and Inspection of (Inspect and Modify as Described in the Attached Breeze Corp. Bulletin No. BEB-162-8)
ASB 206-80-12	Basic	9-Sep-80	Aluminum Tail Rotor Blade, P/N 206-010-750-005 and -007, Retirement and Replacement of
ASB 206-81-13	Basic	24-Apr-81	Stability and Control Augmentation System (SCAS) Anti-Torque Cylinder Assembly, Inspection and Rigging of
ASB 206-81-14	Basic	22-Jun-81	Engine, Allison 250-C20/C20B, N1 and N2 Operating Speed Restrictions
ASB 206-81-15	Rev A	28-Sep-81	External Hoist and Hoist Provision Kits, P/N 206-706-124-001/003, 206-706-126-001/003, Addition of Ground to Hoist Assembly and Route Shield Through Electrical Connector on
ASB 206-82-16	Basic	19-May-82	Tail Rotor Blade, P/N 206-016-201-001 and 206-016-201-103, Check and Repair of
ASB 206-82-17	Basic	28-May-82	Skid Mounted, Light-Weight Emergency Flotation System Kit, P/N 206-706-211-101 and -103, Float Restraint Tubes, P/N 206-050-269-101, Addition of
ASB 206-82-18	Basic	19-Jul-82	Fuel Shutoff Valve, Provision for Thermal Relief
ASB 206-82-19	Basic	15-Nov-82	Tail Rotor Gearbox P/N 206-040-400 (All Dash Numbers), Inspection of
ASB 206-83-20	Basic	29-Aug-83	External Hoist Kits, P/N 206-706-126-1/-5/-101/-103, Hoist P/N BL-16600 (All Dash Numbers), Conversion and Inspection of
ASB 206-83-21	Rev A	29-Feb-84	Mast Assembly, Main Rotor, P/N 206-010-332, Inspection and Processing of
ASB 206-84-22	Basic	4-Jan-84	Fuel Supply Tube Assembly, P/N 206-061-452-101, Replacement of

## 206A/B/B3 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/REV	DATE	SUBJECT
ASB 206-84-23	Basic	24-Jan-84	Emergency Flotation Kit Reservoir and Piping Installation, P/N 206-073-801-001, Clamps, P/N MS 21920-53, Replacement
ASB 206-84-24	Basic	30-Aug-84	Reservoir, Emergency Flotation, P/N 274645, 206-073-919-001, 206-073-919-003, 206-073-919-005, 206-073-919-007, Installation of Decal (WARNING), P/N 31-023-8B, Decal (CAUTION), P/N 31-023-9B, On
ASB 206-84-25	Basic	30-Aug-84	Reservoir, Emergency Flotation, P/N 1269556-4, Installation of Decal (WARNING), P/N 31-023-8B, and Decal (CAUTION), P/N 31-023-9B, On
ASB 206-84-26	Basic	30-Aug-84	Reservoir, Emergency Flotation, P/N 206-073-922-1, -101, 206-073-919-1, -3, -5, -7, Installation of Decal (WARNING), P/N 31-023-8B, and Decal (CAUTION), P/N 31-023-9B, On
ASB 206-85-27	Rev A	15-Mar-85	Quick Disconnect Dual Controls P/N 206-706-127-1, -101, -109, Installation of Spring Pin Assembly
ASB 206-85-28	Rev B	21-Jun-85	Tail Rotor Blade, P/N 206-016-201-001/-103/-107, Check and Rivet Replacement
ASB 206-85-29	Basic	21-Jun-85	Cyclic Control Stick Assembly, P/N 206-001-334-1/-101, and 206-001-381-7, Inspection of
ASB 206-85-30	Rev B	13-Oct-86	External Hoist Kits, P/N 206-706-126-1/-5/-101/-103, Conversion of Hoist P/N BL-16600-80 to P/N BL-16600-110
ASB 206-86-31	Basic	24-Mar-86	Tail Rotor Crosshead, P/N 206-011-857-001, Installation of
ASB 206-86-32	Basic	27-Mar-86	206-070-263-005 Altimeter, Malfunction of Setting Knob Mechanism
ASB 206-86-33	Basic	13-Aug-86	Oil Cooler Blower Impeller P/N 206-061-432-031, Inspection of
ASB 206-86-34	Rev A	23-Oct-86	Airframe Fuel Filter Assembly P/N 222366-621-003 and P/N 52-2889-016 or -016A, Modification of
ASB 206-87-35	Basic	19-Jan-87	Reservoir Assembly, P/N 206-073-848-103/-105/-109, Valve Assembly, P/N 206-073-915-005/-101, Cap, Replacement of
ASB 206-87-36	Rev A	17-Jun-87	Rescue Hoist Cable Cutter Circuit, Rewiring of, In Accordance with Breeze Manufacturing Preferred Method
ASB 206-87-37	Basic	23-Apr-87	Main Rotor Mast, P/N 206-010-332-121, Return for Metallurgical Evaluation
ASB 206-87-38	Basic	26-May-87	Wire Strike Protection System, Inspection and Rework of
ASB 206-87-39	Basic	17-Sep-87	Tail Rotor Pitch Link(s), P/N 206-010-793-101, Inspection of
ASB 206-87-40	Rev A	3-Nov-87	Engine Fuel Valve Electrical Connector, P/N 3456W14S-5S, One Time Inspection of
ASB 206-88-41	Basic	28-Jan-88	Tail Rotor Yoke, P/N 206-011-819-101, Return for Inspection and Rework
ASB 206-88-42	Rev A	26-Aug-88	External Hoist, P/N BL-16600-(All Dash Numbers), Inspection of Load Cable and Hook/Bumper Stowage

## 206A/B/B3 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 206-89-43	Rev A	1-Aug-89	Aeroquip 601 Hose Assemblies, One-Time Inspection and Replacement
ASB 206-89-44	Basic	21-Mar-89	Pc Air Filter Housing Assembly, Replacement of
ASB 206-89-45	Rev B	28-Jul-92	Bendix Power Turbine Governor Py Port, Inspection of
ASB 206-89-46	Rev A	29-Aug-89	Strap Assembly, Main Rotor, Tension-Torsion P/N 206-011-147-7 and P/N 206-011-154-101/-105, Removal from Service
ASB 206-89-47	Rev A	29-Aug-89	Tail Rotor Hub Assembly P/N 206-011-810-015 and Tail Rotor Yoke P/N 206-011-811-009, Removal from Service
ASB 206-89-48	Basic	21-Sep-89	Main Rotor Flight Control System Bolts, Inspection of
ASB 206-89-49	Basic	10-Oct-89	Emergency Float Bag Inflation Valve Restrictors-Installation of, (Service Instruction 206-115)
ASB 206-89-50	Rev A	29-Nov-89	Main Rotor Blade P/N 206-010-200-033, Removal from Service
ASB 206-89-51	Rev B	5-Feb-90	Breeze-Eastern Cargo Hooks P/N SP4232-5, -31 and 14027-2, Warning Plate, Addition of
ASB 206-90-52	Rev B	5-Mar-92	Tail Rotor Control Tube-Inspection For Possible Interference of
ASB 206-90-53	Basic	15-May-90	VOR Antenna P/N CI-259D Date Coded D/M 8930 to D/M 9015 Inclusive
ASB 206-90-54	Basic	31-May-90	Fuel Valve Switch Guard, Installation of
ASB 206-90-55	Rev A	16-Jul-90	Turbine Spline Adapter, Replacement of
ASB 206-90-56	Rev A	15-Jan-91	Sungear P/N 206-040-662-101, Recall of by Serial Number
ASB 206-90-57	Basic	27-Jun-90	Tail Rotor Blade P/N 206-016-201-113 and 206-016-201-127, Inspection of
ASB 206-90-58	Rev A	31-Oct-90	Tail Rotor Blade 206-016-201-125/-127, Removal From Service
ASB 206-91-59	Basic	30-Jan-91	Bearing Hanger, 206-040-346 One Time Inspection
ASB 206-91-60	Basic	28-Jun-91	PART I: Vertical Fin Supports P/N 206-031-417 and 206-031-418, Inspection and Modification of - PART II: Vertical Fin Assembly P/N 206-020-113-5, -7, -9, -107 Inspection for Gaps and Addition of Mounting Spacers, if Required
ASB 206-91-61	Basic	13-Sep-91	Driveshaft Seal Assembly 206-040-272-101, Replacement of
ASB 206-91-62	Basic	19-Sep-91	Restraint Assembly 222-320-823-109, -111, Improvement of
ASB 206-91-63	Rev A	31-Oct-91	Possible Incorrect Max Fuel Flow Setting on Certain Bendix Fuel Controls
ASB 206-91-64	Basic	21-Nov-91	Horizontal Stabilizer Spare Assembly P/N 206-020-120-011, Removal From Service
ASB 206-91-65	Basic	26-Nov-91	Engine Bleed Valve, Removal From Service
ASB 206-92-66	Basic	5-May-92	Main Rotor Pillow Block Retention Hardware, Replacement of Bolt MS21250-04018
ASB 206-92-67	Basic	7-May-92	Tail Rotor Gearbox Oil Level Indicators 204-040-508-001 and 204-040-508-011
ASB 206-92-68	Basic	5-Aug-92	Flap Restraint 206-011-117-003



## 206A/B/B3 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 206-92-69	Rev A	27-Feb-95	Bracket, Bearing Support 206-030-407-007/-009 and 206-030-433-005/-007/-011/-013/-015 and -017, One Time Inspection
ASB 206-92-70	Basic	3-Dec-92	Main Rotor Latch Bolt 206-011-260-101 and -103, Removal of Unapproved Bolts From Service
ASB 206-92-71	Basic	8-Dec-92	Fuel Quantity Probes 7740-00381 and 7740-00302, One Time Inspection
ASB 206-92-72	Basic	14-Dec-92	Torque Transducer 206-061-535-005-011, -013, Replacement of
ASB 206-93-73	Rev A	20-Jun-94	Cargo Hook, Breeze Eastern Customer Advisory Bulletin No. CAB-100-41 and Customer Service Bulletin No. CSB-143 and CSB-144
ASB 206-93-74	Rev B	4-Apr-94	Swashplate Support Assembly 206-010-452-001/-005/-109, Inspection of
ASB 206-93-75	Basic	19-Oct-93	Trunnion 206-011-113-103 Master Spline, Mislocation of
ASB 206-93-76	Rev B	6-Sep-94	Main Driveshaft Grease Lubricated Couplings 206-040-108 and 206-040-118, Over-Temperature Indicators, Installation of
ASB 206-93-77	Basic	17-Nov-93	Main Rotor Blade 206-010-200-133 Inspection and Rework
ASB 206-94-78	Basic	11-Apr-94	Landing Gear Assembly Improvement: Crosstube Assemblies, Replacement of and Skid Tube Assemblies, Modification of
ASB 206-94-79	Basic	5-May-94	Tail Rotor Pitch Horn 206-011-809-005/-107/-109, Looseness Check of
ASB 206-94-80	Basic	2-Aug-94	Main Rotor Trunnion 206-011-113-103, Removal From Service
ASB 206-94-81	Rev A	1-Nov-95	Landing Gear Assembly Improvement; Fixed Floats Kit P/N 206-706-008-013, Crosstube Assemblies P/N 206-050-169-001/-003, Replacement of
ASB 206-94-82	Rev A	17-Apr-95	Landing Gear Assembly Improvement; Emergency Flotation System Kit P/N 206-706-010, Crosstube Assemblies P/N 206-050-134-001, -007, -103, -003, -005, -011 and -105, Replacement of
ASB 206-94-83	Basic	6-Sep-94	Landing Gear Assembly Improvement Emergency Lightweight Float Kit P/N 206-706-211, Crosstube Assemblies P/N 206-050-107-25, -27, -119 and -121, Replacement of Skid Tube Assemblies P/N 206-050-246-ALL Dash Numbers, Modification of and Step Assemblies, P/N 206-050-259, Modification of
ASB 206-95-84	Basic	24-Jul-95	Hydraulic Servo Actuators (HR Textron) Shoulder Bolts, One Time Inspection of
ASB 206-95-85	Basic	5-Sep-95	Main Drive Shaft 206-040-015-103 Inner Coupling to Shaft Attachment Hardware, One Time Inspection of
ASB 206-95-86	Rev B	18-Dec-95	Tail Rotor Driveshaft Hanger Assembly and Spring, Inspection of

## 206A/B/B3 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 206-96-87	Rev A	22-Mar-96	Cyclic and Collective Servo Support Assembly P/N 206-001-566-105, Identification of
ASB 206-96-88	Basic	3-Jun-96	Landing Gear Assembly Improvement; Fixed Float Kit P/N 206-706-008-011; Crosstube Assemblies P/N 206-050-157-001 & -003, Replacement of
ASB 206-97-89	Basic	20-May-97	R-134a Air Conditioning System Installation Hardware, Replacement of
ASB 206-97-90	Basic	20-Jun-97	Main Rotor Hub Pillow Block, Change in Retention Hardware
ASB 206-97-91	Basic	10-Oct-97	Engine Driven Fuel Pump (CECO), Internal Drive Spline, Inspection of
ASB 206-98-92	Rev A	10-Oct-02	Engine Fuel Control Unit, Internal Spring Replacement
ASB 206-00-93	Rev A	10-May-00	Collective Lever Assembly 206-010-467-001, Modification and New Collective Lever Assembly/-105, Introduction of
ASB 206B1-01-94	Basic	19-Jan-01	Magnetic Brake P/N 204-001-376-003, One Time Inspection of
ASB 206-01-95	Basic	6-Mar-01	Rescue Hoist, BL-16600 Series, Breeze Eastern Customer Alert Bulletin CAB-100-58
ASB 206-01-96	Rev A	7-May-01	Chip Detector Assembly, Tedeco B3188B
ASB 206-01-97	Basic	26-Jul-01	Strap Fittings P/N 206-011-140-001, Tail Rotor Gearbox Input Pinions, P/N 206-040-405-101, Inspection and Recall of Specific Serial Number Part
ASB 206-01-98	Basic	11-Oct-01	Rolls Royce Engine, Gearbox Assembly - Inspection of Helical Torquemeter Gearshaft Assembly
ASB 206-02-99	Rev A	31-Jan-03	Main Rotor Blades 206-010-200-ALL, Inspection and Rework of
ASB 206-04-100	Rev C	5-Mar-05	Tail Rotor Blades 206-016-201-133/-131, Check/Inspection of
ASB 206-04-101	Basic	13-Sep-04	Tail Rotor Blade 206-016-201-131, Check and Removal from Service of
ASB 206-04-102	Basic	24-Sep-04	Inside Door Handle Assembly P/N 206-031-620-101, Inspection and Rework of
ASB 206-05-103	Rev A	12-Jul-06	Fuel Distribution System, Inspection and Rework of
ASB 206-05-104	Basic	17-May-05	Torque Indicator 206-075-739-125, Recall of
ASB 206-05-105	Basic	8-Nov-05	Tail Rotor Trunnion Housing Seal 535642 Installation, One Time Inspection of
ASB 206-06-106	Basic	17-Feb-06	Float Inflation Valve Squib P/N 29022968, Misidentification of
ASB 206-06-107	Rev A	15-Jun-06	Vertical Fin Supports 206-031-417-003/-007 and 206-031-418-001/-005, Inspection of
ASB 206-06-108	Basic	8-Jul-06	Aeronautical Accessories Inc. Flat Crew Window P/N 206-202-001 and 206-202-002, STC SH5773SW
ASB 206-06-109	Basic	25-Jul-06	Main Rotor Latch Bolts 206-010-169-001/-003 and 206-011-122-003, Removal from Service of
ASB 206-06-110	Basic	7-Sep-06	Upper Left-hand Tailboom Attachment Hardware, Inspection of
ASB 206-06-111	Basic	12-Oct-06	Engine, Turbine Assembly - Power Turbine Outer Shaft

## 206A/B/B3 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 206-07-112	Basic	9-Mar-07	Aeronautical Accessories, Inc. ASB No. AA-06107 for PC Safety Valve: Valve Stem Over Torque
ASB 206-07-113	Basic	23-Mar-07	Cargo Hook Stress Corrosion Cracks
ASB 206-07-114	Basic	28-Mar-07	Disc Assembly 32721-1, Inspection of
ASB 206-07-115	Rev C	4-Feb-09	Power Turbine RPM (N2) Steady State Operation Avoidance, Introduction of
ASB 206-07-116	Rev B	29-Nov-10	Tail Rotor Blade Assembly, Inspection of
ASB 206-08-117	Basic	17-Jun-08	Engine, Fuel and Control - Power Turbine Governor Increased Reliability
ASB 206-08-118	Basic	18-Aug-08	Misidentification Of: 206-010-467-105 Collective Lever Assembly
ASB 206-09-119	Basic	15-Jan-09	Vertical Fin Assembly 206-020-113-231, Inspection of
ASB 206-09-120	Basic	25-Feb-09	Main Rotor Pitch Horn Trunnion Bearing 206-011-105-001, One Time Check
ASB 206-09-121	Rev C	24-Aug-09	Lever Assembly P/N 206-001-401-111, 206-001-400-115 and 206-001-400-111 One Time Inspection of
ASB 206-09-122	Basic	7-Apr-09	Staked Bearings, One Time Inspection of
ASB 206-09-123	Rev A	10-Jun-09	Disc Assembly 101584-2, Recall of
ASB 206-09-124	Basic	18-May-09	Hydraulic System or Control Boost Switch - Off Check, Change of
ASB 206-09-125	Basic	4-Aug-09	Engine, Fuel and Control -- Honeywell Main Fuel Controls -- Verification of Fuel Flow Calibration
ASB 206-10-126	Basic	19-Apr-10	Aircraft Ground Receptacle, One Time Verification
ASB 206-11-127	Basic	2-May-11	Control Box Assembly P/N 206-375-017-101, Recall of
ASB 206-11-128	Basic	30-Jun-11	Crew Seat Clip Retainers, Installation of



# BHT-206A/B/B3-ASB-INDEX

## NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
-------------	---------------	------	---------