



ALERT SERVICE BULLETIN INDEX

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

13 DECEMBER 2011

430 ALERT SERVICE BULLETIN INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 430-97-1	Basic	21-May-97	Engine, Allison 250-C40B Operational Restrictions and Replacement of Power Take-Off Gears
ASB 430-97-2	Basic	11-Jul-97	Model 430 Temporary Airspeed Restriction
ASB 430-97-3	Basic	17-Sep-97	FADEC EUC Fail and Retractable Landing Gear Indicating Systems
ASB 430-97-4	Basic	19-Dec-97	Temporary Airspeed Restriction, Removal of, Following Damper Yoke Set
ASB 430-98-5	Basic	12-Jun-98	Vertical Fin Assembly, Installation Inspection and Modification
ASB 430-98-6	Basic	12-Jun-98	Replacement of Lateral Control Tube Assembly
ASB 430-98-7	Basic	9-Sep-98	Pilot and Copilot Static System Modifications
ASB 430-98-8	Basic	31-Dec-98	Damper Blade Set, Introduction of
ASB 430-99-9	Basic	3-Mar-99	Swashplate Duplex Bearing Inspection
ASB 430-99-10	Basic	16-Dec-99	Electrical Power Distribution System, Modification of
ASB 430-99-11	Basic	7-May-99	Auto Pilot Resolver Installation, Improvement of
ASB 430-99-12	Basic	16-Dec-99	Tail Rotor (T/R) Pitch Change Bearings, Inspection of; And Tail Rotor Blade Attaching Hardware, Replacement of
ASB 430-99-13	Basic	13-Dec-99	Fuel Quantity Indicating System Calibration
ASB 430-99-14	Basic	17-Dec-99	Chapter 4 - Airworthiness Limitations Schedule, Changes To
ASB 430-00-15	Rev A	13-Jul-01	Rolls-Royce 250-C40B Engine, Inspection of the Self-Sealing Magnetic Chip Detectors
ASB 430-00-16	Basic	21-Jun-00	Instrument Panel Cooling, Improvement
ASB 430-00-17	Basic	19-May-00	Hydraulic Actuator Support, Inspection of
ASB 430-00-18	Rev A	13-Nov-00	Rolls-Royce 250-C40B Engine, Replacement of Compressor Scroll
ASB 430-01-19	Rev A	24-Jan-02	Electrical Systems, Improvements
ASB 430-01-20	Basic	26-Jan-01	Swashplate Duplex Bearing, Removal from Service
ASB 430-01-21	Basic	7-Feb-01	Upper Fuel Enclosure, Right Side, Addition of Drain Provision
ASB 430-01-22	Basic	30-Apr-01	Temporary Ambient Air Temperature Limitation, Removal of
ASB 430-01-23	Basic	20-Jul-01	Drive Hub, Inspection and Recall of Specific Serial Number Part
ASB 430-02-24	Basic	12-Feb-02	Isolation of FADEC-ECU Power Supplies
ASB 430-02-25	Basic	9-Apr-02	Fuel System Check and Relief Valve, Replacement of
ASB 430-02-26	Basic	2-May-02	Wheel Gear Hydraulic Tube Assembly and Wheel Brake Hydraulic Tube Assembly, Replacement of
ASB 430-03-27	Basic	14-Oct-03	Electrical Power Feeders, Modification of
ASB 430-03-28	Basic	3-Mar-03	Airspeed Limits, Revision of
ASB 430-03-29	Basic	11-Nov-03	Rolls-Royce 250-C40B Engine, Inspection of 4th Stage Turbine Wheels
ASB 430-04-30	Rev C	16-Feb-06	Tail Rotor Counterweight Bellcrank, Removal from Service
ASB 430-04-31	Rev C	31-Mar-08	Tail Rotor Blade, Inspection of
ASB 430-04-32	Rev B	15-Mar-06	Tail Rotor Counterweight Bellcrank, Inspection of

430 ALERT SERVICE BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 430-05-33	Basic	16-Feb-05	Introduction of Retirement Life for the Servo Actuator to Actuator Support Bolts
ASB 430-05-34	Basic	10-Jun-05	New Transient Limit and Power Turbine RPM (NP) Steady State Operation Avoidance, Introduction of
ASB 430-05-35	Basic	21-Jun-05	AFCS Air Data Computer, Modification of, and VNE Overspeed Warning Computer, Airspeed Indicator and VNE Converter, Replacement of
ASB 430-05-36	Basic	11-Jul-05	Engine, Fuel and Control - Hydromechanical (HMU) Unit Procedures for Checking Nozzle Screen for Contamination
ASB 430-06-37	Basic	13-Mar-06	Revised Engine Power Assurance Check Procedures and Revised Run-in Test Procedure for Overhauled Transmission, Introduction of
ASB 430-06-38	Basic	11-Oct-06	Engine, Turbine Assembly - Power Turbine Outer Shaft
ASB 430-07-39	Basic	9-Jan-07	Tail Rotor Pitch Change Mechanism, Revised Rigging Procedures
ASB 430-07-40	Basic	28-Mar-07	Disc Assembly 36300-1, 37855-1 and C048354-1, Inspection of
ASB 430-07-41	Rev D	29-Nov-10	Tail Rotor Blade Assembly, Inspection of
ASB 430-09-42	Basic	7-Apr-09	Staked Bearings, One Time Inspection of
ASB 430-09-43	Basic	30-Oct-09	Revised Operating Limits, Introduction of
ASB 430-10-44	Rev A	30-Aug-11	Hydraulic Servoactuator P/N 222-382-001-107 Manufactured by Woodward HRT, Inspection of
ASB 430-10-45	Rev A	15-Dec-10	Directional Flight Control Bearing P/N MS27643-4; Inspection and Replacement of
ASB 430-11-46	Basic	9-Dec-11	Overhaul of Hydraulic Servo Actuator P/N 222-382-001-107 and Introduction of Servo Actuator P/N 222-382-001-111

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
--------------------	-----------------------	-------------	----------------