



A Textron Company

INFORMATION LETTER

505-24-39
206L-24-189
21 March 2024

TO: All owners and operators of Model 505 and 206L Series helicopters

SUBJECT: MAIN ROTOR MAST 206-040-535-109 AIRWORTHINESS LIFE, INCREASE OF.

Bell and Transport Canada Civil Aviation (TCCA) have reached an agreement to extend the life of main rotor mast 206-040-535-109 by 500 flight-hours to a new limit of 5500 flight-hours. The Retirement Index Number remains at 44,000 RIN. Revisions to the applicable Maintenance Manuals (MM) and Maintenance Planning Information (MPI) have been released.

It is also important to remind operators that any previously retired mast being re-introduced into service must be thoroughly inspected per the applicable Component Maintenance Manual (CMM) or Component Repair & Overhaul (CR&O) Manual. The records must be complete, and any damage repaired.

For any questions regarding this letter, please contact:

Bell Product Support Engineering
Tel: 1-450-437-2862 / 1-800-363-8023 / productsupport@bellflight.com