



ALERT SERVICE BULLETIN INDEX

NOTE

THIS INDEX IS A LIST OF ALERT SERVICE BULLETINS ISSUED. THIS INDEX DOES NOT IDENTIFY WHICH ALERT BULLETINS ARE ACTIVE OR INACTIVE.

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Alert Service Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-214ST-ASB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

214ST ALERT SERVICE BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
214ST-82-1	Basic	9-16-82	I	64	Tail Rotor Hub Assembly, P/N 214-010-800-101, Modification and Inspection of
214ST-82-2	Basic	10-1-82	I	64	Tail Rotor Installation, P/N 214-010-800-101, Modification of
214ST-82-3	Basic	10-25-82	I-I	53	Upper Left Hand Aft Fuselage Tail Boom Attach Longerons, P/N 214-031-431-101, Inspection and Modification of
214ST-82-4	Basic	11-19-82	I	53	Inspection Door Assy, P/N 214-030-325-003, Replacement with Door Assy, P/N 214-030-325-103
214ST-82-5	Basic	1-18-83	I	67	Dual Hydraulic Servo Actuator Assembly, P/N 214-076-161-101, Actuator Mount Nut Torque, Inspection of
214ST-83-6	Basic Rev A	1-19-83 2-28-83	A	64	Tail Rotor Blade, P/N 214-015-700-103, Inspection/Rework of
214ST-83-7	Basic	5-20-83	A	32	Emergency Float Kit, Forward Float(s) Installation, Improved Abrasion Protection Between Floats, P/N 214-052-200-101/-102 and Inflation Fittings

BHT-214ST-ASB INDEX**214ST ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
214ST-83-8	Basic	8-19-83	I	26	Engine Fire Extinguishing Bottles, P/N 214-069-980-101, Squib Discharge Valve, Identification and Wiring, Clarification of
214ST-83-9	Basic	8-31-83	I	62	Swashplate and Support Assembly, P/N 214-010-500-101, Lubrication and Inspection of
214ST-83-10	Basic	9-12-83	I	62	Main Rotor Spindle, P/N 214-010-103 (All Dash Numbers), Inspection of
214ST-83-11	Basic Rev A	10-17-83 12-1-83	I	53	Tailboom Ballast, P/N 214-031-661-101, and Provisions, Modification of
214ST-83-12	Basic	11-3-83	I	64	Tail Rotor Blade Retention/ Feathering Bearing Bolt, P/N 20-071-8-49H, Torque Verification
214ST-83-13	Basic	11-28-83	I	62	Main Rotor Grip Assembly, P/N 214-010-104-113, Retirement Life, Reduction of
214ST-84-14	Basic Rev A	1-9-84 5-10-84	I	64	Tail Rotor Pitch Change Tube Assembly, P/N 214-010-816-101, Inspection of
214ST-84-15	Basic	1-4-84	I	53	One Time Inspection of Electrical Cable for Evidence of Chafing
214ST-84-16	Basic	1-27-84	A	32	Nose Landing Gear Wheel Assembly, P/N 222-036-002-101, Inspection and/or Replacement of
214ST-84-17 (See ASB 214ST-85-30)	Basic	3-12-84	I-S	62	Collective Sleeve, P/N 214-010-411-001, With Serial Number A-19 Prefix, Inspection of
214ST-84-18	Basic	3-9-84	A	53	Pylon Support Assembly, P/N 214-031-810-107, Modification of
214ST-84-19	Basic	4-16-84	I	62	Inspection of Locking Plates, P/N's 214-010-231-101 and 214-010-232-101, for Proper Installation

214ST ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
214ST-84-20	Basic	5-9-84	I-P	64	Tail Rotor Pitch Change Tube Assembly, P/N 214-010-816-101, and Bearing Set, P/N 214-010-714-001, Replacement of
214ST-84-21	Basic	7-23-84	I	62	Scissors Drive Plate, P/N 214-010-413-105, Inspection of
214ST-84-22	Basic	7-24-84	I-I	62	Collective Lever, P/N 214-010-474-109/-113, Retirement Life, Reduction of
214ST-84-23	Basic	8-30-84	I-I	32	Emergency Flotation Reservoir, P/N 222-325-021-101, Decal (WARNING), P/N 31-023-8B, and Decal (CAUTION), P/N 31-023-9B, Installation of
214ST-84-24	Basic	8-30-84	I-1	62	Main Rotor Spindle, P/N 214-010-103-003, Retirement Life, Reduction of
214ST-84-25	Basic Rev A	11-12-84 11-29-84	I-I	62	Swashplate Duplex Bearing, P/N 214-010-430-001, Replacement of
214ST-84-26	Basic	12-10-84	I-P	64	Tail Rotor Crosshead Bearing Set, P/N 214-010-856-101, Inspection and Replacement of
214ST-85-27	Basic	3-15-85	I-I	96	One Time Inspection of Engine Aft Firewall Disconnects, 22P3, 22J23, 22P24, and 22J24, for Proper MIL Qualified Connector Part Numbers
214ST-85-28	Basic	5-28-85	I-1	95	Instrument Current Limiter, P/N 531-1, Reconfiguration of
214ST-85-29 (See ASB 214ST-86-35)	Basic	9-3-85	I-S	62	Drag Brace Assembly, P/N 214-010-113-001/-003, Inspection of
214ST-85-30	Basic	11-7-85	I-I	62	Collective Sleeve, P/N 214-010-411-001/-003 With Serial Number A-19 Prefix and A-1 Thru A-10, Reinspection of

BHT-214ST-ASB INDEX**214ST ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
214ST-85-31	Basic	11-7-85	A-R	62	Main Rotor Pitch Link Assembly, P/N 214-010-410 (All Dash Numbers), Inspection of
214ST-85-32	Basic Rev A	12-20-85 2-20-86	A-R	62	Main Rotor Spindle Bolt Assembly, P/N 214-010-183-101, Inspection, Replacement, and Retirement Life Reduction
214ST-86-33	Basic	2-20-86	I-P	62	Collective Sleeve Assembly, P/N 214-010-411-001/-003, Introduction of
214ST-86-34	Basic Rev B	2-26-86 5-23-88	I-I	4	Main Rotor Yoke, P/N 214-010-105-001, Reduction of Retirement Life, and Introduction of Main Rotor Hub Assembly, P/N 214-010-100-183
214ST-86-35	Basic	3-31-86	I-I	62	Drag Brace Assembly, P/N 214-010-113-001, Replacement of
214ST-86-36	Basic	6-11-86	I-I	62	Inspection Interval of Locking Plate, P/N 214-010-232-101, for Condition and Proper Installation, and Torque Check of Collective Hub Nut, P/N 214-010-417-001
214ST-86-37	Basic Rev A	10-8-86 11-3-86	I-I	62	Scissors and Sleeve Locking Plates, P/N 214-010-231-101 and P/N 214-010-232-101, Replacement of Retirement Life Reduction
214ST-87-38	Basic	2-17-87	I-I	64	Tail Rotor Crosshead, P/N 214-010-806-101, and Counterweight Bellcrank, Bearings, P/N 214-010-774-001, Inspection of
214ST-87-39	Basic Rev A	6-17-87 10-4-88	I-I	65	Tail Rotor Gearbox Main Case Assembly, P/N 214-040-409-109/-113, Inspection of
214ST-87-40	Basic	9-17-87	I-I	65	Tail Rotor Intermediate Gearbox, P/N 214-040-009-101, Inspection of

214ST ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
214ST-87-41	Basic Rev A	10-8-87 11-4-87	A	28	Engine Fuel Valve Electrical Connectors, P/N MS3456W14S5S, One Time Inspection of
214ST-88-42	Basic	3-14-88	I	32	Wheeled Landing Gear Kit, P/N 214-706-118-107, Beam and Fitting Assemblies, Serialization of
214ST-88-43	Basic	3-16-88	A	32	Wheeled Landing Gear Kit, P/N 214-706-118-101, -103, and -105, Main Gear Beam Assy and Oleo Shock Strut Attach Bolt, P/N NAS6214-33D, 40D, 44D
214ST-88-44	Basic	3-17-88	I	62	Drag Brace Assembly, P/N 214-010-113-105, Inspection of
214ST-88-45	Basic	4-25-88	A	25	Replacement of Cylinders on Charged Cylinder Assemblies, P/N 130101-400
214ST-88-46	Basic	5-31-88	A	62	Main Rotor Drag Brace Assembly, P/N 214-010-113-105, Inspection of
214ST-88-47	Basic Rev A	12-5-88 2-20-89	I-P	62	Drag Brace Assembly, P/N 214-010-113-105, Replacement of
214ST-88-48	Basic Rev A	1-10-89 8-1-89	A	71	Aeroquip 601 Hose Assemblies, One-Time Inspection and Replacement
214ST-89-49	Basic Rev B	8-11-89 4-10-90	I-P	63	Transmission External Oil Filter Bracket, P/N 214-040-599-101/-111, Replacement of
214ST-90-50 (See ASB 214ST-93-61)	Basic	1-15-90	I-S	SI	Breeze-Eastern Cargo Hooks P/N 17138-3, Warning Plate, Addition of
214ST-90-51	Basic	1-15-90	I-I	62	Main Rotor Flight Control System Bolts, Inspection of
214ST-90-52	Basic	2-5-90	A	62	Main Rotor Pylon Controls Installation, Bolt and Washer Replacement of

BHT-214ST-ASB INDEX**214ST ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
214ST-91-53 (See ASB 214ST-92-56)	Basic	1-15-91	I-S	53	Safety of Flight Message-Vertical Fin Forward Spar Crack
214ST-91-54	Basic	10-22-91	A	96	AFCS-SCAS Actuator Assemblies P/N 214-001-540-107/-113 Roll; P/N 214-001-540-109/-115 Pitch; P/N 214-001-540-111/-117 Yaw; Centering Spring P/N 214-001- 552-101, Inspection and Functional Test of
214ST-91-55	Basic	12-11-91	A	64	Tail Rotor Crosshead P/N 214- 010-806-101, Inspection of
214ST-92-56	Basic	3-4-92	A	53	Tailboom Fin Assembly, P/N 214- 021-002-ALL, Cold Expansion of Selected LH Forward Spar Fastener Holes
214ST-92-57	Basic	5-1-92	I-P	64	Tail Rotor Crosshead, P/N 214- 010-806-101, Replacement of
214ST-92-58	Basic	10-27-92	A	53	Tailboom Assembly, P/N 214-030- 003-ALL, Modification to Prevent Thermal Buckling of the Top Skin
214ST-92-59 (See ASB 214ST-94-68)	Basic Rev A	10-30-92 5-19-93	I-S	63	Spider, P/N 214-040-080-101, Establishment of a Retirement Life, and Method of Calculating Retirement Life
214ST-93-60	Basic Rev A	1-14-93 4-21-93	I-I	63	Improved Rotor Brake Quill, P/N 209-040-173-103, Installation of
214ST-93-61	Basic Rev A	6-21-93 5-24-93	A	SI	Breeze-Eastern Cargo Hook Customer Advisory Bulletin No. CAB-100-41 and Customer Service Bulletin No. CSB-148
214ST-93-62	Basic Rev A	7-5-93 10-8-99	I-I	4	Emergency Float System Pneumatic Hose Assembly Replacement and Calendar Life Assignment

214ST ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
214ST-93-63	Basic Rev A	12-7-93 3-4-94	I-I	63/65	Main Driveshaft and Tail Rotor Drive System Grease Lubricated Couplings, Overtemperature Indicators, Installation of
214ST-94-64	Basic	1-19-94	A	29/96	Additional Clamping Required Between Hydraulic Lines and Generator Feeder Cables to Maintain a Fixed Separation and to Eliminate Chafing
214ST-94-65	Basic	6-15-94	A	32	Air Crusiers Company Service Bulletin No. 903-25-1
214ST-94-66	Basic	11-7-94	I-I	4	Upper Planetary Carrier, P/N 214-040-077-007 and -101, Change in Retirement Life and Method of Determination
214ST-94-67	Basic	11-7-94	I-I	4	Main Rotor Mast, P/N 214-040-090-109 and -121, Change of Retirement Life and Method of Determination
214ST-94-68	Basic	11-7-94	I-I	4	Spider, P/N 214-040-080-101, Change in Retirement Life and Method of Determination
214ST-94-69	Basic	11-7-94	I-I	4	Pillow Block Bearing Bolts, P/N 20-057-12-48D, -50D, Change of Retirement Life and Method of Determination
214ST-94-70	Basic	11-7-94	I-I	4	Trunnion, P/N 214-010-230-101, Change in Retirement Life and Method of Determination
214ST-95-71	Basic	1-12-95	A	53	Left Hand Upper Fuselage Longeron, P/N 214-031-431-103, -105, One Time Inspection
214ST-95-72	Basic	7-24-95	A	5/53	Tailboom Assembly P/N 214-031-003-111, Inspection and Modification

BHT-214ST-ASB INDEX**214ST ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
214ST-95-73	Basic	11-13-95	A	53	Left Hand Upper Fuselage Longeron Assembly, P/N 214-031-431-103 Replacement, and P/N 214-031-431-105 Cold Expansion of Selected Fastener Holes
214ST-96-74	Basic	5-28-96	A	32	Modification and Upgrade of Emergency Float Inflation Solenoid Valve, P/N 214-073-929-ALL, and Solenoid Valve Assembly, P/N 214-073-940-ALL
214ST-96-75	Basic	8-26-96	A	64	Tail Rotor Yoke Assembly P/N 214-011-802-105 and -111 Inspection and Installation of Tail Rotor Flapping Stop P/N 214-011-809-109
214ST-97-76	Basic	5-20-97	A	62	Swashplate Duplex Bearing, P/N 214-310-400-101, One Time Inspection of
214ST-97-77	Basic	6-4-97	A	32	Air Cruisers Company Service Bulletin No. 903-25-02
214ST-97-78	Basic	7-17-97	A	62/53	Self-locking Barrel Nut, P/N NAS577B-10A, One Time Inspection of
214ST-97-79	Basic	9-8-97	A	95	Air Speed Indicator P/N 214-175-299-105 and Vertical Speed Indicator P/N 212-070-239-003, Removal From Service
214ST-98-80	Basic	2-23-98	A	95	Triple Tachometer P/N 214-175-251-103, Removal From Service
214ST-99-81	Basic	7-5-99	A	62	Main Rotor Strap Pin, P/N 214-010-117-001, Recall of
214ST-00-82	Basic	7-12-00	A	64	Tail Rotor Crosshead P/N 214-010-806-105, One Time Inspection of
214ST-01-83	Basic	1-19-01	A	67	Magnetic Brake P/N 204-001-376-103, One Time Inspection of

214ST ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
214ST-06-84	Basic Rev A	8-11-06 9-14-06	A	65	Tail Rotor Driveshaft Hanger Assembly Bearing, P/N 214-040-606-101, One Time Inspection
214ST-07-85	Basic	10-18-07	A	67	Cyclic Flight Control Bearing, P/N MS27643-3, One Time Inspection and Replacement of

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
---------------	--------------	-------------	---------------	--------------------------	----------------

BHT-214ST-ASB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------