



A Textron Company

## **INFORMATION LETTER**

**505-19-03**  
29 April 2019

**TO: All owners and operators of Model 505 helicopters**

**SUBJECT: BOSE® HEADSET SHORT CORD**

It was brought to Bell's attention that the headset cord as furnished with the Bose® A20 headset is unnecessarily too long to manage from tangling or interfering with the flight controls. This Bose® A20 headset configuration is installed as a customizing option during aircraft customizing prior to delivery from Bell.

As requested by some owner/operators, to help provide improved cockpit management of the dangling headset cord, a shorter cord is now available for those requesting this change.

The following part numbers apply, and are available from aviation equipment distributors:

Part number 324843-J040 provides a Bose® A20 headset with short Lemo® cord (6 pin).  
Part number 327070-J040 provides a short cord only with Lemo® connector (6 pin).

For any questions regarding this letter, please contact:

Bell Product Support Engineering  
LIGHT Tel: 450-437-2862 / 1-800-363-8023 / [productsupport@bellflight.com](mailto:productsupport@bellflight.com)