



TECHNICAL BULLETIN INDEX

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL ® HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

15 SEPTEMBER 2011

205B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205B-91-1	Basic	21-Jan-91	MRC Duplex Bearings P/N 204-040-424-001, Inspection and Recall
TB 205B-91-2	Rev A	19-Mar-92	Tail Rotor Pitch Change Tube Assembly P/N 209-011-710-All Electro Chemical Metalizing
TB 205B-92-3	Basic	3-Mar-92	Sump Case Assembly P/N 204-040-355-017, Rework Procedure to Reduce the Size of The Chip Detector Boss Entry-Countersink
TB 205B-92-4	Basic	10-Apr-92	Transmission Assembly P/N 212-040-001-187, Increase in Time-Between-Overhaul (TBO)
TB 205B-92-5	Basic	2-Jun-92	Transmission Oil Pump Key P/N 38-56007-1003 - 2 and MS35756-3 Which Were Supplied As Spares, Replacement of
TB 205B-93-6	Basic	24-Jun-93	Rotor Brake Quill P/N 412-040-123-101, One Time (External) Inspection
TB 205B-94-7	Basic	7-May-94	Case Assembly, Bevel Gear P/N 212-040-053-009
TB 205B-94-8	Basic	10-Sep-94	Electronic Power Turbine Overspeed Control System, Removal of
TB 205B-94-9	Basic	28-Nov-94	Rotor Brake Assembly, Introduction of Stainless Steel Piston
TB 205B-95-10	Basic	17-Jul-95	Tail Rotor Hub Assembly P/N 212-011-701-003, Conversion to -125 Configuration
TB 205B-95-11	Basic	18-Sep-95	Pillow Block Bushing P/N 204-011-135-105, Increase in Retirement Life
TB 205B-98-12	Basic	9-Sep-98	Breeze-Eastern A60LT Cargo Hook
TB 205B-99-13	Basic	10-Feb-99	Improved Pitch Horn to Main Rotor Grip Hardware
TB 205B-99-14	Basic	22-Feb-99	New Door Rollers and Sliders
TB 205B-99-15	Basic	19-Mar-99	Tail Rotor Gearbox Output Shaft Speedi-Sleeve, Addition of
TB 205B-99-16	Basic	7-May-99	Bellcrank Assembly Rework
TB 205B-99-17	Basic	7-May-99	New Sliding Door Latch Guards
TB 205B-99-18	Basic	26-Nov-99	Hinged Panel Assembly, Improvement of
TB 205B-00-19	Basic	30-Jun-00	Cyclic and Collective Jackshafts, Inspection and Modification of
TB 205B-01-20	Basic	31-Jan-01	Improved Tail Rotor Pitch Links
TB 205B-03-21	Basic	26-Mar-03	Lower Nose Doors P/N 212-030-217-011 and 212-030-205-001 and Seal Replacement
TB 205B-03-22	Basic	27-Aug-03	Transmission Oil Filter Assembly P/N 204-040-760-113, Introduction of
TB 205B-03-23	Basic	20-Oct-03	Swashplate and Support Assembly, Bolt 204-011-463-107, Introduction of
TB 205B-03-24	Basic	1-Dec-03	Engine to Transmission (Main Driveshaft) Alignment Procedure
TB 205B-04-25	Basic	28-May-04	Transmission Oil Pump 212-040-184-001, Modification of
TB 205B-05-26	Basic	11-May-05	Bearing and Liner Assemblies P/N 204-010-433-001 and P/N 204-011-443-001: Installation Improvements
TB 205B-05-27	Rev A	14-Dec-07	Tailboom Bulkhead Reinforcement

205B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 205B-06-28	Rev A	22-Jun-07	Improved Baggage Compartment Door Seal
TB 205B-06-29	Basic	21-Jul-06	Vertical Fin Cover Hinge Pin Improved Installation
TB 205B-08-30	Basic	26-Feb-08	Upper Crew Door Hinge Structure, Reinforcement of
TB 205B-08-31	Basic	13-May-08	Fuel Overflow Deflector Upgrade
TB 205B-09-32	Basic	28-Apr-09	Tail Rotor Gearbox Excluder Housing Leak: Prevention of

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
--------------------	-----------------------	-------------	----------------