



TECHNICAL BULLETIN INDEX

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

09 DECEMBER 2011

214ST TECHNICAL BULLETIN INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 214ST-82-1	Basic	7-Dec-82	Addition of a Doubler to the Tailboom Fin Upper Rib, P/N 214-021-214-119
TB 214ST-83-2	Basic	17-Jan-83	Hydraulic Servo Actuators, P/N 214-076-161-101, Install Boot, P/N 214-076-297-101
TB 214ST-83-3	Basic	28-Feb-83	Cargo Mirror Kit, P/N 214-706-041-101, Provision, Location of
TB 214ST-83-4	Basic	24-Feb-83	Passenger Steps, Pneumatic Lines, Boot Seal Addition of
TB 214ST-83-5	Basic	24-Feb-83	Float Switch Shields, P/N 214-073-950-101, Replacement of
TB 214ST-83-6	Basic	24-Feb-83	Engine Air Inlet Duct Assy, P/N 214-062-256-103, and -104, Modification of
TB 214ST-83-7	Basic	28-Feb-83	Fly-By-Wire (FBW) Elevator Control System, Improved Elevator Horn to Spar Attachment
TB 214ST-83-8	Basic	16-Mar-83	Air Barrier, P/N 214-031-641, on Number One Hanger Bearing Beam, P/N 214-031-716, Installation of
TB 214ST-83-9	Basic	17-Mar-83	Landing Gear Forward and Aft Crosstube Assemblies, P/N 214-052-002-101 or, -103 or 214-052-052-101, Inspection and Rework of
TB 214ST-83-10	Basic	29-Mar-83	Elastomeric Spring, (Helper Spring) P/N 214-031-617-107, Modification of
TB 214ST-83-11	Rev B	24-Jul-95	Upper door Track, P/N 214-031-277-119, -121, -129, -131 and FS 255.20 Bulkhead Cap, P/N 214-031-252-127, -128, -179, -180, Repair/Modification
TB 214ST-83-12	Basic	26-Apr-83	Aft Engine Tailpipe Fairing, P/N 214-061-866-267, Modification of
TB 214ST-83-13	Basic	16-May-83	Modification - Seat Installation Aux. Fuel Seat Belt Attach Point, Provisions for
TB 214ST-83-14	Basic	1-Jun-83	Tailboom Elevator Assemblies, P/N 214-021-100-103 and-104, Modification of
TB 214ST-83-15	Basic	6-Jun-83	Copilot Control Annunciator Dimming Resistor, Replacement of
TB 214ST-83-16	Basic	15-Jun-83	Forward Fuselage Assembly, P/N 214-031-002-107, Addition of Drain Holes and Seals
TB 214ST-83-17	Basic	20-Jun-83	Windshield Wiper Motor Converter, P/N 214-073-932-105 and -107, Replacement of
TB 214ST-83-18	Basic	4-Aug-83	Main Rotor Hydraulic Actuator, P/N 214-076-161-101/-103, Mount Bearing, Friction Adjustment of
TB 214ST-83-19	Basic	29-Aug-83	Cockpit Area Access Step P/N 214-031-840-103/-104, Installation of
TB 214ST-83-20	Basic	25-Oct-83	Engine Rigging and Load Demand Spindle (LDS) Marking, Change to
TB 214ST-83-21	Basic	25-Oct-83	Tail Rotor Retrofit Kit, P/N 214-704-071-101, Installation of
TB 214ST-83-22	Basic	11-Nov-83	Thrust Ring, P/N 214-010-559-101, and Idler Pin, P/N 214-010-422-101, Modification of

214ST TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 214ST-83-23	Basic	30-Oct-83	Park Brake Light, Disabling of
TB 214ST-84-24	Basic	25-Jan-84	Emergency Float System, P/N 214-706-120-105, Modification of
TB 214ST-84-25	Basic	15-Mar-84	Passenger Step Actuators, P/N 214-001-423-105, Replacement of
TB 214ST-84-26	Basic	15-Mar-84	Tail Rotor Driveshaft Cover Assemblies, P/N 214-031-319-105 and 214-061-866-215, Modification of, and Center Support Assy, P/N 214-031-318-103, Replacement of
TB 214ST-84-27	Basic	15-Mar-84	Passenger Door Bumper, Modification of
TB 214ST-84-28	Basic	16-Mar-84	Main Rotor Blade Tie-Down, Provisions for
TB 214ST-84-29	Basic	4-Apr-84	Number One Engine Throttle Grip Replacement of
TB 214ST-84-30	Basic	29-May-84	Extended Flights Over Water Food Ration Bag Assemblies, P/N 214-706-044-103/-104, Installation and Provisions for
TB 214ST-84-31	Rev B	25-Jun-85	Main Rotor Outboard Strap Fitting Assembly, P/N 214-010-115-001, Replacement of
TB 214ST-84-32	Basic	1-Jun-84	Life Raft Painter Line Kit, Provisions for
TB 214ST-84-33	Basic	12-Jun-84	Seals to the Access Panels on the Forward Fuselage Assembly, P/N 214-031-002-107, Replacement and Addition of
TB 214ST-84-34	Basic	15-Jun-84	Hinged Door Interior Panel Assembly, P/N 214-070-567-101/-102, Modification of
TB 214ST-84-35	Basic	13-Sep-84	Flight Director Kit, P/N 214-705-001-109, Wiring Modification of
TB 214ST-84-36	Basic	10-Sep-84	Tail Rotor Flapping Stop, P/N 214-001-809-101, Rework of
TB 214ST-84-37	Rev A	30-Jan-86	Main Rotor Hydraulic Actuator, P/N 214-076-161-101/-103, Piston Seals and Cylinder Assemblies, Replacement of
TB 214ST-84-38	Basic	28-Sep-84	Cabin Vent System, P/N 214-073-102-101, Modification of
TB 214ST-84-39	Basic	11-Oct-84	Emergency Float Bottle Brackets, P/N 214-031-305-123 and 214-031-925-121, Replacement of
TB 214ST-84-40	Basic	7-Nov-84	Access for On Ship Adjustments of Elevator Position Indicator, Provisions for
TB 214ST-84-41	Basic	20-Nov-84	Engine Governor Control Panel, P/N 214-175-385-103, RF Interference of
TB 214ST-84-42	Basic	27-Nov-84	Tailboom Fin, P/N 214-021-002-103, Modification of
TB 214ST-85-43	Rev A	2-Feb-88	M/R Hydraulic Actuator Bearing Housing Assembly, P/N 214-076-166-001, Modification of
TB 214ST-85-44	Basic	9-Jan-85	Throttle Rack Dust Cap, P/N 214-001-250-101, Modification of
TB 214ST-85-45	Basic	14-Feb-85	Improved Bleed Air Tube Assembly, P/N 214-060-069-127, Installation of
TB 214ST-85-46	Basic	14-Feb-85	Electrical Fuel Sump Drain Valve, P/N 214-066-328-101, Installation of
TB 214ST-85-47	Basic	14-Mar-85	Rotor Brake Master Cylinder Detent, Increase of
TB 214ST-85-48	Basic	18-Mar-85	Nose Wheel Landing Gear, P/N 214-052-121-105, Modification of

214ST TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 214ST-85-49	Basic	11-Mar-85	Liferaft Assemblies, P/N 214-070-943-103, -104, -107, -108, -109, and -110, (Vendor: Sargent Industries, Pico Division, P/Ns 100103-205, -206, -305, and -306 and 100102-701 and -702) Modification of
TB 214ST-85-50	Basic	26-Apr-85	Retirement Life for Main Rotor Grip, P/N 214-010-104-121
TB 214ST-85-51	Basic	2-May-85	Improved Oil Pressure Transmitter, P/N 222-375-077-111, Introduction of
TB 214ST-85-52	Basic	10-May-85	Flight Director Kit, P/N 214-705-001-109, Altitude Sensor, Wiring Modifications of
TB 214ST-85-53	Basic	23-May-85	Combining Gearbox Assembly, P/N 214-040-013-109, Installation of
TB 214ST-85-54	Basic	18-Jun-85	Engine Fire Extinguisher Decal, P/N 214-069-936-101, Addition of
TB 214ST-85-55	Basic	18-Jun-85	Hose Assembly, P/N AE3908K0226-065 Installation of
TB 214ST-85-56	Basic	18-Jun-85	Improved Transmission Oil Filter Support Bracket, P/N 214-040-599-111, Installation of (See ASB 214ST-89-49)
TB 214ST-85-57	Basic	12-Aug-85	AARS Tachometer Excitation External Bias Resistor, Addition of
TB 214ST-85-58	Basic	15-Aug-85	Hydraulic Motor, P/N 214-076-333-101, Modification to New Configuration
TB 214ST-85-59	Basic	4-Sep-85	Air Conditioning Installation, P/N 214-889-199-101/-103 and P/N 214-899-285-101/-103/-105, Installation of Caution Decal
TB 214ST-85-60	Rev A	29-Oct-85	Fuel Quantity Decal, P/N 214-175-274-101, Replacement of
TB 214ST-85-61	Basic	15-Oct-85	Cyclic Control Tube, P/N 214-001-088-101, Inspection and Replacement of
TB 214ST-85-62	Basic	15-Oct-85	Airspeed Data Computer Retrofit, P/N 214-704-073-101
TB 214ST-85-63	Basic	1-Nov-85	Tail Rotor Blade, P/N 214-015-700-111, Improved Visibility Paint Scheme
TB 214ST-86-64	Rev A	28-Sep-87	Nodal Beam Assembly, P/N 214-031-601-101, -109, -111, Modification of
TB 214ST-86-65	Basic	26-Mar-86	Retainer Secured (Push Out) Passenger Compartment Windows
TB 214ST-86-66	Basic	21-May-86	Hydraulic System Installation, PCI, PCII, and Utility, Replacement of 2014/2024 Aluminum Alloy Flareless Tube Fittings
TB 214ST-86-67	Basic	19-Jun-86	Hydraulically Driven Fan, P/N 214-040-860-103 and -105, Replacement of Washer
TB 214ST-86-68	Basic	30-Jul-86	Main Rotor Hydraulic Actuator, P/N 214-076-161-101/-103 and -105, Piston Seals and Upper Cylinder, Replacement of
TB 214ST-86-69	Basic	3-Oct-86	Hydraulic Pump, P/N 214-076-033-001 (Abex Model AP1V-105, P/N 63074), Replacement of External Driveshaft

214ST TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 214ST-87-70	Basic	14-Jan-87	Collective Lever Assembly, P/N 214-010-492-105 and 214-010-250-105, Introduction of
TB 214ST-87-71	Basic	27-Jan-87	Center Headliner, P/N 214-070-527-101, Modification of
TB 214ST-87-72	Basic	27-Jan-87	Environmental/EMI Protected Engine Compartment Harnesses, P/N 214-075-083-101/-103, Addition of
TB 214ST-87-73	Basic	28-Jan-87	PC2 Hydraulic System Module, Installation of Fill Port Elbow
TB 214ST-87-74	Basic	21-Apr-87	Support, P/N 214-031-716-115, Modification to Improve Water Drainage from Aft Engine Deck, P/N 214-031-712-101
TB 214ST-87-75	Rev A	7-Mar-88	Landing Gear Strap Assemblies, P/N 214-031-839-101/-102, Rework of
TB 214ST-87-76	Basic	1-Jun-87	Passenger Step Assembly, P/N 214-031-791-101/-102, Attachment, Replacement of
TB 214ST-87-77	Basic	18-Aug-87	Markings Installation, P/N 214-070-515-101/-103/-105/-107/-109/-113/-115, Tail Rotor Hazard Warnings Decals, Addition of
TB 214ST-87-78	Basic	26-Oct-87	Heat Sensor Access Panel for Helicopters with Air Conditioning
TB 214ST-88-79	Basic	14-Jan-88	Inspection and Corrosion Protection of Directional Control Bellcrank Support to Tail Rotor Gearbox Faying Surface
TB 214ST-88-80	Basic	8-Feb-88	Addition of Identification Decal to Aircraft Exterior
TB 214ST-88-81	Basic	8-Apr-88	Nose Frame Assembly, P/N 214-031-123-115 and -116, Repair of
TB 214ST-88-82	Basic	8-Apr-88	Roof Door Track, P/N 214-031-512-101, Repair of
TB 214ST-88-83	Rev A	13-May-88	Fuel Cell Panel Assembly, P/N 214-031-709-103, Repair of
TB 214ST-88-84	Basic	2-May-88	Aft Engine Tailpipe, Fairing P/N 214-061-866-267, Modification and/or Replacement of
TB 214ST-88-85	Rev A	17-Oct-88	Lower Center, Left and Right Side Skins, P/N 214-031-703-107 and -109, 214-031-704-103 and -105, and 214-031-705-103, Modification of
TB 214ST-88-86	Basic	30-Jun-88	Rotor Brake Assembly, Modification of
TB 214ST-88-87	Basic	12-Sep-88	Transmission Oil Cooler Blower Bleed Air Shutoff and Line Check Valve, P/N 209-072-433-107, Installation of
TB 214ST-88-88	Basic	16-Sep-88	Firewalls Installation, P/N 214-061-870-105/-107/-109/-111, Repair of
TB 214ST-88-89	Basic	26-Sep-88	Engine Bleed Air Shutoff and Line Check Valves, P/N 209-072-433-105, Installation of
TB 214ST-88-90	Basic	28-Sep-88	Left Hand Panel Assembly, P/N 214-021-211, Lower Vertical Tailboom Fin, Cracked
TB 214ST-88-91	Basic	6-Oct-88	Tailboom Attachment at Fuselage Longeron Forgings, Spot Facing of Forward Surfaces
TB 214ST-88-92	Basic	27-Oct-88	Clevis Assembly, P/N 214-031-817-102, Modification of

214ST TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 214ST-89-93	Basic	5-Jan-89	Collective Hub, P/N 214-010-505-109 and Hub Nut, P/N 214-010-417-103, With Left Hand Threads, Introduction of
TB 214ST-89-94	Basic	6-Jan-89	Nodal Beam Support Weight Attachment Bolts, Increase Torque and Replacement of
TB 214ST-89-95	Basic	26-Jan-89	Left Pylon Cover Plate and Seal Tape, Replacement of
TB 214ST-89-96	Basic	30-Jan-89	Baggage and Electrical Compartment Seal Tape P/N 4516, Addition of
TB 214ST-89-97	Basic	9-Feb-89	Hydraulic Flight Control Cylinders, P/N 214-076-161-101/-103/-105 and 214-076-294-101, Bypass Indicator Switch Replacement and Adjustment Procedure
TB 214ST-89-98	Basic	22-Feb-89	Utility Hydraulic System, Modification of
TB 214ST-89-99	Basic	23-Feb-89	Oil Cooler System, P/N 214-040-018-103 and -105, Replacement of Hydraulic Motor and Tube Assemblies
TB 214ST-89-100	Basic	13-Apr-89	Air Conditioning Expansion Valve, Providing Additional Clearance to Nodal Beam Assy
TB 214ST-89-101	Basic	18-May-89	85 Gallon Auxiliary Fuel Kit, P/N 214-706-600, Modification of
TB 214ST-89-102	Basic	18-May-89	FWD Cabin Roof Assy/Door Post Joint P/N 214-031-500-103, -107, -155, -159, Modification of
TB 214ST-89-103	Basic	8-Jun-89	Tail Rotor Gearbox Assembly P/N 214-040-011, Configuration Change and Upgrade
TB 214ST-89-104	Basic	28-Jul-89	Tail Rotor Crosshead P/N 214-010-806-105, Introduction of (See ASB 214ST-92-57)
TB 214ST-89-105	Basic	28-Sep-89	Left and Right Side Upper Aft Cabin Rain Gutter, P/N 214-031-525-117/-118, Modification of
TB 214ST-89-106	Basic	7-Nov-89	Tailboom Assembly, P/N 214-031-003- Prior to -111, Modification of
TB 214ST-89-107	Basic	8-Nov-89	Intermediate Gearbox Assembly, P/N 214-040-011, Configuration Change and Upgrade
TB 214ST-89-108	Rev A	17-Feb-95	Scissors and Sleeve Assembly, P/N 214-010-501, Configuration Change and Upgrade
TB 214ST-90-109	Rev A	12-Nov-90	Mast Assembly P/N 214-040-003-105 and -107, Configuration Change and Upgrade
TB 214ST-90-110	Rev C	22-Dec-00	Combining Gearbox Assembly P/N 214-040-013, Configuration Change and Upgrade
TB 214ST-90-111	Basic	6-Mar-90	Main Rotor Blade Tiedown, P/N 214-070-081-147 Rework, to, P/N 214-070-081-171 and Add Attachment Bracket to Tailboom
TB 214ST-90-112	Rev A	30-Aug-11	Roof Frame P/N 214-031-516-131, -132, -139, and -140, Repair/Modification of
TB 214ST-90-113	Basic	3-Oct-90	3 Micron Transmission External Oil Filter Assembly, P/N 214-040-760-101, Installation of

214ST TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 214ST-90-114	Basic	8-Oct-90	3 Micron Combining Gearbox External Oil Filter Assembly P/N 214-040-760-101, Installation of
TB 214ST-90-115	Rev A	30-Apr-08	Tail Rotor Driveshaft Hanger Assembly P/N 214-040-600, Configuration Change and Upgrade
TB 214ST-90-116	Basic	9-Nov-90	Voltage Transient Suppression Diode Assembly For Yaw Magnetic Brake, Installation of
TB 214ST-90-117	Basic	9-Nov-90	AFCS SCAS Actuator P/N's 214-001-540-107; -113 (Roll), 214-001-540-109; -115 (Pitch), 214-001-540-111; -117 (Yaw), Repair and Overhaul
TB 214ST-91-118	Basic	9-Jan-91	AFCS Fly by Wire Elevator Actuator P/N's 214-001-970-107/-111, Overhaul of
TB 214ST-91-119	Rev A	25-Sep-00	Main Transmission Assembly P/N 214-040-002, Configuration Change and Upgrade
TB 214ST-91-120	Basic	30-Jan-91	Improved Anti-Collision Light Installation
TB 214ST-91-121	Basic	13-Feb-91	Swashplate and Support Assembly P/N 214-010-500, Configuration Change and Upgrade
TB 214ST-91-122	Basic	19-Feb-91	Introduction of New Oil Sight Glass for Combining Gearbox
TB 214ST-91-123	Basic	7-May-91	Main and Tail Rotor Driveshaft Splined Coupling and Hangers, Revision to the Special Inspection and Overhaul Requirements
TB 214ST-91-124	Basic	27-Jun-91	Main Rotor Hydraulic Actuator, P/N 214-076-161-101/-103/-105 and -107, Piston Seals and Rod Seals, Replacement of
TB 214ST-91-125	Basic	1-Aug-91	Passenger and Sliding Door Lock Switches, Replacement of
TB 214ST-91-126	Basic	22-Oct-91	Non-Essential Bus, Improved Operational Logic of
TB 214ST-92-127	Basic	13-Feb-92	Improved Rotor Brake Quill, P/N 209-040-173-103, Introduction of (See ASB 214ST-93-60)
TB 214ST-93-128	Basic	17-Mar-93	Tail Rotor Hub Assembly, P/N 214-011-801-109, Bonding of Trunnion Bearing Housings in Yoke
TB 214ST-93-129	Basic	27-Aug-93	Main Rotor Spindle Special Inspection Deletion
TB 214ST-93-130	Basic	20-Oct-93	Tail Rotor Gearbox Inspection Change
TB 214ST-93-131	Basic	3-Dec-93	Forward Main (Wheel) Landing Gear Support Fitting, P/N 214-031-438-101, -102, -103 and -104, Retirement Life, Increase of
TB 214ST-93-132	Basic	15-Dec-93	AFCS Actuator, Attitude (AARS) P/N's 214-001-370-101/-103, Functional Test
TB 214ST-94-133	Basic	19-Jan-94	Main (Wheel) Landing Gear Beam Assembly, P/N 214-052-102-103, -104, -105, and -106, Retirement Life, Increase of
TB 214ST-94-134	Basic	19-Jan-94	Left Hand Upper Fuselage Longerons, P/N 214-031-431-101, -105, Maintenance Manual Inspection Revision
TB 214ST-94-135	Basic	26-Jul-94	Main Rotor Mast Assembly, P/N 214-040-090-109 and -121, Retirement Life, Increase of

214ST TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 214ST-94-136	Basic	29-Jul-94	TBO Increase for Generator P/N 214-175-150-105
TB 214ST-94-137	Basic	18-Aug-94	Upper Door Track P/N 214-031-512-103, -104, -105 and -106 and Roof Skin P/N 214-031-500-115/-116 Repair/Modification
TB 214ST-94-138	Basic	6-Sep-94	AFCS SCAS Actuator P/N 214-001-540-107, -113 (Roll); -109, -115 (Pitch); and -111, -117 (Yaw), Rework When Solenoid P/N 214-001-570-103 is Installed
TB 214ST-94-139	Rev A	17-Feb-95	Crew Seat Attenuators P/N 222-020-840-117/-119, Verification and Rework of
TB 214ST-94-140	Basic	28-Nov-94	Aircraft Braking Systems Service Bulletin: Introduction of Stainless Steel Piston 5011934
TB 214ST-94-141	Basic	28-Nov-94	214ST Relocation and Replacement of, "Door Lock" Sliding and Hinge Cargo Door Switches and Addition of Baggage Compartment Isolation Switch
TB 214ST-95-142	Basic	14-Feb-95	Scissors and Sleeve Assembly, P/N 214-010-501-103, -107, -109, -113 and -115, Drive Plate Attachment Bolt and Washer Replacement
TB 214ST-95-143	Basic	17-Feb-95	Lucas Western Service Bulletins: High Performance Rescue Hoist Assembly Washer Interference
TB 214ST-95-144	Basic	13-Mar-95	Tailboom Assembly P/N 214-031-003-111, Inspection and Modification (See ASB 214ST-95-72)
TB 214ST-95-145	Rev A	1-Jun-95	Introduction of Improved Spider P/N 214-040-357-101
TB 214ST-95-146	Basic	15-Jun-95	Main Rotor Blade Assembly, P/N 214-015-300-105 and -107, Retirement Life, Increase of
TB 214ST-95-147	Basic	14-Aug-95	HR Textron Service Bulletin 41002810-67-02: Replacement of Upper End Cap on Dual Hydraulic Servo Actuator Assembly 41002810 (BHT P/N 214-076-161-ALL)
TB 214ST-95-148	Basic	2-Oct-95	Engine to Transmission Driveshaft Assembly P/N 214-040-014, Configuration Change and Upgrade
TB 214ST-95-149	Basic	9-Oct-95	Introduction of New Emergency Float Inflation Solenoid Valve, P/N 214-073-929-105 and Solenoid Valve Assembly, P/N 214-073-940-103 (See ASB 214ST-96-74)
TB 214ST-97-150	Basic	8-Jan-97	Introduction of New Life Raft Ejection Bag Reservoir Bottle, P/N 44000-1
TB 214ST-97-151	Basic	31-Jan-97	Combining Gearbox Assembly, P/N 214-040-013-115, Installation of
TB 214ST-97-152	Basic	21-Mar-97	Introduction of New Main Rotor Pitch Change Bearing Assembly, Inner Race P/N 214-310-001-101, and Bearing, P/N 214-310-002-101
TB 214ST-97-153	Basic	11-Jul-97	Modification of Collective Actuator Balance Spring Installation
TB 214ST-97-154	Basic	31-Jul-97	Main Rotor Hub Assembly, P/N 214-010-100-183 and Subsequent, Configuration Change and Upgrade

214ST TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 214ST-97-155	Basic	27-Aug-97	Modification of P/N 214-015-300, Main Rotor Blades to P/N 214-015-300-129 By Application of a High Visibility Paint Scheme
TB 214ST-98-156	Rev A	15-Mar-00	Bellmouth Heater Circuit, Modification of
TB 214ST-98-157	Rev A	22-Oct-98	Forward and Aft Cross Tube Assemblies, P/N 214-052-002-103 and 214-052-052-101, Maintenance Manual Revision, Inspection, Data Plate Removal, and Re-identification
TB 214ST-98-158	Rev A	11-Aug-99	Dual Hydraulic Servo Actuator Assembly, P/N 214-076-161-ALL: Change in Retirement Life and Establishment of TBO Interval
TB 214ST-98-159	Basic	27-Oct-98	Keith Products, Inc., Service Bulletin SB-98002, Modification of ES73171-4 Blower Assembly
TB 214ST-99-160	Basic	26-Jan-99	Starter Motor Clutch Assembly, P/N 36B510954G2, Cleaning/Overhaul Procedure
TB 214ST-99-161	Basic	2-May-99	Speaker Mount Bracket Assembly, Replacement of
TB 214ST-99-162	Basic	19-Nov-99	Introduction of P/N 214-030-626-103 Clevis and P/N 214-031-601-129 Restraint Assembly, and Modification of P/N 214-030-626-101 Clevis
TB 214ST-00-163	Basic	14-Jun-00	Introduction of New Transmission Ring Gear Case Assembly, P/N 214-040-361-101
TB 214ST-00-164	Basic	27-Nov-00	Introduction of New Combining Gearbox Assembly Generator Pad Seal, P/N 209-340-265-103
TB 214ST-01-165	Basic	2-Apr-01	BL 14.0 Left and Right Hand Main Beam Assemblies, FS 227.10 Center Bulkhead Assembly, and FS 255.20 Aft Cabin Bulkhead Assembly, Additional Maintenance Manual Inspection Requirements
TB 214ST-02-166	Basic	25-Jan-02	Tail Rotor Hub Assembly Blade Pitch Change Bearing Bolts, Additional Maintenance Manual and Component Repair and Overhaul Manual Inspection and Assembly Requirements
TB 214ST-02-167	Basic	31-May-02	Tailboom Station (BS) 293.50 Bulkhead Installation and Vertical Fin Assembly Splices, Additional Maintenance Manual Inspection Requirements
TB 214ST-02-168	Basic	11-Jun-02	Introduction of P/N 214-001-133-103 Collar and Modification of Existing P/N 214-001-133-001 Collar
TB 214ST-02-169	Basic	30-Aug-02	Main Rotor Hub Assembly Spindle Assembly, P/N 214-010-103, Revision of Inspection and Overhaul Requirements
TB 214ST-02-170	Basic	30-Aug-02	Introduction of P/N 214-060-056-109 Electric Starter Motor
TB 214ST-02-171	Basic	4-Nov-02	Introduction of New Tail Rotor Blade Retaining Bolt and Washer Hardware
TB 214ST-02-172	Basic	8-Nov-02	Replacement of P/N 214-175-380-101 Nickel-Cadmium Battery
TB 214ST-03-173	Basic	14-Mar-03	Intermediate Gearbox Mounting Hardware Change

214ST TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 214ST-04-174	Rev A	26-Jun-06	Scissors and Sleeve Assembly, Sleeve Upper Nut, P/N 214-010-418-001, Additional Maintenance Manual Inspection Requirements
TB 214ST-06-175	Basic	28-Aug-06	Support Plates on the Fly By Wire (FBW) 214-001-970-107/-111 Actuators, Installation of
TB 214ST-11-176	Basic	28-Nov-11	Main Rotor Trunnion Assembly, P/N 214-010-230-101, Revision of Magnetic Particle Inspection Procedure

BHT-214ST-TB-INDEX

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
-------------	---------------	------	---------