



TECHNICAL BULLETIN INDEX

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

15 SEPTEMBER 2011

222/B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 222-80-1	Basic	13-Jun-80	Increase of Usable Fuel
TB 222-80-2	Basic	3-Sep-80	Transmission Pan Drain Line, P/N 222-031-531, Modification
TB 222-80-3	Basic	8-Sep-80	Clear Vision Window Hinge Pin, P/N 222-031-177-119, Retention of
TB 222-80-4	Basic	10-Sep-80	Gear Ground Lock Warning Streamer, P/N NAS1091-36H, Modification of
TB 222-80-5	Basic	15-Sep-80	Seal Drain Provisions for Input Quill Assembly, P/N 222-040-027, Installation of
TB 222-80-6	Basic	15-Sep-80	Exhaust Ejectors, P/N 222-062-216-101, Modification of
TB 222-80-7	Basic	5-Nov-80	Firewall, Center, Modification of Line, T1, Restraint of
TB 222-80-8	Rev A	25-May-83	Engine LTS101 650C-3, Installation and Use of
TB 222-80-9	Basic	10-Nov-80	Copilot Collective Stick, P/N 222-001-262-101, Modification of
TB 222-80-10	Basic	10-Dec-80	Recommended APU Battery Charging Voltage Decal, P/N 222-075-088-101, Installation of
TB 222-80-11	Rev B	28-Aug-95	Controllable Landing Light, P/N 45-0128-3, Alternate Lamp Authorization of
TB 222-81-12	Basic	20-Jan-81	Forward Fairing Doors, P/N 222-061-822-105 and -106, Stiffening of
TB 222-81-13	Basic	20-Jan-81	Transmission Cowl Assemblies, P/N 222-061-819-101, Stiffening of
TB 222-81-14	Basic	20-Jan-81	Avionics Bay Door Moisture Seal, Modification of
TB 222-81-15	Basic	12-Feb-81	Walking Beam Bearing P/N 222-310-461-001, Lubrication Interval Change and Inspection of
TB 222-81-16	Basic	12-Feb-81	Cable Assembly, P/N 222-301-009-101, Modification to P/N 222-301-009-103
TB 222-81-17	Basic	12-Feb-81	Swashplate Triplex Bearing Set, P/N 222-310-476-101, Installation of
TB 222-81-18	Basic	11-Feb-81	Hydraulic Tube Assembly, P/N 222-080-511-101, Replacement of
TB 222-81-19	Basic	12-Feb-81	Transmission Pan Gasket, P/N 222-031-591-101, Addition of
TB 222-81-20	Basic	12-Feb-81	Fuel Filler Assembly, Modification of
TB 222-81-21	Basic	13-Feb-81	Transmission Breather Filler Cap, and Chip Detector, Change of
TB 222-81-22	Basic	3-Mar-81	Swashplate and Lever Assembly Nylatron Washer, P/N 222-010-499-101, Installation of
TB 222-81-23	Basic	4-Mar-81	Sleeve, Protective Coil, Installation of
TB 222-81-24	Basic	23-Mar-81	Crew Doors, P/N 222-031-120-101 and -102, Drain Holes, Addition of
TB 222-81-25	Basic	25-Mar-81	Switch Bracket, Ozone P/N 3969005, on Landing Gear Downlock Actuators, P/N 222-336-001-105, Rework of

222/B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 222-81-26	Basic	8-Apr-81	Landing Gear Proximity Switches, Moisture Penetration, Protection of
TB 222-81-27	Basic	8-Apr-81	Nodal Beam Flexure Attach Bolts, Inspection of
TB 222-81-28	Basic	9-Apr-81	Replacement of the Avionics Compartment Door Hinge Lanyard and Insulation of Heated Windshield De-Ice Relay Terminals
TB 222-81-29	Basic	15-Apr-81	Swashplate and Fiction Collect Boot Clamps, P/N NH102305-0400, NH102305-0575 and NH102305-0925, Replacement of
TB 222-81-30	Basic	20-Apr-81	Tail Rotor Crosshead Bearing Housing, P/N 222-012-716-005, Grease Seal, Correct Installation of
TB 222-81-31	Basic	22-Apr-81	Emergency Floats Electrical System Float Arm Switch Guard, Re-orientation of
TB 222-81-32	Basic	30-Apr-81	Tail Rotor Hub and Blade Assembly Titanium Bolts, P/N NAS677V32D, NAS677V56D, NAS677V58D, and NAS677V60D, Replacement of
TB 222-81-33	Basic	30-Apr-81	Hydraulic Actuator Support Bracket Wear Pads, Installation of
TB 222-81-34	Basic	2-May-81	Actuator, Centering P/N OMP3970-2, Operating Pressure, Change of
TB 222-81-35	Basic	15-May-81	Frahm Damper Assembly P/N 222-031-285, Modification of
TB 222-81-36	Rev A	8-Feb-82	Landing Gear Control Panel Assembly, Replacement of
TB 222-81-37	Rev A	30-Oct-81	Crew Seat, P/N 222-020-810-103, -105, and -107, Modification of
TB 222-81-38	Rev A	6-Oct-81	Flexure Restraint Arm Assembly, P/N 222-031-611-105, L.H. and -107, R.H., Inspection of
TB 222-81-39	Basic	20-Aug-81	Pilot/Copilot, Pitot/Static Heater Circuit Harness and Circuit Breaker, Replacement of
TB 222-81-40	Basic	1-Sep-81	Filler, Auxiliary Fuel Tank, Modification of
TB 222-81-41	Rev A	5-May-82	Swashplate Drive Link Assy, P/N 222-010-460-101, Replace-ment of
TB 222-81-42	Rev A	3-Sep-81	Copilot Emergency Light-Overhead Console Installation of
TB 222-81-43	Basic	16-Sep-81	VHF NAV 2 (Proline) 26 VAC Circuit Breaker, Replacement of
TB 222-81-44	Basic	19-Oct-81	Lower Strobe Light Rework, P/N 30-0504-21
TB 222-82-45	Basic	16-Feb-82	Bleed Air Tube Assembly, P/N 222-060-251-101, Support Clamps, Addition of
TB 222-82-46	Basic	31-Mar-82	Pilot and Copilot Directional Control Pedal Assembly, P/N 222-001-760-001 and -003, Modification of
TB 222-82-47	Basic	13-Apr-82	Nose Wheel Halves, P/N 222-336-004, Joining Bolts, P/N AN4-22A, and Nuts, P/N AN365-428, Replacement with Bolts, P/N NAS604-30, and Nuts, P/N MS21042L4
TB 222-82-48	Basic	1-Jun-82	Radar Nose Door, P/N 222-031-107, Rework to Provide Additional Stiffness to

222/B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 222-82-49	Rev A	16-Jan-85	Swashplate Ball Sleeve Assembly, P/N 222-010-405-005/-113/-115, Added Inspection Criteria and Improvement of
TB 222-82-50	Basic	28-Oct-82	Engine Air Inlet Duct Assy, P/N 222-062-211, Screen Attachment Rivet Inspection and Replacement of
TB 222-83-51	Basic	11-Feb-83	Tail Skid Attach Casting, P/N 222-035-206-101, Repair of
TB 222-83-52	Basic	21-Mar-83	Drive Hub and Walking Beam, Protection of
TB 222-83-53	Basic	5-Apr-83	Nodal Beam Left Side Aft Support Fitting, P/N 222-031-520-105, Replacement of
TB 222-83-54	Rev A	17-May-83	Driveshaft Assembly, P/N 222-044-006-103, Upgrade to Springless Configuration
TB 222-83-55	Basic	25-Apr-83	Tail Rotor Boost Cylinder Support Bracket, P/N 222-031-471-001, Inspection and Replacement of
TB 222-83-56	Basic	12-May-83	Hydraulic System Reservoir Assembly, P/N 222-080-003-1, Modification of
TB 222-83-57	Basic	22-Jul-83	Nose Wheel Well, P/N 222-031-110-(All), Inspection and Modification of
TB 222-83-58	Basic	15-Aug-83	Fluorescent Lighting and RPM Limit Detector, Interference of
TB 222-83-59	Basic	1-Sep-83	Hydraulic Installation - System PCI, PCII, and Brakes, Modification of
TB 222-83-60	Basic	23-Sep-83	Door Hinge Fitting, P/N 222-031-131-101 and -102, Installation - Inspection and Modification of
TB 222-83-61	Rev A	1-Nov-83	Lower Anti-Collision Light Ground Strap, P/N 222-075-206-101, Installation of
TB 222-83-62	Basic	24-Oct-83	Swashplate Drive Link, Load Reduction
TB 222-83-63	Basic	9-Dec-83	Tail Rotor Gearbox Output Sleeve Lug Corrosion Protection, Increase of
TB 222-84-64	Basic	25-Jan-84	222 Main Input Shaft, Balance of
TB 222-84-65	Basic	9-Feb-84	Main Transmission, P/N 222-040-003, 600 Hour Special Internal Inspection, Deletion of
TB 222-84-66	Rev A	2-Aug-90	Main Transmission, P/N 222-040-003, Commonality, Modification of
TB 222-84-67	Basic	28-Feb-84	Copilot Torque Indicator Circuit Ground Wires, Addition of
TB 222-84-68	Basic	13-Mar-84	Voltage Regulator, P/N 222-375-060-105, Replacement of
TB 222-84-69	Rev A	4-May-84	Landing Gear Warning Horn Audio Coupler, Addition of
TB 222-84-70	Basic	8-Jun-84	RPM Limit Detector, P/N 222-375-009-103, Replacement of
TB 222-84-71	Basic	16-Jul-84	Directional Control Tube, P/N 222-001-006-101, Wear Sleeve Replacement
TB 222-84-72	Basic	16-Jul-84	Directional Control Tube, P/N 222-001-088-101, Wear Sleeve Replacement

222/B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 222-84-73	Basic	27-Jul-84	Caution Annunciator Panel, P/N 222-375-010-107, -117, -119, and -123, Modification of
TB 222-84-74	Basic	10-Aug-84	Weight Arm, P/N 222-031-611-105 and -107, or -109 and -111, Cam Arm, P/N 222-031-639-105 and -107, Installation of
TB 222-84-75	Basic	5-Sep-84	Modification to Prevent Transmission Input Quill Assembly Seal Housing(s) from Draining onto Nodal Beam Arm(s)
TB 222-84-76	Basic	5-Nov-84	Voltage Regulator, P/N 222-375-060-103, -105, -111, Replacement of
TB 222-84-77	Rev A	6-Jun-85	Engine Bleed Air System, Modification of (222)
TB 222-85-78	Basic	9-Jan-85	Hydraulic System Modules, P/N 222-380-020-001, Bracing of
TB 222-85-79	Rev A	6-Jun-85	Engine Bleed Air System, Modification of (222B)
TB 222-85-80	Basic	21-Jan-85	Swashplate Boot, P/N 222-010-494-101, Replacement of
TB 222-85-81	Basic	12-Mar-85	Case Assembly, Gearshaft Support, P/N 222-040-062, Repair of
TB 222-85-82	Basic	15-Aug-85	Main Rotor Tie-Down, Provision of
TB 222-85-83	Basic	1-May-85	Tail Rotor Blade, P/N 222-016-001-101/-107, Root Closure Repair
TB 222-85-84	Basic	10-Jun-85	Swashplate and Levers Assemblies, P/N's 222-010-400-013/-105/-107/-111/-115/-117/-119, Ball Sleeve Assembly Replacement
TB 222-85-85	Basic	1-Nov-85	Tail Rotor Blade, P/N 222-016-001-101/-107, Improved Visibility Paint Scheme
TB 222-85-86	Basic	1-Nov-85	ANS-31C RNAV System Kit, P/N 222-705-018-101, Sneak Path Diode, Addition to
TB 222-85-87	Basic	11-Nov-85	Aft Fairing, P/N 222-061-824-101 and -133, and Ejector Assembly, P/N 222-062-216-101, Modification of
TB 222-86-88	Basic	23-Jan-86	Dynamic Stop, P/N 222-010-156-101, Removal
TB 222-86-89	Basic	14-Feb-86	Lycoming LTS101-650C-2/-3/-3A Engine, Scavenge Debris Monitor Modification, Electrical Interface of
TB 222-86-90	Basic	26-Mar-86	Retainer Secured (Push Out) Passenger Compartment Windows
TB 222-86-91	Basic	22-May-86	Hydraulic System Installation, PCI and PCII, Replacement of 2014/2024 Aluminum Alloy Flareless Tube Fittings
TB 222-86-92	Basic	5-Aug-86	Roof Assembly, P/N 222-031-501, Inspection and Modification of
TB 222-86-93	Basic	3-Nov-86	Bleed Air Heater Installation, Modification of Air Distribution System
TB 222-86-94	Basic	6-Nov-86	Lever Assembly, P/N 222-012-715-001, Modification of
TB 222-86-95	Basic	25-Nov-86	Directional Hydraulic Actuator Support, P/N 222-001-730-005, Modification of
TB 222-87-96	Basic	5-Feb-87	Engine Inlet Screen Assembly, P/N 222-062-215, Inspection of

222/B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 222-87-97	Basic	26-Feb-87	Caution Annunciator Panel, P/N 222-375-010-107, -117, -119, -121, -123, -125, -127, -129, Ref. Midland Ross/Division Service Bulletin 80-0500-33-003, Rev. A
TB 222-87-98	Basic	12-Jun-87	Main Driveshaft Assemblies, Calendar Inspection, Addition of
TB 222-87-99	Basic	17-Jun-87	Main Transmission, P/N 222-040-003-111, and Tail Rotor Gearbox, P/N 222-042-001-007, Increase in Time-Between-Overhaul
TB 222-87-100	Basic	25-Jun-87	Fire Detection System, Component Changes
TB 222-87-101	Basic	13-Aug-87	Wing to Fuselage Attach Bolts, Adding Washer to Improve Clamping
TB 222-87-102	Basic	14-Aug-87	Cyclic and Collective Control System Balancing Springs, Adjustment Procedures
TB 222-87-103	Basic	17-Aug-87	Markings Installations, P/N 222-020-610-105, -111, -115, and -119, Tail Rotor Hazard Warning Decals, Addition to
TB 222-87-104	Basic	18-Aug-87	Voltage Regulator, P/N 222-375-060-113, Addition of Bonding Strap
TB 222-87-105	Rev A	23-Apr-92	Hydraulic System Reservoirs, Installation of Elbow with Filter Screen and Removal of Baffle
TB 222-87-106	Rev A	20-Oct-87	Nodal Beam Weight Arm Cam Bearing, Provision for Lubrication
TB 222-87-107	Basic	18-Sep-87	Hydraulic System Modules, Installation of Bracing
TB 222-87-108	Basic	24-Sep-87	Rotor Brake Assembly, Modification of P/N 4000424-1
TB 222-87-109	Basic	20-Oct-87	Heated Birdproof Windshields, Interior Surface Waxing to Enhance Service Life
TB 222-87-110	Basic	9-Dec-87	Swashplate Drive Link Bolt, P/N 20-057-9-95D, Torque Increase
TB 222-87-111	Basic	16-Dec-87	Main Rotor Trunnion Bolts, P/N NAS626-8, Installation and Retorque Inspection
TB 222-87-112	Basic	21-Dec-87	Transmission Stop Water Shield, Installation of
TB 222-88-113	Basic	8-Feb-88	Addition of Identification Decal on Aircraft Exterior
TB 222-88-114	Rev A	18-Nov-91	Right Side Roof Beam, P/N 222-031-583-102, Removal and Replacement
TB 222-88-115	Basic	27-Jun-88	Hydraulic Pump, P/N 222-380-009-103, (Abex Model AP1V-47, P/N 65132) Replacement of External Driveshaft
TB 222-88-116	Basic	29-Sep-88	Flight Control Actuators, P/N 222-382-001-101 and 222-382-002-101 Incorporation of Dual Retention of Servo Linkage Operational Low-Gain Control Valve Assembly for the 222-382-002-101
TB 222-89-117	Basic	15-Feb-89	Improved Anti-Collision Light Installation
TB 222-89-118	Basic	2-May-89	Prevention of Hydraulic System Flexible Hose Chafing
TB 222-89-119	Basic	12-May-89	Copilot Cyclic Stick Quick-Disconnect Modification

222/B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 222-89-120	Rev B	4-Aug-00	Main Rotor Hub Assembly, P/N 222-011-101-103, -105, -107, -109 and P/N 222-012-101-103 and -107 Configuration Change and Upgrade
TB 222-89-121	Basic	2-Jun-89	Main Rotor Blades, P/N 222-015-500-105/-107 and -111, and P/N 222-015-600-101/-105 and -107, Retirement Life, Increase of
TB 222-89-122	Basic	6-Jun-89	Mast Assembly P/N 222-040-002, Configuration Change And Upgrade
TB 222-89-123	Basic	6-Jun-89	Main Driveshaft Assembly, P/N 222-044-006, Configuration Change and Upgrade
TB 222-89-124	Rev C	18-Apr-06	Swashplate and Levers Assemblies P/N 222-010-400, Configuration Change and Upgrade
TB 222-89-125	Basic	23-Jun-89	Main Rotor Pendulum Damper Shaft P/N 222-011-113-101, Modification of
TB 222-89-126	Basic	27-Sep-89	Ten Place Seating Configuration, Three Main Forward Facing-Passenger Seat Assembly, P/N 222-020-703-101, Seat Folding Instructions, Addition of
TB 222-89-127	Rev A	10-Aug-90	Main Transmission P/N 222-040-003-111, and Tail Rotor Gearbox, P/N 222-042-001-007, Increase in Time-Between-Overhaul
TB 222-90-128	Basic	28-Feb-90	Inspection and Modification of Tailpipe Assembly P/N 222-063-307-101, -102, -107, -108, -141, and -142 to Accommodate LTS 101-650 and 750 Engine Power Turbine Rotor Mechanical Retention System
TB 222-91-129	Basic	15-Jan-91	Roof Installation P/N 222-031-501 ALL, Modification of
TB 222-91-130	Basic	5-Feb-91	Introduction of P/N 222-031-662-105/-107 Lift Link Rod End Bearing Assemblies
TB 222-91-131	Basic	27-Sep-91	Replacement of Horizontal Stabilizer Auxiliary Fin Attachment Screws, P/N AN525-10R7
TB 222-92-132	Basic	6-May-92	Oil Cooler Blower Assembly, 365-515-101 and -103, Modification and Upgrade to The -105 Configuration (Torlon Drive)
TB 222-92-133	Basic	14-May-92	Collective Lever Assembly P/N 222-010-497-105 and Cyclic Lever Assembly P/N 222-010-408-109 Modification of
TB 222-92-134	Basic	14-May-92	Main Rotor Flight Control Actuators P/N 222-382-001-101/-103 Modification of
TB 222-92-135	Basic	27-Aug-92	Trunnion Shimming Procedure Tail Rotor Hub, Alternate Method
TB 222-93-136	Basic	24-Nov-93	Swashplate Cyclic Link, P/N 222-010-419-101/-106, Upgrade
TB 222-93-137	Basic	24-Nov-93	Standby Attitude Indicator, Lighting Level, Decrease of
TB 222-94-138	Basic	17-Feb-94	Tailboom Reinforcement Doubler Installation

222/B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 222-94-139	Basic	14-Mar-94	Emergency Float Arm Annunciator Switch, P/N 10648BH1 - 19, Relocation of
TB 222-94-140	Basic	6-May-94	Maintenance Step Installation, Roof Right Hand Side
TB 222-94-141	Basic	11-May-94	Introduction of P/N 230-366-001-101 Drain Valve, Upper Auxiliary Fuel Kit Provisions P/N 222-706-204-103/-107
TB 222-94-142	Rev A	16-Oct-95	Tail Rotor Controls, Improvement
TB 222-94-143	Basic	23-May-94	Power Trim Check (Topping), 6 Percent Delta Topping Stop Assembly P/N LTCT 12725-01, Introduction of
TB 222-94-144	Basic	29-Sep-94	Directional Control Tube, P/N 222-001-006-101 and 222-001-088-101, -107 and -109, Modification of
TB 222-94-145	Basic	14-Nov-94	Start Relay (1K3, 1K4), Transient Current Surges, Suppression of
TB 222-94-146	Basic	4-Nov-94	Bulkhead Sta. 270 Reinforcement Doubler Installation
TB 222-94-147	Basic	28-Nov-94	Rotor Brake Assembly, Introduction of Stainless Steel Piston
TB 222-94-148	Basic	12-Dec-94	Main Rotor Hub and Blades Assembly, Chordwise Balance Capability Increase
TB 222-94-149	Basic	23-Dec-94	Hydraulic System Reservoirs, Installation of Baffle
TB 222-95-150	Basic	1-May-95	Baggage Compartment Door Handle, Modification of
TB 222-95-151	Basic	19-Jun-95	External Power (2K1), Bus Interconnect (2K2), No. 1 Generator (2K5) and No. 2 Generator (2K6) Contactors, Upgrade of
TB 222-95-152	Basic	11-Sep-95	Flapping Springs P/N 222-310-117-105, Introduction of
TB 222-95-153	Basic	20-Nov-95	Drive Shaft Outer Coupling, P/N 222-044-672-101 and Inner Coupling P/N 222-044-607-003, Corrosion Protection of
TB 222-96-154	Basic	5-Aug-96	Tail Rotor Drive Shaft Hanger Assembly P/N 222-044-003-101/-103/-105 and -107, Modification of
TB 222-96-155	Basic	30-Aug-96	Improved Passenger Door Lock Switch, Installation
TB 222-98-156	Rev A	6-Jul-98	Vertical Fin Assembly, Installation Modification
TB 222-98-157	Basic	3-May-98	BHT-222/222B-MM-1, Re-Issue; Date 02-12-98
TB 222-98-158	Basic	8-Jun-98	Horizontal Stabilizer Slat Installation P/N 222-035-003-101/-103, Introduction of
TB 222-98-159	Basic	17-Sep-98	Swashplate Drive Assembly, Configuration Change and Upgrade
TB 222-98-160	Rev A	14-Dec-98	Main Rotor Flight Control Actuator, P/N 222-382-001-107, Introduction of
TB 222-99-161	Basic	20-Oct-99	Tail Rotor Gearbox P/N 222-042-001-007, -101 and -103 Configuration Change and Upgrade
TB 222-00-162	Basic	1-May-00	Transmission Longitudinal Restraint Installation Retrofit
TB 222-00-163	Basic	1-May-00	Transmission Assembly P/N 222-040-003-003, -103, -109, -111, -119 and -123 Configuration Change and Upgrade
TB 222-00-164	Basic	28-Jul-00	Lycoming LT 101 Engine, Introduction of Oil Wetted Starter Gear Drive Splines

222/B TECHNICAL BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 222-00-165	Basic	23-Oct-02	Honeywell LTS 101 Engine, Introduction of Flexible Fuel Manifold Assembly
TB 222-00-166	Basic	23-Oct-02	Honeywell LTS 101 Engine, Introduction of Flexible Fuel Manifold Assembly
TB 222-01-167	Basic	19-Jan-01	Main Driveshaft Assembly P/N 222-044-006-111, Introduction of
TB 222-01-168	Basic	16-Apr-01	Fuel Vent Assembly P/N 430-060-004-101, Introduction of
TB 222-02-169	Basic	25-Mar-02	Transmission Top Case Bushings P/N 222-040-326-101, Replacement of
TB 222-02-170	Basic	14-Oct-02	Improved Nose Frahm Bulkhead Support Assemblies, Installation of
TB 222-03-171	Basic	11-Jun-03	Fuel Valve Switch, Rewiring of
TB 222-04-172	Basic	28-Oct-04	Bulkhead STA. 270, Improvement of
TB 222-05-173	Basic	8-Dec-05	Landing Gear Actuator P/N 222-336-001-015, Introduction of
TB 222-06-174	Rev A	13-Feb-07	Tail Rotor Blades 222-016-001-139 and -141 and Tail Rotor Yoke Assembly 222-012-702-005, -113 and -117, Introduction of
TB 222-08-175	Basic	12-Sep-08	Main Rotor Mast Assembly (Torquemeter) Seven Calendar Year Inspection, Increase of
TB 222-09-176	Basic	21-Apr-09	Tail Rotor Blade P/N 222-016-001-123, -123M, -127, -127M, -131, -135,-139M and -141M Reworked per ASB 222-04-100, Inspection of

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
--------------------	-----------------------	-------------	----------------