



A Textron Company

ALERT SERVICE BULLETIN

430-14-54

10 November 2014

Revision A, 6 January 2015

MODEL AFFECTED: 430

SUBJECT: GOODRICH EXTERNAL HOIST

HELICOPTERS AFFECTED: Serial number 49001 and subsequent with Goodrich 42325 Series Hoist System installed.

COMPLIANCE: See attached Vendor Bulletin ASB 44301-10-18, Rev 2. It is the responsibility of the owner to make sure that the most current version of the Goodrich ASB 44301-10-18 is consulted. Revision A of this bulletin attaches the most recent version of ASB 44301-10-18, Rev 2 dated October 22, 2014.

DESCRIPTION:

The purpose of this bulletin is to achieve complete distribution of the attached vendor bulletin to the current affected model distribution list on record by Bell Helicopter.

APPROVAL:

See attached Vendor Bulletin ASB 44301-10-18, Rev 2 dated October 22, 2014.

CONTACT INFO:

For any questions regarding this bulletin, please contact:

Goodrich Corporation
Sensors & Integrated Systems
Brea, CA 92821
Phone: 714-984-1461