



**ALERT
SERVICE
BULLETIN
INDEX**

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

***Bell* helicopter**
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

15 SEPTEMBER 2011

214ST ALERT SERVICE BULLETIN INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214ST-82-1	Basic	16-Sep-82	Tail Rotor Hub Assembly, P/N 214-010-800-101, Modification and Inspection of
ASB 214ST-82-2	Basic	1-Oct-82	Tail Rotor Installation, P/N 214-010-800-101, Modification of
ASB 214ST-82-3	Inactive	10-Aug-84	Upper Left Hand Aft Fuselage Tail Boom Attach Longeron, P/N 214-031-431-101, Inspection and Modification of
ASB 214ST-82-4	Basic	19-Nov-82	Inspection Door Assy, P/N 214-030-325-003, Replacement with Door Assy, P/N 214-030-325-103
ASB 214ST-82-5	Basic	18-Jan-83	Dual Hydraulic Servo Actuator Assembly, P/N 214-076-161-101, Actuator Mount Nut Torque, Inspection of
ASB 214ST-83-6	Rev A	28-Feb-83	Tail Rotor Blade, P/N 214-015-700-103, Inspection/Rework of
ASB 214ST-83-7	Basic	20-May-83	Emergency Float Kit, Forward Float(s) Installation, Improved Abrasion Protection Between Floats, P/N 214-052-200-101/-102 and Inflation Fittings
ASB 214ST-83-8	Basic	19-Aug-83	Engine Fire Extinguishing Bottles, P/N 214-069-980-101, Squib Discharge Valve, Identification and Wiring, Clarification of
ASB 214ST-83-9	Basic	31-Aug-83	Swashplate and Support Assembly, P/N 214-010-500-101, Lubrication and Inspection of
ASB 214ST-83-10	Basic	12-Sep-83	Main Rotor Spindle, P/N 214-010-103 (All Dash Numbers), Inspection of
ASB 214ST-83-11	Rev A	1-Dec-83	Tailboom Ballast, P/N 214-031-661-101, and Provisions, Modification of
ASB 214ST-83-12	Basic	3-Nov-83	Tail Rotor Blade Retention/Feathering Bearing Bolt, P/N 20-071-8-49H, Torque Verification
ASB 214ST-83-13	Basic	28-Nov-83	Main Rotor Grip Assembly, P/N 214-010-104-113, Retirement Life, Reduction of
ASB 214ST-84-14	Rev A	10-May-84	Tail Rotor Pitch Change Tube Assembly, P/N 214-010-816-101, Inspection of
ASB 214ST-84-15	Basic	4-Jan-84	One Time Inspection of Electrical Cable for Evidence of Chafing
ASB 214ST-84-16	Basic	27-Jan-84	Nose Landing Gear Wheel Assembly, P/N 222-036-002-101, Inspection and/or Replacement of
ASB 214ST-84-17	Basic	12-Mar-84	Collective Sleeve, P/N 214-010-411-001, With Serial Number A-19 Prefix, Inspection of (See ASB 214ST-85-30)
ASB 214ST-84-18	Basic	9-Mar-84	Pylon Support Assembly, P/N 214-031-810-107, Modification of
ASB 214ST-84-19	Basic	16-Apr-84	Inspection of Locking Plates, P/N's 214-010-231-101 and 214-010-232-101, for Proper Installation
ASB 214ST-84-20	Basic	9-May-84	Tail Rotor Pitch Change Tube Assembly, P/N 214-010-816-101, and Bearing Set, P/N 214-010-714-001, Replacement of
ASB 214ST-84-21	Basic	23-Jul-84	Scissors Drive Plate, P/N 214-010-413-105, Inspection of
ASB 214ST-84-22	Basic	24-Jul-84	Collective Lever, P/N 214-010-474-109/-113, Retirement Life, Reduction of

214ST ALERT SERVICE BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214ST-84-23	Basic	30-Aug-84	Emergency Flotation Reservoir, P/N 222-325-021-101, Decal (WARNING), P/N 31-023-8B, and Decal (CAUTION), P/N 31-023-9B, Installation of
ASB 214ST-84-24	Basic	30-Aug-84	Main Rotor Spindle, P/N 214-010-103-003, Retirement Life, Reduction of
ASB 214ST-84-25	Rev A	29-Nov-84	Swashplate Duplex Bearing, P/N 214-010-430-001, Replacement of
ASB 214ST-84-26	Basic	10-Dec-84	Tail Rotor Crosshead Bearing Set, P/N 214-010-856-101, Inspection and Replacement of
ASB 214ST-85-27	Basic	15-Mar-85	One Time Inspection of Engine Aft Firewall Disconnects, 22P3, 22J23, 22P24, and 22J24, for Proper MIL Qualified Connector Part Numbers
ASB 214ST-85-28	Basic	28-May-85	Instrument Current Limiter, P/N 531-1, Reconfiguration of
ASB 214ST-85-29	Basic	3-Sep-85	Drag Brace Assembly, P/N 214-010-113-001/-003, Inspection of (See ASB 214ST-86-35)
ASB 214ST-85-30	Basic	7-Nov-85	Collective Sleeve, P/N 214-010-411-001/-003 With Serial Number A-19 Prefix and A-1 Thru A-10, Reinspection of
ASB 214ST-85-31	Basic	7-Nov-85	Main Rotor Pitch Link Assembly, P/N 214-010-410 (All Dash Numbers), Inspection of
ASB 214ST-85-32	Rev A	20-Feb-86	Main Rotor Spindle Bolt Assembly, P/N 214-010-183-101, Inspection, Replacement, and Retirement Life Reduction
ASB 214ST-86-33	Basic	20-Feb-86	Collective Sleeve Assembly, P/N 214-010-411-001/-003, Introduction of
ASB 214ST-86-34	Rev B	23-May-88	Main Rotor Yoke, P/N 214-010-105-001, Reduction of Retirement Life, and Introduction of Main Rotor Hub Assembly, P/N 214-010-100-183
ASB 214ST-86-35	Basic	31-Mar-86	Drag Brace Assembly, P/N 214-010-113-001, Replacement of
ASB 214ST-86-36	Basic	11-Jun-86	Inspection Interval of Locking Plate, P/N 214-010-232-101, for Condition and Proper Installation, and Torque Check of Collective Hub Nut, P/N 214-010-417-001
ASB 214ST-86-37	Rev A	3-Nov-86	Scissors and Sleeve Locking Plates, P/N 214-010-231-101 and P/N 214-010-232-101, Replacement of Retirement Life Reduction
ASB 214ST-87-38	Basic	17-Feb-87	Tail Rotor Crosshead, P/N 214-010-806-101, and Counterweight Bellcrank, Bearings, P/N 214-010-774-001, Inspection of
ASB 214ST-87-39	Rev A	4-Oct-88	Tail Rotor Gearbox Main Case Assembly, P/N 214-040-409-109/-113, Inspection of
ASB 214ST-87-40	Basic	17-Sep-87	Tail Rotor Intermediate Gearbox, P/N 214-040-009-101, Inspection of

214ST ALERT SERVICE BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214ST-87-41	Rev A	4-Nov-87	Engine Fuel Valve Electrical Connectors, P/N MS3456W14S5S, One Time Inspection of
ASB 214ST-88-42	Basic	14-Mar-88	Wheeled Landing Gear Kit, P/N 214-706-118-107, Beam and Fitting Assemblies, Serialization of
ASB 214ST-88-43	Basic	16-Mar-88	Wheeled Landing Gear Kit, P/N 214-706-118-101, -103, and -105, Main Gear Beam Assy and Oleo Shock Strut Attach Bolt, P/N NAS6214-33D, 40D, 44D
ASB 214ST-88-44	Basic	17-Mar-88	Drag Brace Assembly, P/N 214-010-113-105, Inspection of
ASB 214ST-88-45	Basic	25-Apr-88	Replacement of Cylinders on Charged Cylinder Assemblies, P/N 130101-400
ASB 214ST-88-46	Basic	31-May-88	Main Rotor Drag Brace Assembly, P/N 214-010-113-105, Inspection of
ASB 214ST-88-47	Rev A	20-Feb-89	Drag Brace Assembly, P/N 214-010-113-105, Replacement of
ASB 214ST-89-48	Rev A	1-Aug-89	Aeroquip 601 Hose Assemblies, One-Time Inspection and Replacement
ASB 214ST-89-49	Rev B	10-Apr-90	Transmission External Oil Filter Bracket, P/N 214-040-599-101/-111, Replacement of
ASB 214ST-90-50	Basic	15-Jan-90	Breeze-Eastern Cargo Hooks P/N 17138-3, Warning Plate, Addition of (See ASB 214ST-93-61)
ASB 214ST-90-51	Basic	15-Jan-90	Main Rotor Flight Control System Bolts, Inspection of
ASB 214ST-90-52	Basic	5-Feb-90	Main Rotor Pylon Controls Installation, Bolt and Washer Replacement of
ASB 214ST-91-53	Basic	15-Jan-91	Safety of Flight Message-Vertical Fin Forward Spar Crack (See ASB 214ST-92-56)
ASB 214ST-91-54	Basic	22-Oct-91	AFCS-SCAS Actuator Assemblies P/N 214-001-540-107/-113 Roll; P/N 214-001-540-109/-115 Pitch; P/N 214-001-540-111/-117 Yaw; Centering Spring P/N 214-001-552-101, Inspection and Functional Test of
ASB 214ST-91-55	Basic	11-Dec-91	Tail Rotor Crosshead P/N 214-010-806-101, Inspection of
ASB 214ST-92-56	Basic	4-Mar-92	Tailboom Fin Assembly, P/N 214-021-002-ALL, Cold Expansion of Selected LH Forward Spar Fastener Holes
ASB 214ST-92-57	Basic	1-May-92	Tail Rotor Crosshead, P/N 214-010-806-101, Replacement of
ASB 214ST-92-58	Basic	27-Oct-92	Tailboom Assembly, P/N 214-030-003-ALL, Modification to Prevent Thermal Buckling of the Top Skin
ASB 214ST-92-59	Rev A	19-May-93	Spider, P/N 214-040-080-101, Establishment of a Retirement Life, and Method of Calculating Retirement Life (See ASB 214ST-94-68)
ASB 214ST-93-60	Rev A	21-Apr-93	Improved Rotor Brake Quill, P/N 209-040-173-103, Installation of
ASB 214ST-93-61	Rev A	24-May-94	Breeze-Eastern Cargo Hook Customer Advisory Bulletin No. CAB-100-41 and Customer Service Bulletin No. CSB-148

214ST ALERT SERVICE BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214ST-93-62	Rev A	8-Oct-99	Emergency Float System Pneumatic Hose Assembly Replacement and Calendar Life Assignment
ASB 214ST-93-63	Rev A	4-Mar-94	Main Driveshaft and Tail Rotor Drive System Grease Lubricated Couplings, Overtemperature Indicators, Installation of
ASB 214ST-94-64	Basic	19-Jan-94	Additional Clamping Required Between Hydraulic Lines and Generator Feeder Cables to Maintain a Fixed Separation and to Eliminate Chafing
ASB 214ST-94-65	Basic	15-Jun-94	Air Crusiers Company Service Bulletin No. 903-25-1
ASB 214ST-94-66	Basic	7-Nov-94	Upper Planetary Carrier, P/N 214-040-077-007 and -101, Change in Retirement Life and Method of Determination
ASB 214ST-94-67	Basic	7-Nov-94	Main Rotor Mast, P/N 214-040-090-109 and -121, Change of Retirement Life and Method of Determination
ASB 214ST-94-68	Basic	7-Nov-94	Spider, P/N 214-040-080-101, Change in Retirement Life and Method of Determination
ASB 214ST-94-69	Basic	7-Nov-94	Pillow Block Bearing Bolts, P/N 20-057-12-48D, -50D, Change of Retirement Life and Method of Determination
ASB 214ST-94-70	Basic	7-Nov-94	Trunnion, P/N 214-010-230-101, Change in Retirement Life and Method of Determination
ASB 214ST-95-71	Basic	12-Jan-95	Left Hand Upper Fuselage Longeron, P/N 214-031-431-103, -105, One Time Inspection
ASB 214ST-95-72	Basic	24-Jul-95	Tailboom Assembly P/N 214-031-003-111, Inspection and Modification
ASB 214ST-95-73	Basic	13-Nov-95	Left Hand Upper Fuselage Longeron Assembly, P/N 214-031-431-103 Replacement, and P/N 214-031-431-105 Cold Expansion of Selected Fastener Holes
ASB 214ST-96-74	Basic	28-May-96	Modification and Upgrade of Emergency Float Inflation Solenoid Valve, P/N 214-073-929-ALL, and Solenoid Valve Assembly, P/N 214-073-940-ALL
ASB 214ST-96-75	Basic	26-Aug-96	Tail Rotor Yoke Assembly P/N 214-011-802-105 and -111 Inspection and Installation of Tail Rotor Flapping Stop P/N 214-011-809-109
ASB 214ST-97-76	Basic	20-May-97	Swashplate Duplex Bearing, P/N 214-310-400-101, One Time Inspection of
ASB 214ST-97-77	Basic	4-Jun-97	Air Cruisers Company Service Bulletin No. 903-25-02
ASB 214ST-97-78	Basic	17-Jul-97	Self-locking Barrel Nut, P/N NAS577B-10A, One Time Inspection of
ASB 214ST-97-79	Basic	6-Oct-97	Air Speed Indicator P/N 214-175-299-105 and Vertical Speed Indicator P/N 212-070-239-003, Removal From Service
ASB 214ST-98-80	Basic	23-Feb-98	Triple Tachometer P/N 214-175-251-103, Removal From Service
ASB 214ST-99-81	Basic	5-Jul-99	Main Rotor Strap Pin, P/N 214-010-117-001, Recall of

214ST ALERT SERVICE BULLETIN INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214ST-00-82	Basic	12-Jul-00	Tail Rotor Crosshead P/N 214-010-806-105, One Time Inspection of
ASB 214ST-01-83	Basic	19-Jan-01	Magnetic Brake P/N 204-001-376-103, One Time Inspection of
ASB 214ST-06-84	Rev A	14-Sep-06	Tail Rotor Driveshaft Hanger Assembly Bearing,P/N 214-040-606-101, One Time Inspection
ASB 214ST-07-85	Basic	18-Oct-07	Cyclic Flight Control Bearing, P/N MS27643-4, One Time Inspection and Replacement Of
ASB 214ST-08-86	Rev B	14-Apr-09	P/N 214-030-606-103 Pylon Support Spindle Assembly, Reduction of Retirement Life and Establishment of an Alternate RIN Limit
ASB 214ST-09-87	Basic	11-Feb-09	Inspection/Change of Restraint System Assembly with Inertia Reel and Manual Lock Handle
ASB 214ST-10-88	Basic	10-Dec-10	Elevator and Directional Flight Control Bearings P/N MS27643-4; Inspection and Replacement of

BHT-214ST-ASB-INDEX

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
-------------	---------------	------	---------