



A Textron Company

INFORMATION LETTER

206-14-105

22 April 2014

**TO: All owners and operators of Model 206A/B helicopters**

**SUBJECT: HYDRAULIC ACTUATORS USABLE ON 206A/B MODELS**

This Information Letter is issued to inform owners/operators that the following servo actuators can be mixed and matched on all 206A/B helicopters S/N 4 through 550 having the **TB 206-82-78** accomplished, and S/N 551 through 4690.

<b>AUTHORIZED P/N</b>	<b>VENDOR P/N (ref)</b>
206-076-031-003	41000670
206-076-031-007	41000670-001
206-076-031-013	41000670-005/-005A
206-076-031-017	42C42641-1
206-076-031-021	41000670-007
206-076-031-023	42C42641-3
206-076-031-107 (1)	41000670-009
206-076-031-109	42C42641-9

Note 1: The 206-076-031-107 is the actuator currently available through Vista.

Originally, helicopters S/N 4 through 550 had a different actuator configuration calling for different linkages for support attachment. For questions regarding hydraulic actuators applicability for these specific helicopters S/N 4 through 550 not having the **TB 206-82-78** accomplished, refer to the BHT-206A/B-SERIES-IPB.

For any questions regarding this letter, please contact:

Bell Helicopter Product Support Engineering - Light Helicopters  
Tel: 450-437-2862 / 1-800-363-8023 / pselight@bh.com