



214ST OPERATIONS SAFETY NOTICE INDEX

MAY 17/2022

ERICKSON  **N**[®]
ERICKSON INCORPORATED
214ST OPERATIONS SAFETY NOTICE INDEX

THIS PAGE INTENTIONALLY LEFT BLANK



ERICKSON INCORPORATED
214ST OPERATIONS SAFETY NOTICE INDEX

214ST OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN 214ST-84-1	Basic	7-Nov-84	Swashplate Bearing Outer Race Rotation, P/N 214-010-430-001
OSN 214ST-86-2	Basic	19-May-86	Collective Hub Locking Plate, P/N 214-010-232-101
OSN 214ST-89-3	Basic	24-Jan-89	Investigation of Top Skin Separation on Model 214B Composite Main Rotor Blade
OSN 214ST-89-4	Basic	7-Feb-89	Transmission Oil Filter Bracket P/N 214-040-599
OSN 214ST-91-5	Basic	4-Oct-91	Model 214ST In-Flight Incident
OSN 214ST-92-6	Basic	8-Jan-92	Status of Bell 214ST Incident Investigation
OSN 214ST-94-7	Basic	5-May-94	Cyclic Stick/Crew Seat Interference
OSN 214ST-96-8	Basic	17-May-96	Tail Rotor Yoke -- Static/Dynamic Damage
OSN 214ST-99-9	Basic	21-Jun-99	Notice of Common Part Failure
OSN 214ST-08-10	Basic	9-May-08	Starter Engine Jaw Coupling Installation
OSN 214ST-22-11	Basic	07-Feb-22	Tail Rotor Crosshead Duplex Bearing and Counterweight Installation

ERICKSON  **N**[®]
ERICKSON INCORPORATED
214ST OPERATIONS SAFETY NOTICE INDEX

THIS PAGE INTENTIONALLY LEFT BLANK



ERICKSON INCORPORATED
214ST OPERATIONS SAFETY NOTICE INDEX

GENERAL OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-76-1	Basic	21-Jan-76	Use of Life Vests During Over-water Operations
OSN GEN-76-2	Basic	23-Jan-76	Helicopter Accidents Caused by Ground Handling Errors
OSN GEN-76-3	Basic	24-Sep-76	Use of Standard Hardware
OSN GEN-76-4	Basic	13-Sep-76	Heavy Lift, Aft Center of Gravity, Prolonged Hover, Cyclic Control Abuse
OSN GEN-76-5	Basic	13-Sep-76	Fuel Contamination
OSN GEN-76-6	Basic	18-Oct-76	Collective Minimum Friction
OSN GEN-76-7	NOT USED		
OSN GEN-76-8	Basic	22-Dec-76	Operation of Helicopters in Salt Laden Atmosphere
OSN GEN-77-1	Rev. A	3-Nov-77	Airworthiness of Aircraft Parts
OSN GEN-78-1	Basic	10-Jan-78	Maintenance of the Main Rotor Blade Inspection System (B.I.S.)
OSN GEN-78-2	Basic	5-May-78	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-78-3	Basic	13-Sep-78	Chadwick C-47 Electronic Weighing System, Load Cell Link P/N 47-40200-19
OSN GEN-78-4	Basic	11-Dec-78	Chaffed Oil Lines
OSN GEN-79-1	Basic	2-May-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-79-2	Basic	26-Nov-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-80-3	Basic	13-Feb-80	Cracked Main Rotor Blade, P/N 204-011-250 Series
OSN GEN-80-4	Basic	19-Jun-80	Rotating Control Bolts
OSN GEN-80-5	Basic	27-Jun-80	Enhancement of Crew and Passenger Safety During High Impact Landings
OSN GEN-80-6	Basic	27-Jun-80	Daily Inspection of Main Input Driveshafts
OSN GEN-80-7	Basic	24-Jul-80	Transporting Flammable Cargo
OSN GEN-81-8	Basic	22-Sep-81	Inspection of Tail Rotor Pitch Links
OSN GEN-82-9	Basic	6-Oct-82	Tail Rotor Driveshaft Curvic Couplings, Inspection, Maintenance
OSN GEN-83-10	Basic	1-Sep-83	Engine Compressor Washing
OSN GEN-85-11	Basic	6-Nov-85	Beware of "Certificate of Manufacture, Inspection and Conformance"
OSN GEN-87-12	Basic	13-May-87	FAA Airworthiness Directive 87-06-09 (Mechanical Products, Inc.)
OSN GEN-88-13	Reissue	5-May-92	Lines Extending from the Helicopter
OSN GEN-89-14	Basic	6-Dec-89	Bogus P/N 212-073-905-1 Pressure Gage, Emergency Floats
OSN GEN-91-15	Basic	29-Jul-91	Electromagnetic Compatibility (EMC) of Aircraft Wiring with Pyrotechnic Device and Cargo Hooks



ERICKSON INCORPORATED
214ST OPERATIONS SAFETY NOTICE INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-91-16	Basic	21-Aug-91	Airframe Structural Repair
OSN GEN-91-17	Basic	1-Oct-91	Main Driveshaft Assembly, Inspection of
OSN GEN-92-18	Basic	19-Mar-92	Proper Stowage of Miscellaneous Items in and Around the Flight Crew Compartment
OSN GEN-92-19	Basic	5-May-92	MS21042 Series Nuts Approved Vendors
OSN GEN-92-20	Basic	25-Jun-92	Use of Non-Conforming Floatbag Assemblies
OSN GEN-92-21	Basic	25-Jun-92	Lubricant P/N 204-040-755-005
OSN GEN-93-22	Basic	29-Jan-93	Main Rotor Vibration; Emphasis on Timely Investigation
OSN GEN-93-23	Basic	29-Jan-93	Maintenance/Overhaul Procedures
OSN GEN-93-24	Basic	1-Mar-93	Parts Authenticity and Traceability
OSN GEN-93-25	Basic	15-Dec-93	"Slingshot" Maneuvers in Heavy Lift Operations
OSN GEN-95-26	Basic	19-Jan-95	Aircraft Cleaning
OSN GEN-95-27	Basic	24-Mar-95	Tail Rotor Yoke (Flexure Style) Failure
OSN GEN-96-28	Basic	21-May-96	Transmission Spiral Bevel Gear Cracks
OSN GEN-96-29	Basic	18-Oct-96	Unapproved Tail Rotor Driveshaft Hanger Bearings
OSN GEN-97-30	Basic	27-Jan-97	Breeze-Eastern Customer Advisory Bulletin Number CAB-100-54
OSN GEN-97-31	Basic	1-May-97	Tail Rotor Hanger Bearings Maintenance
OSN GEN-02-32	Basic	2-May-02	Bogus Parts Tail Rotor Grips
OSN GEN-02-33	Basic	10-Oct-02	Maintenance/Overhaul Procedures
OSN GEN-02-34	Basic	22-Nov-02	Correct Procedure for Torquing Fasteners
OSN GEN-04-35	Basic	21-Sep-04	Cyclic Stick Grip Assembly
OSN GEN-06-36	Basic	17-Apr-06	Paint Application on Helicopter Faying Surfaces
OSN GEN-06-37	Basic	20-Jul-06	NAS 1291-7 and -8 Nut, Confirmation of Condition Upon Installation
OSN GEN-09-38	Basic	7-Apr-09	Bearings in Flight Controls
OSN GEN-09-39	RESERVED		
OSN GEN-09-40	Basic	16-Nov-09	Onboard Systems International Alert Service Letter Document no. 159-027-00.
OSN GEN-10-41	Basic	18-Jan-10	Honeywell Bendix/King Discrepant Databases for KLN35A/KLN 88/KLN 89/KLN 89B/KLN 90/ KLN 90A/KLN90B/KLN 94/KLX 100/KLX 135/ KLX 135A/KLN 900
OSN GEN-10-42	Basic	13-Dec-10	Use of Specified Hardware
OSN GEN-11-43	Rev. A	16-Sep-11	NAS1291 Nuts and NAS626 Bolts
OSN GEN-11-44	Basic	10-May-11	Defective Grease Fittings NAS516-1A
OSN GEN-12-45	Basic	20-Aug-12	Personnel Injuries While Working on Helicopters
OSN GEN-13-46	Basic	17-Dec-13	Fluid Lines Fretting Damage
OSN GEN-14-47	Basic	14-Jan-14	Lines or Cables Extending from Helicopter



ERICKSON INCORPORATED
214ST OPERATIONS SAFETY NOTICE INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-16-48	Basic	7-Jun-16	Helicopter Operations with Query: Field Elevation (QFE) Altimeter Settings
OSN GEN-17-49	Basic	12-Oct-17	Main Rotor Pitch Link Assembly
OSN GEN-20-50	Basic	07-Jul-20	Cockpit and Cabin Passenger Safety
OSN GEN-22-51	Basic	20-Jan-22	Potential 5G C-Band Wireless Broadband Interference with Radio (Radar) Altimeter

THIS PAGE INTENTIONALLY LEFT BLANK

