



**OPERATIONS
SAFETY
NOTICE INDEX**

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

19 SEPTEMBER 2011

222/B OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN 222-81-1	Basic	6-Feb-81	Walking Beam Bearing, Main Rotor Controls, Failure of
OSN 222-81-2	Basic	19-Feb-81	Helicopter Landing Attitude - Elevated Platforms
OSN 222-82-3	Basic	21-May-82	Main Rotor Blades, P/N 222-015-500-101, Report of Spar Crack
OSN 222-82-4	Basic	30-Jun-82	Nodal Beam Attach Fitting
OSN 222-82-5	Basic	23-Nov-82	Directional Control Hydraulic Servo Actuator Support Brackets Airworthiness 100 Hour Inspection
OSN 222-85-6	Basic	19-Apr-85	External Hoist Kit, P/N 222-899-110 (All Dash Numbers)
OSN 222-85-7	Basic	27-Jun-85	Model 222U Dual-Engine-Caused Shutdown
OSN 222-86-8	Basic	3-Jun-86	Main Rotor Blade Inspection
OSN 222-86-9	Basic	5-Dec-86	Engine Failure
OSN 222-86-10	Basic	22-Dec-86	Hydraulic Reservoir Baffle Inspection
OSN 222-87-11	Basic	30-Sep-87	Swashplate Drive Link, P/N 222-011-416-103
OSN 222-89-12	Basic	22-May-89	Broken Main Rotor Pitch Link Upper Bolt
OSN 222-90-13	Basic	14-Feb-90	Vertical Fin P/N 222-035-200-ALL and 222-035-220-ALL
OSN 222-92-14	Basic	11-May-92	Flapping Bearing, P/N 222-310-114-003,-105/-107/-109
OSN 222-92-15	Basic	2-Dec-92	Main Rotor Blades, P/N 222-015-600-105, Report of Spar Crack
OSN 222-94-16	Basic	6-Sep-94	Tail Rotor Pitch Link, Failure of
OSN 222-98-17	Basic	20-Mar-98	Tail Rotor Crosshead, P/N 222-012-726-001
OSN 222-99-18	Basic	15-Oct-99	Fuel System Vent Tubes, P/N 222-066-605-101
OSN 222-00-19	Basic	2-Jun-00	Tail Rotor Gearbox Output Shaft Splines Wear
OSN 222-00-20	Basic	30-Aug-00	Heated and Heated Bird-Proof Windshield Assemblies P/N 222-331-101-101/-102 and 222-031-105-111/-112
OSN 222-01-21	Basic	30-Nov-01	Transmission Top Case P/N 222-040-061-101 and -105
OSN 222-03-22	Basic	16-Oct-03	Tail Rotor Blades 222-016-001-ALL, Periodic Inspection of
OSN 222-04-23	Basic	15-Nov-04	Tail Rotor Blades 222-016-001-131 and -135

GENERAL OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-76-1	Basic	21-Jan-76	Use of Life Vests During Over-water Operations
OSN GEN-76-2	Basic	23-Jan-76	Helicopter Accidents Caused by Ground Handling Errors
OSN GEN-76-3	Basic	24-Sep-76	Use of Standard Hardware
OSN GEN-76-4	Basic	13-Sep-76	Heavy Lift, Aft Center of Gravity, Prolonged Hover, Cyclic Control Abuse
OSN GEN-76-5	Basic	13-Sep-76	Fuel Contamination
OSN GEN-76-6	Basic	18-Oct-76	Collective Minimum Friction
OSN GEN-76-7			NOT USED
OSN GEN-76-8	Basic	22-Dec-76	Operation of Helicopters in Salt Laden Atmosphere
OSN GEN-77-1	Rev A	3-Nov-77	Airworthiness of Aircraft Parts
OSN GEN-78-1	Basic	10-Jan-78	Maintenance of the Main Rotor Blade Inspection System (B.I.S.)
OSN GEN-78-2	Basic	5-May-78	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-78-3	Basic	13-Sep-78	Chadwick C-47 Electronic Weighing System, Load Cell Link P/N 47-40200-19
OSN GEN-78-4	Basic	11-Dec-78	Chaffed Oil Lines
OSN GEN-79-1	Basic	2-May-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-79-2	Basic	26-Nov-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-80-3	Basic	13-Feb-80	Cracked Main Rotor Blade, P/N 204-011-250 Series
OSN GEN-80-4	Basic	19-Jun-80	Rotating Control Bolts
OSN GEN-80-5	Basic	27-Jun-80	Enhancement of Crew and Passenger Safety During High Impact Landings
OSN GEN-80-6	Basic	27-Jun-80	Daily Inspection of Main Input Driveshafts
OSN GEN-80-7	Basic	24-Jul-80	Transporting Flammable Cargo
OSN GEN-81-8	Basic	22-Sep-81	Inspection of Tail Rotor Pitch Links
OSN GEN-82-9	Basic	6-Oct-82	Tail Rotor Driveshaft Curvic Couplings, Inspection, Maintenance
OSN GEN-83-10	Basic	1-Sep-83	Engine Compressor Washing
OSN GEN-85-11	Basic	6-Nov-85	Beware of "Certificate of Manufacture, Inspection and Conformance"
OSN GEN-87-12	Basic	13-May-87	FAA Airworthiness Directive 87-06-09 (Mechanical Products, Inc.)
OSN GEN-88-13	Reissue	5-May-92	Lines Extending from the Helicopter
OSN GEN-89-14	Basic	6-Dec-89	Bogus P/N 212-073-905-1 Pressure Gage, Emergency Floats
OSN GEN-91-15	Basic	29-Jul-91	Electromagnetic Compatibility (EMC) of Aircraft Wiring with Pyrotechnic Device and Cargo Hooks
OSN GEN-91-16	Basic	21-Aug-91	Airframe Structural Repair
OSN GEN-91-17	Basic	1-Oct-91	Main Driveshaft Assembly, Inspection of
OSN GEN-92-18	Basic	19-Mar-92	Proper Stowage of Miscellaneous Items in and Around the Flight Crew Compartment
OSN GEN-92-19	Basic	5-May-92	MS21042 Series Nuts Approved Vendors
OSN GEN-92-20	Basic	25-Jun-92	Use of Non-Conforming Floatbag Assemblies
OSN GEN-92-21	Basic	25-Jun-92	Lubricant P/N 204-040-755-005

GENERAL OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-93-22	Basic	29-Jan-93	Main Rotor Vibration; Emphasis on Timely Investigation
OSN GEN-93-23	Basic	29-Jan-93	Maintenance/Overhaul Procedures
OSN GEN-93-24	Basic	1-Mar-93	Parts Authenticity and Traceability
OSN GEN-93-25	Basic	15-Dec-93	"Slingshot" Maneuvers in Heavy Lift Operations
OSN GEN-95-26	Basic	19-Jan-95	Aircraft Cleaning
OSN GEN-95-27	Basic	24-Mar-95	Tail Rotor Yoke (Flexure Style) Failure
OSN GEN-96-28	Basic	21-May-96	Transmission Spiral Bevel Gear Cracks
OSN GEN-96-29	Basic	18-Oct-96	Unapproved Tail Rotor Driveshaft Hanger Bearings
OSN GEN-97-30	Basic	27-Jan-97	Breeze-Eastern Customer Advisory Bulletin Number CAB-100-54
OSN GEN-97-31	Basic	1-May-97	Tail Rotor Hanger Bearings Maintenance
OSN GEN-02-32	Basic	2-May-02	Bogus Parts Tail Rotor Grips
OSN GEN-02-33	Basic	10-Oct-02	Maintenance/Overhaul Procedures
OSN GEN-02-34	Basic	22-Nov-02	Correct Procedure for Torquing Fasteners
OSN GEN-04-35	Basic	21-Sep-04	Cyclic Stick Grip Assembly
OSN GEN-06-36	Basic	17-Apr-06	Paint Application on Helicopter Faying Surfaces
OSN GEN-06-37	Basic	20-Jul-06	NAS 1291-7 and -8 Nut, Confirmation of Condition Upon Installation
OSN GEN-09-38	Basic	7-Apr-09	Bearings in Flight Controls
OSN GEN-09-39			RESERVED
OSN GEN-09-40	Basic	16-Nov-09	Onboard Systems International Alert Service Letter Document no. 159-027-00.
OSN GEN-10-41	Basic	18-Jan-10	Honeywell Bendix/King Discrepant Databases for KLN35A/KLN 88/KLN 89/KLN 89B/KLN 90/KLN 90A/KLN90B/KLN 94/KLX 100/KLX 135/KLX 135A/KLN 900
OSN GEN-10-42	Basic	13-Dec-10	Use of Specified Hardware
OSN GEN-11-43	Rev A	16-Sep-11	NAS1291 Nuts and NAS626 Bolts
OSN GEN-11-44	Basic	10-May-11	Defective Grease Fittings NAS516-1A

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
--------------------	-----------------------	-------------	----------------